

MEMORANDUM

DATE: December 15, 2017

TO: Zoning Board of Appeals

FROM: Clifford E. Radatz \mathcal{CER}

Building Official

SUBJECT: Variation Request – 1431 Monroe Avenue

Carla and Mark Tomassini, owners of the property at 1431 Monroe Avenue, have submitted the attached application for variations to the floor area regulations (Section 10-9-5), and the side yard setback regulations (Section 10-9-7) of the Zoning Code. The applicants propose to construct an addition onto the existing home.

Section 10-9-5 of the Zoning Code requires that the floor area ratio not to exceed 0.40. The applicant is requesting to construct a new single family residence with a floor area ratio of 0.486.

Section 10-9-7 of the Zoning Code requires a minimum side yard setback of ten percent of the lot width or five feet, whichever is greater, and the minimum required combined side yard setback to be twenty five percent of the lot width, or ten feet, whichever is greater as measured to the exterior wall of the structure. For the 50 foot wide lot, the minimum required setback at each side is 5'-0", and the combined side yard setback should be a total of 12'-6".

The applicants are requesting variations so that the existing one-story north wall of the building, which maintains a non-conforming side yard setback of 3'-0", may be demolished and replaced with a new two-story wall at the same non-conforming setback.

The proposed addition will have a 5'-0" setback from the south property line, so that the combined side yard setback for the addition will only be 8'-0". Note that the setback of the existing house at the south side of the building is 3.15 feet (slightly less than 3'-2"). The overall combined side yard setback is 6.15 feet, which will be reproduced by the proposed addition.

The setback of roof eaves from the side property line is required to be 3'-0". The proposed roof overhang of 6 inches will result in a setback of 2'-6" to the roof eave at the north side of the addition.

If the Zoning Board wishes to recommend the approval of these variations to the Village Board of Trustees, the following motion should be made: Motion to recommend to the Village Board of Trustees the approval of the variations to Sections 10-9-5 and 10-9-7 of the Zoning Code at 1431 Monroe Avenue.

If you have any questions regarding this application, please do not hesitate to call me.

APPLICATION FOR ZONING VARIATION Village of River Forest Zoning Board of Appeals

Address of Subject Property: 14.	31 Monroe Avenue R	iver Forest, IL 60305
Applicant: Carla and Mark Tor	massini	
Name		
1431 Monroe Aver	nue River Forest, IL	60305
Address		
312-560-5699	312-896-5725	home@cjrmat.com
Phone (Daytime)	Fax	E-Mail
Owner		
Relationship of Applicant to	Property (owner, contract purch	aser, legal counsel, etc.)
Architect/Contractor: Kim Smith	1	
Name		
811 North East Av	enue Oak Park, IL 60	0302
Address		
773-934-9124		ksmith@smith-arch.com
Phone (Daytime)	Fax	E-Mail
Date of Application: 10/25/2	017	
Application requirements: Attached read the attached carefully, the applic	d you will find an outline of the o ant will be responsible for submit	ther application requirements. Please tting all of the required information.
Also attached for your information as hearings.	re the Zoning Board of Appeals "	Rules of Procedure" for their public
Application Deadline: A complete smonth in order to be heard by the Zo Appeals meets on the second Thursd	oning Board of Appeals in the fol	mitted no later than the 15th day of the lowing month. The Zoning Board of
SIGNATURES:		
requested, that all statements herein	and on all related attachments at	illage of River Forest to take the action herein the true and that all work herein mentioned will
Owner: Wash a. To		prest and the laws of the State of Illinois. _ Date:
Applicant (if other than Owner):		Date:

Application Fee: A non-refundable fee of \$650.00 must accompany every application for variation. Checks should be made out to the Village of River Forest.

APPLICATION FOR ZONING VARIATION

Address of Subject Property: 1431 Monroe Avenue Date of Application: 10/25/2017

Summary of Requested Variation(s):

Applicable Code Section (Title, Chapter, Section) Example: 10-8-5, lot coverage	Code Requirement(s) Example: no more than 30% of a lot	Proposed Variation(s) Example: 33.8% of the lot (detailed calculations an a separate sheet are required)
10-8-5, Floor Area Ratio	0.4 of Lot Area (3,763 s.f.)	0.486 of Lot Area (4,570 s.f.)
10-8-7-C-1 Side Yard Setback	ten percent of the lot width or five feet, whichever is greater, 5'-0"	3'-0"
10-8-7-C-2-a Side Yard Setback, roof eave	The eaves of a structure shall be required to maintain a minimum three foot side yard setback.	2'-6"
10-8-7-C-1 Combined Side Yard Setback	the minimum required combined side yard setback shall be twenty five percent of the lot width, or ten feet, whichever is greater as measured to the exterior wall of the structure. 12'-6"	8'-0"

THE APPLICANT IS REQUIRED TO SUBMIT DETAILED LONG HAND CALCULATIONS AND MEASUREMENTS FOR ALL APPLICABLE ZONING PROVISIONS. APPLICATIONS WILL NOT BE CONSIDERED COMPLETE WITHOUT THESE CALCULATIONS AND MEASUREMENTS.

Zoning Application Tomassini Residence 1431 Monroe Avenue

Description of the Project

The home improvement project includes enhancing the living space without having a significant impact on the house's original footprint. The current plans remain below the allow site coverage by approximately 500 feet or 5%. We would like to avoid changing the footprint of the house and garage due to flooding concerns in the area and specifically the pooling of water in our backyard (See attached pictures).


We have lived in the house since moving to River Forest in 2004. We plan on remaining in the house after the improvements are completed. We believe that our renovation will positively increase the value of the area.

There has been significant flooding in the area in recent years. In May 2013, there was an exchange relating to significant backyard flooding of the 1400 block of Monroe and William. E-mail messages were exchanged with Phil Cotter at the Village, E-mail message string attached. There is a significant accumulation of rainwater due to the building of patios and higher grading in the backyards on the block has led to that does not allow the nature drainage on the block. This limitation is the basis of our decision that has limited the design options.

The 1400 blocks of Monroe and William are low points in River Forest. Please note pages 21-23 on the attached presentation from the Village's Proposed Sewer Improvement Project dated April 29, 2013.

We have also attached letters of approval from our immediate neighbors:


- 1. North neighbor 1435 Monroe (Shelstad family)
- 2. South neighbor 1427 Monroe (Drury family)



SCHOMIG LAND SURVEYORS, LTD. PLAT OF SURVEY

LOT 5 IN BLOCK 5 IN O. C. BRAESE'S SUBDIVISION OF THE EAST 1/2 OF THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 1, TOWNSHIP 39 NORTH, RANGE 12, EAST OF THE THIRD PRINCIPAL MERIDIAN, IN COOK COUNTY, ILLINOIS.

COMMON ADDRESS: 1431 MONROE AVENUE, RIVER FOREST.



THE CUSTOMER LISTED BELOW PROVIDED THE LEGAL DESCRIPTION SHOWN HEREON. WE DO NOT GUARANTEE THAT THIS IS THE CORRECT LEGAL DESCRIPTION FOR THE TRANSACTION INTENDED.

IMPORTANT: COMPARE LEGAL DESCRIPTION TO DEED OR TITLE POLICY AND REPORT ANY DISCREPANCY FOR CLARIFICATION OR CORRECTION IMMEDIATELY. UNLESS OTHERWISE NOTED, THIS PLAT DOES NOT SHOW BUILDING LINES OR OTHER RESTRICTIONS ESTABLISHED BY LOCAL ORDINANCES.

DO NOT SCALE DIMENSIONS FROM THIS PLAT; THE LOCATION OF SOME FEATURES MAY BE EXAGGERATED FOR CLARITY. NO EXTRAPOLATIONS MAY BE MADE FROM THE INFORMATION SHOWN WITHOUT THE WRITTEN PERMISSION OF SCHOMIG LAND SURVEYORS LTD. ONLY PLATS WITH AN EMBOSSED SEAL ARE OFFICIAL DOCUMENTS. FIELD WORK WAS COMPLETED PER SURVEY DATE LISTED BELOW. © COPYRIGHT, ALL RIGHTS RESERVED.

SURVEY DATE:

AUGUST 10, 2004.

BUILDING LOCATED:

AUGUST 10, 2004.

ORDERED BY:

MARK A. TOMASSINI

PLAT NUMBER:

041833

SCALE: 1" = 20'



M. = MEASURED DIMENSIONR. = RECORDED DIMENSION

B.L. = BUILDING LINE

P.U.E. = PUBLIC UTILITY EASEMENT

D.E. = DRAINAGE EASEMENT

E = CENTER LINE

W.F. = WOOD FENCE

I.F. = IRON FENCE -X X

V.F. = VINYL FENCE ---

NYL FENCE - - - - - LICENSE E

909 E 31st ST

60526 RUSSELL W. SCHOMIG

035-002448

PROFESSIONAL

LAND SURVEYOR


STATE OF ILLINOIS) ss.


WE, SCHOMIG LAND SURVEYORS, LTD. AS AN ILLINOIS PROFESSIONAL DESIGN FIRM, LAND SURVEYOR CORPORATION, DO HEREBY CERTIFY THAT WE HAVE SURVEYED THE PROPERTY DESCRIBED HEREON.

ALL DIMENSIONS ARE IN FEET AND DECIMAL PARTS OF A FOOT. DIMENSIONS SHOWN ON BUILDINGS ARE TO THE OUTSIDE OF BUILDINGS. THE BASIS OF BEARINGS, IF SHOWN AND UNLESS OTHERWISE NOTED, ARE ASSUMED AND SHOWN TO INDICATE ANGULAR RELATIONSHIP OF LOT LINES.

THIS PROFESSIONAL SERVICE CONFORMS TO THE CURRENT ILLINOIS MINIMUM STANDARDS FOR A BOUNDARY SURVEY.

BY: Pusell W. Schomig PROFESSIONAL ILLINOIS LAND SURVEYOR LICENSE # 035,000,446





BASEMENT PLAN D 3/16"=1'-0"


TOMASSINI RESIDENCE **1431 MONROE** RIVER FOREST, IL 60305



ARCHITECTURE ADDITION HISTORIC PRESERVATION RENOVATION NEW CONSTRUCTION GRAPHIC DESIGN

B11 NORTH EAST AVENUE. OAK PARK, IL 60302

M I T H 773.934.9124 KSMITH@SMITH-ARCH.COM



1ST FLR PLAN D

3/16"=1'-0"


2349 S.F. GROSS - 300 S.F FOR GARAGE ALLOWANCE=2049 S.F.

TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



ARCHITECTURE HISTORIC PRESERVATION RENOVATION
NEW CONSTRUCTION GRAPHIC DESIGN

811 NORTH EAST AVENUE. OAK PARK, IL 60302 M I T H 773.934.9124



2ND FLR PLAN D 3/16"=1'-0"


2204 s.F.

TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



A SMITH ARCHITECTURE HISTORIC PRESERVATION RENOVATION NEW CONSTRUCTION GRAPHIC DESIGN ARCHITECTURE ADDITION

811 NORTH EAST AVENUE. OAK PARK, IL 60302 773.934.9124 KSMITH@SMITH-ARCH.COM S M I T H 773.934.9124




3RD FLR PLAN D 3/16"=1'-0" 296 S.F. AT 7' OR HIGHER

TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



HISTORIC PRESERVATION RENOVATION NEW CONSTRUCTION GRAPHIC DESIGN

M I T H 773.934.9124 SSMITH@SMITH-ARCH.COM



ROOF PLAN D 3/16"=1'-0"

TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



811 NORTH EAST AVENUE. S M I T H 773.934.9124



WEST ELEVATION 1/8"=1'-0"



SOUTH ELEVATION 1/8"=1'-0"

TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



A S MITH ARCHITECTURE

ARCHITECTURE

ARCHITECTURE

HISTORIC PRESERVATION GRAPHIC DESIGN

REMOVATION NEW CONSTRUCTION GRAPHIC DESIGN

S M I T H 773.934.9124

811 NORTH EAST AVENUE. OAK PARK, IL 60302 KSMITH@SMITH-ARCH.COM



NORTH ELEVATION 1/8"=1'-0"



TOMASSINI RESIDENCE 1431 MONROE RIVER FOREST, IL 60305



SMITH ARCHITECTURE

ARCHITECTURE R ADDITION

HISTORIC PRESERVATION RENOVATION NEW CONSTRUCTION GRAPHIC DESIGN

S M I T H 773.934.9124

811 NORTH EAST AVENUE. OAK PARK, IL 60302 773.934.9124 KSMITH@SMITH-ARCH.COM

Zoning Review Checklist

Address: 1431 Monroe Avenue

Date of Review:

11/7/2017

Date of Submission: 11/6/2017

Contact:

Telephone #:

Zoning District:

R2

Use:	Addition to	a Single Famil	y Residence	
		Permitted U	se	
Lot Area		Lot Width 50.00	Lot Depth 188.14	Lot Area 9407.00
Lot Coverage		Allowed	Existing	Proposed
30% allowed for the R2 District		2822.10	1873.39	2300.22 🗹
Floor Area Ratio		Allowed	19.91% Existing	24.45% Proposed
40% allowed for the R2 District		3762.80	2988.37	4570.03 ×
4070 dilowed for the N2 Bistriot		0702.00	31.77%	48.58%
Setbacks	***	Required	Existing	Proposed
Frontyard	West			
Average of block, see 10-8-7 A			0.0000	No Change
Eave Length		0.0000		No Change
Setback to Eave		0.0000	48.4000	□ 0.0000 □ € Proposed setback
Sideyard	North			at addition NC SYSB
10% of Lot Width for the R2 Distr	ict	5.0000	3.0000	3.0000 🗷 🗷
Eave Length			0.5000	0.5000
Setback to Eave		3.0000	2.5000	2.5000
Sideyard	South			
10% of Lot Width for the R2 Distr	ict	5.0000	3.1500	5.0000 🗹
Eave Length			0.0000	0.5000
Setback to Eave		3.0000	3.1500	4.5000
Combined Sideyard				
25% of Lot Width for the R2 Distr	ict	12.5000	6.1500	8.0000
Rearyard	East			
15% of Lot Depth or 26'-2" minim	um		63.2800	57.2700
Eave Length			0.5000	0.5000
Setback to Eave		28.2210	62.7800	56.7700

Zoning Review Checklist

Building Height Ridge	Allowed	Existing	Proposed H at addition	lt.
Height above grade in feet	35'	31'	34'	\checkmark
Story Height	2.5	2	2.5	\checkmark
Off-Street Parking	Required	Existing	Existing + Proposed	
Garage spaces	2	2	2	

1431 Monroe Avenue Area Calculations			11/7/2017
Lot Area		50.0000	188.1400
Allowed Coverage Allowed FAR		0.3000 0.4000	
Lot Coverage - Existi	ng		
First Floor Area	Existing		1873.3908
	Total		1873.3908
Lot Coverage - New First Floor Area	Proposed		2300.2173
	Total		2300.2173
Floor Area Evicting			
Floor Area - Existing Floor Area - existing	1st floor 2nd floor Attic		1873.3908 1264.9743 0.0000
garage allowance (up t	o 500 s.f)		-150.0000 2988.3651
Floor Area - Proposed			
Floor Area - Proposed	1st floor 2nd floor Attic		2300.2173 2146.6242 273.1875
garage allowance			-150.0000

9407.0000

2822.1000 3762.8000

4570.0291

House - 1st floor - Existing				
round bay	Α			6.7525
	В	0.6400	8.5300	5.4592
	C	9.6900	15.3500	148.7415
	D	0.6500	16.5000	10.7250
	E	13.2000	25.0500	330.6600
	F	6.7300	0.7000	4.7110
	G	16.0200	26.4300	423.4086
	Н	11.4600	22.7100	260.2566
-0.5	"-H"	3.1100	3.0400	-4.7272
	J	0.6200	13.9000	8.6180
	K	5.4100	33.6500	182.0465
	L	9.4300	33.4400	315.3392
	M	8.1800	20.6500	168.9170
	Ν	18.0400	0.3700	6.6748
round bay	0			5.8081
				1873.3908
House - 1st floor - Prop	osed			
Existing to remain				
•				
round bay	Α			6.7525
•	В	0.6400	8.5300	6.7525 5.4592
•	B C	9.6900	15.3500	5.4592 148.7415
•	B C D	9.6900 0.6500	15.3500 16.5000	5.4592 148.7415 10.7250
•	B C D E	9.6900 0.6500 13.2000	15.3500 16.5000 25.0500	5.4592 148.7415 10.7250 330.6600
•	B C D E F	9.6900 0.6500 13.2000 6.7300	15.3500 16.5000 25.0500 0.7000	5.4592 148.7415 10.7250 330.6600 4.7110
•	B C D E F G	9.6900 0.6500 13.2000	15.3500 16.5000 25.0500 0.7000 26.4300	5.4592 148.7415 10.7250 330.6600
•	B C D E F G "H1"	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285
•	B C D E F G	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394
round bay	B C D E F G "H1" "H2" N	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748
•	B C D E F G "H1" "H2"	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394
round bay	B C D E F G "H1" "H2" N	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748
round bay	B C D E F G "H1" "H2" N O	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667 18.0400	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800 0.3700	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748 5.8081
round bay	B C D E F G "H1" "H2" N O P	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667 18.0400	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800 0.3700	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748 5.8081
round bay	B C D E F G "H2" N O P q	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667 18.0400	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800 0.3700 19.7500 1.4792	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748 5.8081 573.1608 6.6564
round bay	B C D E F G "H1" "H2" N O P	9.6900 0.6500 13.2000 6.7300 16.0200 8.3500 0.5667 18.0400	15.3500 16.5000 25.0500 0.7000 26.4300 22.7100 22.4800 0.3700 19.7500 1.4792 20.7708	5.4592 148.7415 10.7250 330.6600 4.7110 423.4086 189.6285 12.7394 6.6748 5.8081

House - 2nd floor - Exis	sting			
	C'	10.6900	15.3500	164.0915
	D'	4.0000	16.5000	66.0000
	E'	8.8500	15.3500	135.8475
	G	16.0200	26.4300	423.4086
	Н	11.4600	22.7100	260.2566
	"-H"	3.1100	3.0400	9.4544
	J	0.6200	13.0400	8.0848
	K	5.4100	13.0400	70.5464
	L	9.4300	12.7900	120.6097
	N	18.0400	0.3700	6.6748
				1264.9743
House - 2nd floor - Pro	posed			
Existing to remain				
	C'	10.6900	15.3500	164.0915
	D'	4.0000	16.5000	66.0000
	E'	8.8500	15.3500	135.8475
	G	16.0200	26.4300	423.4086
	"H1"	8.3500	22.7100	189.6285
	"H2"	0.5667	22.4800	12.7394
New Construction		00.0000	40.7500	570 4000
New Construction	р	29.0208	19.7500	573.1608
New Construction	q	4.5000	1.4792	6.6564
New Construction			20 Maria (2000)	

House - Attic half story - Existing to remain

				0.0000
House - Attic half story	- Propos	sed		
	X	2.2500	24.0000	54.0000
	У	24.8750	8.0000	199.0000
	z	4.7500	4.2500	20.1875
				273.1875

STANDARDS FOR MAJOR VARIATIONS (SECTION 10-5-4F)

A major variation shall be recommended by the Zoning Board of Appeals only if it makes findings, based upon the evidence presented to it, that each of the following standards has been met:

1. The physical surroundings, shape or typographical conditions of the specific property involved with bring a specific hardship upon the owner as distinguished from an inconvenience if the strict letter of the regulations were to be carried out;

The area is an extremely low area in Village. There is frequent localized flooding of the streets and backyards due to significant pooling of water. Based on these conditions, there are limited options to improve the living space for this single family home. The structure will remain a single family home.

The overall site coverage is below the allowed site coverage by approximately 5% or 500 square feet.

The house was built in 1940. The neighboring homes were built in the 1950's. The setback has not changed since the house and neighboring houses were built. The proposed design will not alter the current setback. The variation allows the home to remain as it was originally built.

Please note that we are attempting to not change the overall footprint while not relocating the garage to an area that is subject to flooding. We do not want to add grading issues that will affect neighboring properties and cause additional flooding.

The aforesaid unique physical condition did not result from an action of any person having an interest in the property, but was created by natural forces or was the result or was the result of governmental action, other than the adoption of this Zoning Ordinance, for which no compensation was paid;

The party with interest in the property has not altered the physical condition of the property. The condition is a result of the natural topography as well as the build-up of backyard patios and elevated grading by other residents on the block. The elevated patios were allowed due to the lack of Village ordinances at the time of the construction. The grading was completed over time by the other residents.

At the current time, each residents' yards are unable to drain onto the north side of the block (Le Moyne Parkway) using the natural crown of the lots.

3. The conditions upon which the petition for variation is based may not be applicable generally to other property within the same zoning classification;

Many of the homes have been built well after 1431 Monroe. There doesn't appear to be any other local homes with the need for the setback variance. We are also at one of the lowest points on the block. There is no plan to alter the backyard and will allow the pooling to continue.

4. The purpose of the variation is not based predominantly upon a desire for economic gain;

We purchased and originally remodeled the house in 2004. We have no plans of moving from River Forest. We plan on using this house as our residence for the long-term future.

STANDARDS FOR MAJOR VARIATIONS (SECTION 10-5-4F)

A major variation shall be recommended by the Zoning Board of Appeals only if it makes findings, based upon the evidence presented to it, that each of the following standards has been met:

5. The granting of the variation shall not be detrimental to the public welfare or unduly injurious to the enjoyment, use, or development value of other property or improvements in the neighborhood in which the property is located;

There will be no detrimental impact to public welfare or cause any harm to the development or improvement of neighboring homes. The improvement is strictly residential in nature. It remains consistent with the neighborhood and current and future use. It does not cause any incompatibility issues with the neighboring properties.

6. The proposed variation will not impair an adequate supply of light and air to adjacent property, or substantially increase the danger of fire, or otherwise endanger the public safety or substantially diminish or impair property values within the neighborhood;

There will be no impairment to light or air to adjacent properties or endangerment of public safety. Light and air will not be limited since this is an improvement and above an existing space. Sun exposure from the south and west will not change. There is no change to the existing roofline affecting those exposure points for the neighbor to the north with the sun's movement throughout the day. The improvements will be accretive to neighboring properties. The property will remain a personal residence.

7. That the granting or the variation would not unduly tax public utilities and facilities in the area;

The variation will not tax local public utilities and facilities. The home will remain a person residence moving forward. The number of residents will not change in the household. It remains a single family home. There will not be any additional need for the property.

Please note that the improvements will be outfitted with more efficient light and plumbing fixtures and electrical appliances that will reduce the overall power consumption of the house.

8. That there is no means other than the requested variation by which the alleged hardship or difficulty can be avoided or remedied to a degree sufficient to permit a reasonable use of the subject property.

Due to the flooding conditions and the preexisting setback condition, there are no feasible remedies. This is the purpose for the variation request.

Tomassini Residence - Backyard Water Pooling



1431 Monroe



1435 Monroe



1443 Monroe

Village of River Forest Zoning Board and Permit Applications 400 Park Ave. River Forest, IL 60305 Nov. 7, 2017

Re: Tomassini home addition

Dear Members,

My wife and I have discussed the project the Tomassini's are contemplating and have no concerns or objections. Mark and Carla Tomassini are our immediate neighbors to the south. Their plans for the renovation and addition to their property appear thoughtful and attractive.

Additionally, I will note their expressed mutual unhappiness about the chronic flooding both our back yards experience and the potential benefit of the project.

Please feel free to contact me if you have questions of any kind.

Sincerely,

Mark & Judy Shelstad 1435 Monroe Ave.

708-772-7774



RE: Zoning Application

1 message

Drury, John <JDrury@seyfarth.com> Wed, Nov 8, 2017 at 3:53 PM To: "Carla J. Racanelli" <carla@cjrmat.com>, Jill Drury <jmdrurypharmd@gmail.com> Cc: "mt@cjrmat.com" <mt@cjrmat.com>

Hi Carla,

We have no objection based on the plans and what we discussed.

Thanks,

John

John Drury | Senior Counsel | Seyfarth Shaw LLP 233 S. Wacker Drive | Suite 8000 | Chicago, Illinois 60606-6448 Direct: +1-312-460-5623 | jdrury@seyfarth.com | www.seyfarth.com





Mark A. Tomassini <mtomassini@cirmat.com>

RE: 1447 Monroe - Dam

1 message

Jeff Loster < jloster@vrf.us>

Thu, May 16, 2013 at 4:19 PM

To: "Mark A. Tomassini" <mtomassini@cjrmat.com>

Cc: "phcarlson@comcast.net" <phcarlson@comcast.net>, Mark Shelstad <mshelstad@comcast.net>, Mark Shelstad <judy.s2@comcast.net>, "Racanelli, Carla" <carla@cjrmat.com>, Phil Cotter <pcotter@vrf.us>

The curb and patio are separate items. The patio appears to have been somewhat of a recent development. I investigated the area elevations relative to the patio and came to the determination that the installation of the patio does not appear to be a code violation. My reasoning was explained in a previous email - to save everyone some time I will not repeat myself.

The curb is a different issue. It appears to be an existing condition that has been present for a significant amount of time. While it was obviously installed to create a change in elevation, I cannot state that it was a code violation because it would have had to violate the ordinance that was existing at the time the curb was installed. Since there was no grading ordinance enacted prior to the current one (effective beginning last year) it is unlikely that this curb would have been in violation. Existing conditions such as this one do, on occasion, contribute to problems as time goes on however, we do not have the means to retroactively apply our current ordinance to projects completed under previous ordinances.

Jeff Loster, PE, CFM, CPESC

Village Engineer

Village of River Forest

400 Park Avenue

River Forest, IL 60305

P: 708.714.3551

F: 708.366.3702

jloster@vrf.us

From: Mark A. Tomassini [mailto:mtomassini@cjrmat.com]

Sent: Thursday, May 16, 2013 3:10 PM

To: Jeff Loster

Cc: phcarlson@comcast.net; Mark Shelstad; Mark Shelstad; Racanelli, Carla; Phil Cotter

Subject: Re: 1447 Monroe - Dam

Jeff,

Why is the patio elevation and curb not a violation? It does not allow for the free flow of water to the street. This is the overall plan for the entire village.

Thank you,

Mark

On Thu, May 16, 2013 at 3:06 PM, Jeff Loster <jloster@vrf.us> wrote:

I agree that there is no way for the water to flow out to LeMoyne Pkwy. Unfortunately, there is also no way for the water to drain out to Monroe Ave or William St. Since the connection of a yard drain to the combined sewer system is not an option, the best approach that can be taken at this point is to try to minimize the runoff that is currently directed into this area and to try to better manage the water that does make it there. These include the following:

- -The amount of water can be minimized by removing any sump pump or downspouts that currently drain to the backyard. Removal of these point discharges (especially any sump pumps) would greatly reduce the amount of water that is conveyed to the low spot.
- -Rain barrels could be installed at any downspout that drains to the rear yards. A typical rain barrel holds 55 gallons when full. If every household in the area had just one of these, the amount of runoff conveyed to the low area would be reduced by hundreds of gallons.
- -Any landscaped areas could be converted to depressional rain gardens and planted with native vegetation. The subtle "depression" that is characteristic of rain gardens would help keep portions of the runoff away from the more severely inundated areas. This would make the worst areas slightly more manageable in every rain event and may even prevent significant ponding in other rain events. The native vegetation would be better suited to help draw down some of the standing water after a rain event which would lead to shorter periods of inundation. The stone base beneath the rain garden would also be able to provide additional water storage that isn't currently available onsite.
- -Any number of underground rainwater harvesting systems could be installed throughout the tributary area. This includes everything from a buried cistern to a modular system that can be aesthetically enhanced with a water feature. Systems like this would help trap the water that would help reduce the ponding and could then be re-used for irrigation whenever it is needed.
- -Changes to any future work within the tributary area should be considered if they could help minimize runoff. This includes anything from reducing project footprints to installing permeable products instead of impervious ones.

Also worth noting is the fact that the conceptual storm sewer project that the Village is currently considering proposes (among other things) that a storm sewer be installed along your street. The presence of a storm sewer in this area would likely reduce some of the runoff that enters the low area behind your homes and may even be able to accommodate a connection from a rear-yard drain.

I hope these ideas help. Let me know if there are any of them that you would like to discuss in greater detail and I would be happy to do so.

Jeff Loster, PE, CFM, CPESC

Village Engineer

Village of River Forest

400 Park Avenue

River Forest, IL 60305

P: 708.714.3551

F: 708.366.3702

iloster@vrf.us

From: Mark A. Tomassini [mailto:mtomassini@cjrmat.com]

Sent: Friday, May 10, 2013 1:57 PM

To: Jeff Loster

Cc: phcarlson@comcast.net; Mark Shelstad; Mark Shelstad; Racanelli, Carla; Phil Cotter

Subject: Re: 1447 Monroe - Dam

Jeff.

There is no ability for the water to naturally flow onto LeMoyne. This is the main problem.

What can be done?

Thank you,

Mark

On Fri, May 10, 2013 at 1:30 PM, Jeff Loster <jloster@vrf.us> wrote:

I am sorry you believe I have missed the point. I can assure you all that I have thoroughly reviewed the pictures sent to me and visited the site to see the situation with my own eyes. After my site visit I was able to orient each of the pictures you provided and am aware of each location shown, relative to the area. While I agree that the grading in the area around the patio is preventing water from flowing north I am unable to conclude that this is directly related to the installation of the patio. My reasoning is as follows:

-The water in the pictures that were sent to me is at the top of the timber "retaining wall". It was indicated to me that the water is approximately 18 inches deep in this condition. Based on my site visit, there is an elevation difference of about 6-8 inches from the top of the timber retaining wall to the top of the patio. If the patio were the sole cause of the ponding, it would have to have been installed approximately 2 feet higher than the original grade in this area (which adequately allowed drainage to LeMoyne). Given the vegetation around the patio (which again, appears to have been present longer than the patio itself) and the fact that the patio is directly adjacent to the

residence, raising the grade 2 feet is not practical. Typically there is not 2 feet of exposed foundation wall along the perimeter of a residence that would allow that high of a grade change. Also, raising grades on the magnitude of 2 feet would likely have killed the vegetation in this area.

Other points worth noting:

-I completely agree that the grades increase in elevation as you approach the patio from the south. I also agree that this prevents water from migrating northward. That being said, it does not appear that this is a direct result of the installation of the patio. Rather it would seem to be a function of existing grade changes that appear to have been present for a significant amount of time.

-It should be noted that most, if not all of your properties are sloped towards the backyards (hence the accumulated water). This would indicate that all the properties in this area are contributing significant amounts of runoff to the low area. Any sump pump and/or downspout discharge lines that drain into this area are also contributing to the problem.

While I understand that this situation can be very frustrating to deal with as a homeowner, I do not have adequate information to conclude that it is caused by the installation of the patio at the 1447 Monroe property. I would be happy to meet with any of you on-site at some point next week to discuss the matter in person and review potential solutions that may help alleviate the problems. Please let me know if this is something you would be interested in.

Jeff Loster, PE, CFM, CPESC

Village Engineer

Village of River Forest

400 Park Avenue

River Forest, IL 60305

P: 708.714.3551

F: 708.366.3702

jloster@vrf.us

From: phcarlson@comcast.net [mailto:phcarlson@comcast.net]

Sent: Tuesday, May 07, 2013 1:29 PM

To: Mark A. Tomassini

Cc: Racanelli, Carla; Phil Cotter; Mark Shelstad; Mark Shelstad; Jeff Loster

Subject: Re: 1447 Monroe - Dam

Well said, Mark. He is totally missing the point. Probably because he has not actually seen it in person. Also, we did not have this problem until after the new patio was installed approximately 4-5 years ago.

Debbie Carlson

From: "Mark A. Tomassini" <mtomassini@cirmat.com>

To: "Jeff Loster" <jloster@vrf.us>

Cc: "Racanelli, Carla" <carla@cjrmat.com>, "Carlson Family" <phcarlson@comcast.net>, "Phil Cotter" <pcotter@vrf.us>,

"Mark Shelstad" <mshelstad@comcast.net>, "Mark Shelstad" <judy.s2@comcast.net>

Sent: Tuesday, May 7, 2013 12:38:20 PM

Subject: Re: 1447 Monroe - Dam

Jeff,

I do not understand your point. The reason the water is pooled is that there is no where for it to flow. The patio has dammed the water from flowing onto the LeMoyne Avenue. I believe that you are not looking at the picture correctly. The water is stopped by the retaining wall that supports the patio. If the wall/patio was not there or it was not to the property line with other building up to it, the water would have flowed to LeMoyne. Instead, it pools in the backyards.

It progressively gets worse to my house, four (4) houses to the south. Please see the attached presentation.

If it was not for basement sump pumps and people pumping out their backyards to Monroe, the water may still be standing there.

There needs to be a nature way for the water to flow off of the property. There is none. There needs to be a change.

Mark

312-560-5699

1431 Monroe Avenue.

On Tue, May 7, 2013 at 11:55 AM, Jeff Loster <jloster@vrf.us> wrote:

Mr. Tomassini,

I was able to finally make a round of site visits late last week and am a little behind on getting back to everyone. I took a look at the area from your backyard north to LeMoyne Pkwy. While it is clear that there is insufficient slope needed to drain the entire area to the north, it does not appear that the installation of the patio at 1447 Monroe is the cause. If the installation of the patio were the problem, I would expect to see water up to the patio, making it clear that the patio itself was causing the issue. Based on the attached picture, it does not appear that this is the case.

Often times when patios area installed at a higher elevation, the surrounding grade is also raised. In this case, however, raising the grade significantly around the perimeter of the patio would likely have caused a significant grade change along/near the south property line. Given the fact that there is vegetation in this area that appears to have been established for an extensive amount of time, it does not appear that the grades in this area were significantly altered due to any recent construction. Raising the grade at the base of this vegetation by several inches would likely have caused a great deal of damage.

I can certainly understand your frustration in an area like this where adequate drainage paths are not present. There is a significant tributary area that can lead to a large amount of standing water in high rain events, obviously. Given a lack of evidence that leads to a single cause of the problem, I think the only remaining solution is to try to better manage any standing water that is present. Things such as rain gardens, underground cisterns, or other rainwater harvesting systems would all help prevent standing water on the magnitude currently present. Let me know if this is something you'd like to discuss in more detail and I would be happy to share any additional thoughts that might help.

Please also keep in mind that the Village has pumps that we loan out to residents so that areas like this one can be pumped out (once any surcharge of the sewer system has subsided). Additional information on this topic can be found at the following web address:

http://www.vrf.us/residents/flooding#Pump

Let me know if you have any questions on the items discussed above or if you would like to discuss any of the potential solutions mentioned in greater detail.

Jeff Loster, PE, CFM, CPESC

Village Engineer

Village of River Forest

400 Park Avenue

River Forest, IL 60305

P: 708.714.3551

F: 708.366.3702

jloster@vrf.us

From: Mark A. Tomassini [mailto:mtomassini@cjrmat.com]

Sent: Tuesday, May 07, 2013 10:13 AM

To: Jeff Loster

Cc: Carla Racanelli; Carlson Family; Phil Cotter

Subject: Re: 1447 Monroe - Dam

Jeff,

I wanted to see if you were able to get any grade information, etc.

What will be the next steps?

Thanks,

Mark

312-560-5699

1431 Monroe Avenue

----- Forwarded message -----

From: Mark A. Tomassini <mtomassini@cjrmat.com>

Date: Fri, Apr 19, 2013 at 4:24 PM Subject: Re: 1447 Monroe - Dam To: Phil Cotter <pcotter@vrf.us>

Cc: Carla Racanelli <carla@cjrmat.com>, Carlson Family <phcarlson@comcast.net>, Mark Shelstad

<mshelstad@comcast.net>, Judy Shelstad <judy.s2@comcast.net>

Thank you.

I will contact him.

On Apr 19, 2013, at 4:10 PM, Phil Cotter <pcotter@vrf.us> wrote:

Mr. Tomassini,

I have asked our Village Engineer, Jeff Loster, to contact you regarding your question/concern. His direct number is 708-714-3551 if you decide to expedite contact with him.

Phil Cotter

Director of Public Works

Village of River Forest

400 Park Avenue

River Forest, IL 60305

(708) 714-3550

(708) 366-3702 fax

pcotter@vrf.us

From: Mark A. Tomassini [mailto:mtomassini@cjrmat.com]

Sent: Thursday, April 18, 2013 4:18 PM

To: Phil Cotter

Cc: dmm@dmanorthstar.com; Carla Racanelli; phcarlson@comcast.net; Mark Shelstad;

mshelstad@comcast.net Subject: 1447 Monroe - Dam

Phil,

I live at 1431 Monroe Avenue. I am sure that you are inundated today, but this problem continues to affect all houses south of 1447 Monroe.

The dam that has been created by the houses' built-up patios located at the SE corner of Monroe/LeMoyne and SW Corner of William/LeMoyne has caused more ground water to not be allowed to drain unto LeMoyne.

The water just sits and creates more hydrostatic pressure on ground water surrounding everyone's foundations. A path needs to be created to allow the water to drain naturally on LeMoyne Avenue. A small amount of pooling makes sense, but this is ridiculous. Attached are pictures of 1443 Monroe's backyard. It is approximately 18 inches deep.

Something needs to be done immediately. Pictures are attached.

Please feel free to contact me directly with any questions.

Mark

Mark A. Tomassini

1431 Monroe Avenue

River Forest, IL 60305

Home: 708-488-9310

Office: 312-560-5699


Mark A. Tomassini

312-560-5699

0009 Division St. 0.4 0.5 Berksshire St. 2000 0.5 Greenfield St. ----Crown ------Rim Le Moyne St. 0.5 Monroe Ave. 3000 Jackson Ave. Lathrop Ave. 2000 **Ashland** Ave Franklin Ave. Park Ave. Forest Ave. ,,96 Thatcher Ave. 632 627 612 637 617 607

Existing Conditions (10-Year)

Existing Conditions (50-Year)



Division St. Berksshire St. Existing Conditions (July 2011) Greenfield St. 2.7 in Le Moyne St. Monroe Ave. lackson Ave. Lathrop Ave. **9vA** bnsldzA Franklin Ave. Park Ave. Forest Ave. Thatcher Ave. 642 627 637 632 622 612 617 607

0009

2000

4000

2000

1000

----Crown Rim