





VILLAGE WIDE ARCHITECTURAL + HISTORICAL SURVEY

Final Significant Property Survey June 15, 2013

Village of River Forest Historic Preservation Commission




River Forest Architectural and Historical Survey Significant Property Survey

The Significant Property Survey was undertaken between June and October 2012 for an area comprising the Village of River Forest municipal boundaries, from North Avenue (north) to Madison Street (south), and Harlem (east), Thatcher (west) and Lathrop Avenues (west of Lathrop and south of Central Avenue) (see maps on following pages). Properties are organized in this document by street in alphabetical and numeric order starting with the highest street number first. In other words, properties are presented by street from north to south. Significant properties are marked in deep brown in the following maps.

All other properties not part of this survey document can be found in the Reconnaissance Survey of Survey Areas 1, 2, 3 and 4. For information on the survey project itself, significance and integrity ratings, architectural styles and building forms, please refer to the *River Forest Architectural and Historical Survey Final Report* and the project website at www.thelakotagroup.com/riverforest/.



FIGURE 5: SURVEY AREA 1A



Survey Area 1 Properties by Significance

Significant	37
Potentially Contributing to a National Register District	590
Potentially Non-Contributing to a National Register District	119
Noteworthy Buildings Under 50 Years of Age	5




FIGURE 6: SURVEY AREA 1B







FIGURE 6: SURVEY AREA 2A



Survey Area 2 Properties by Significance

Significant	92
Contributing to a National Register District	53
Non-Contributing to a National Register District	22
Potentially Contributing to a National Register District	463
Potentially Non-Contributing to a National Register District	87
Noteworthy Buildings Under 50 Years of Age	8
Potentially Contributing to a National Register District Potentially Non-Contributing to a National Register District	463 87



FIGURE 7: SURVEY AREA 2B







FIGURE 7: SURVEY AREA 3A



Survey Area 3 Properties by Significance

National Register Landmark	2
Significant	151
Contributing to a National Register District	459
Non-Contributing to a National Register District	39
Potentially Contributing to a National Register District	156
Potentially Non-Contributing to a National Register District	68
Noteworthy Buildings Under 50 Years of Age	4




FIGURE 8: SURVEY AREA 3B





FIGURE 8: SURVEY AREA 4A

LEGEND		
	NATIONAL REGISTER DISTRICT BOUNDARY	
	NATIONAL REGISTER LANDMARK	
	SIGNIFICANT	
	CONTRIBUTING	
	POTENTIALLY CONTRIBUTING	
	NOTEWORTHY BUILDING LESS THAN 50 YEARS OLD	

Survey Area 4 Properties by Significance

National Register Landmark	1
Significant	18
Contributing to a National Register District	15
Non-Contributing to a National Register District	2
Potentially Contributing to a National Register District	459
Potentially Non-Contributing to a National Register District	147
Noteworthy Buildings Under 50 Years of Age	7



Roof Material:

Alterations:

River Forest Village Wide Architectural and Historical Survey

General Information			
Street Number:	Washington Square Park		
Former Street Number:			
Street:			KING SAL
PIN Number(s):			A LEWART
		I want of	
Construction Date/Other Year:			
Architect:	Jens Jensen		No.
Current Function/Category:	Site		
Historic Function:	Site	Photo 1	
Listing in Existing Survey:		Cinnificant	Voo
Evaluation		Significant:	Yes
Condition:	Good	National Register Criterion:	В
Integrity:		Contributing to a National Register District:	
		Potentially Contributing to a National Register District:	
Secondary Structure:		Noteworthy Buildings Less Than 50 Years Old:	
Secondary Structure Condition	:		One of three parks designed by
Secondary Structure Integrity:		Reason for Significance:	One of three parks designed by Jens Jensen in River Forest. It
Landmark/National Register:	No		retains a good level of integrity from its original design.
Architectural Description	ons		
Architectural Classification/Sty	le:	Roof Ornamentation:	
Ornamentation:		Foundation Material/Form:	
Building Form:		Door Detailing:	
Number of Stories:		Porch:	
Current Wall Material 1:			
		Dormers:	
Current Wall Material 2:		Window Type:	
Original Wall Material 1:		Window Configuration:	
Original Wall Material 2:		Window Material:	
Wall Detailing/Ornamentation:		Window Detail:	
Storefront Material:		Window Storms:	
Roof Type:		Significant Features:	



Research Information		
Original Building Owner:		
Historic Name:	Washington Square Park	
Current Name:		
Construction Cost:		
Architect 1 Information:	Jens Jensen	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Doug Gilbert interview with Carol Yetken	
Permit:		
Subdivision:		
Landscape/Streetscape:	Jens Jensen designed park	
Notes		
Based on research, the park retains a good level of integrity and retains most design elements from		
<u>Jensen's original drawings.</u>		-
		Photo 3 / Historic Photo
		_
		_
		_
		_

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: October 15, 2012



General Information

Street Number: 1000 - 1014

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-310-028-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: An addition to the north has been

added and extending into the 1014

lot.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the largest Italian

Renaissance homes in Rover Forest with excellent symmetry and proportions. The house also retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms:

Significant Features:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape: Fence	
Notes	
An addition constructed to the north occupies the lot for 1014 Ashland addition dates from the 1990s - 2000s. This house's original address may have been 7700	
Augusta.	Photo 3 / Historic Photo
	

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: August 21, 2012



General Information

Street Number: 1447

Former Street Number: 710

Street: Ashland Avenue

PIN Number(s): 15-01-109-022-0000, 15-01-109

-023-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations: Second and third story casement

windows may have been replaced.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Built as part of the speculative

homes of the E.E. Woods subdivision, Chris Reier as contractor. The home is a

distinctive, mostly masonry version

Roof Ornamentation:

Porch:

Foundation Material/Form: Brick

Door Detailing: Sidelights

Dormers: Hipped

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: 3 story cross gables; central entry

Entrance

porch; all masonry.



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		A TOTAL OF THE PARTY OF THE PAR
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Informa	ition:	11002
Permit:		
Subdivision:	E.E. Woods subdivision.	
Landscape/Streetscape:		
Notes		
Larger size Tudor esta	te house.	_
		_
		Photo 3 / Historic Photo
		
		_
		_
		<u> </u>
		_

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: July 23, 2012



General Information

Street Number: 1415

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-109-003-0000

Construction Date/Other Year: 1931

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Brick

Original Wall Material 1: Stone

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Side Gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive version of the Tudor

Revival that retains high

architectural integrity. This was one of the speculative houses built

as part of the E.E. Woods

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing:

Porch:

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms:

Significant Features: Large front brick chimney with

chimney pots; central stone entrance bay; side wings.



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		THE RESERVE OF THE PARTY OF THE
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:	E.E. Woods subdivision.	
Landscape/Streetscape:		
N. 4		
Notes		
		Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: July 23, 2013



General Information

Street Number: 1400

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-108-023-0000, 15-01-108

-024-0000

Construction Date/Other Year: 1957

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Building Form: Ranch

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Ornamentation:

Original Wall Material 1: Brick

Original Wall Material 2:

Storefront Material:

Wall Detailing/Ornamentation:

Roof Type:

Roof Material: Not visible/cannot be determined

Flat

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A Mid-Century Modern house that

is similar to some Keck and Keck designs. It is highly distinctive and retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features:



Research Information

1/
NAME OF THE PARTY
The said
6

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1311

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-113-008-0000

Construction Date/Other Year: 1937

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Quoin work on wall corners.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: B

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Historically significant as once the

home of entertainer Lawrence Welk during the 1940s. The house also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Pedimented

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Round arch window at roof line.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 23, 2012



General Information

Street Number: 1250

Former Street Number:

Street: Ashland Avenue

PIN Number(s):

Construction Date/Other Year: 1930s

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation: Quoin work surrounding main

entrance gabled pavilions

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations: Perkins and Will designed addition

on west elevation - dates from

1952.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: The only Classical Revival

institutional building in River Forest; it is a distinctive, elegant version of the style with a high level

of integrity.

Roof Ornamentation: Cornice

Foundation Material/Form: Stone

Door Detailing: Transom

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Ribbon

Window Storms: No

Significant Features: Entrances with Classical detailing



Research Information

Original Building Owner:		
Historic Name:	Frances Willard School	
Current Name:	Willard School	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:	Perkins and Will	
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		-
		•

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1138

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-304-008-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Brick molds over windows.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly unique Italian

Renaissance home constructed by the Buurma Brothers and retains a

high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Large brackets underneath eave

line, central second story bay,

entrance porch



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information: Buurma Brothers	
Developer Information:	Photo 2
Research/Archival Information:	FIIOLO 2
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	_
	Photo 3 / Historic Photo
	
	
	<u> </u>
	 ;

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 1130

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-304-009-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Red brick quoin work around

windows and dormer hoods

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations: First floor bay window may have

been replaced; other windows/ casements may have been



Significant:

Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highjy distinctive French Eclectic

house with high pitched roof and tower entrance. Constructed by the Buurma Brothers, this house retains a high level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Dominant tower bay and tower

entrance are this home's most

significant features.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Field's A Guidebook to River Forest Architecture.	
Permit:		
Subdivision:		
Landscape/Streetscape:	Front path bluestone pavers	
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 1123

Former Street Number: 544

Street: Ashland Avenue

PIN Number(s): 15-01-305-004-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Timbering and herringbone brick

pattern in dominate front gable and

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival

mansion designed and constructed by the Buurma Brothers. The house retains a high level of

integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Oriel

Window Storms: Yes

Significant Features: Oriel window in dominant front

gable.



Research Information			
Original Building Owner:			
Historic Name:			
Current Name:			
Construction Cost:			
Architect 1 Information:			
Architect 2 Information:			
Contractor Information:	Buurma Brothers		
Developer Information:		Photo 2	
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	11002	
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
		Photo 3 / Historic Photo	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 1115

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-305-005-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Leaf work vergeboard and finial

keystones in gable apexes

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Stone

Original Wall Material 1: Stucco

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Prioto 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive representation

of the Tudor Revival cottage in River Forest - well-detailed with gable vergeboard, timbering and oriel window in dominant gable. It

Roof Ornamentation: Vergeboard

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Oriel

Window Storms: No

Significant Features: Oriel window in dominant gable,

timbering and vergeboard

ornamentation.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
One of te more intact, richly designed Tudor Revival	
homes in River Forest.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Street Number: 1105

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-305-006-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations: Some windows may have been

replaced



Photo 1

Significant: Yes

National Register Criterion: C

E

National Register District:
Potentially Contributing to a
National Register District:

Contributing to a

National Register District.

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: The distinctive massing and form of

this French Eclectic country house, constructed by the Buurma Brothers, is quite distinctive. The house also retains a high level of

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Large chimney on south elevation

with pots, entrance tower on west

elevation; arched dormers



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone pavers in front entrance	
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 1047

Former Street Number: 520

Street: Ashland Avenue

PIN Number(s): 15-01-311-001-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Stone quoin work at elevation

corners

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Significant:

Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive and representative

example of the Italian Renaissance house in River Forest, constructed by the Buurma Brothers, which retains a high level of integrity. Its

Roof Ornamentation: Balustrade

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes

Significant Features: Entrance doorway with pediment

and surrounds, one story north wing with roof balustrade.

Page 25



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 1031

Former Street Number: 500

Street: Ashland Avenue

PIN Number(s): 15-01-311-003-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: В С

Contributing to a **National Register District:**

Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Colonial Revival

> house with some Some Tudor Revival influences and built by the Buurma Brothers. It retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	11002
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Recheck architectural style		
	_	Photo 3 / Historic Photo
		· ·

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 931
Former Street Number: 456

Street: Ashland Avenue

PIN Number(s): 15-01-317-018-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Stone quoin at one elevation

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

noted for its leaded glass casement windows above the front entry. This house also retains a high level of integrity. Bluestone paving in

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Dominant central gable with multi-

paned casement windows



Research Information			
Original Building Owner:		ſ	
Historic Name:			
Current Name:			
Construction Cost:			
Architect 1 Information:			
Architect 2 Information:			
Contractor Information:			
Developer Information:		Į	Photo 2
Research/Archival Information:			-
		-	
Permit:			
Subdivision:			
Landscape/Streetscape:	Bluestone paving in front entrance		
Notes			
			Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 930

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-316-006-0000

Construction Date/Other Year: 1920

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the early homes

constructed in the River Forest's "Northwoods" area, this house displays a unique building plan with some Prairie stylistic elements

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Arched windows and deep roof

eaves.



Research Information		
Original Building Owner:	Paul F. Victor	
Historic Name:	Victor House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: Guidebook to the Architecture of River Forest; River Forest National Register District	
Permit:	•	
Subdivision:		
Landscape/Streetscape:		
Notes		
House was once later the h Mars candy maker compan	ome of Franklin Mars of the y.	
		Photo 3 / Historic Photo
	_	Pnoto 37 Historic Pnoto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Former Street Number:

Street Number: 914

Street: Ashland Avenue

PIN Number(s): 15-01-316-007-0000

Construction Date/Other Year: 1925

Architect: Philip Maher

Current Function/Category: Single Family Residential Building

435

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Herringbone brick pattern between

piers in driveway porch.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations: Unclear if windows had been

replaced on all elevations.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: An outstanding, distinctive example

of the Italian Renaissance style with some Art Deco and Tudor influences, designed by the son of

George Maher.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: Driveway porte-cochere, central

bay, chimney and side terrace.



Research Information		
Original Building Owner:	Neil Hurley	
Historic Name:	Neil Hurley House	
Current Name:		
Construction Cost:		THE RESERVE TO THE RE
Architect 1 Information:	Philip Maher	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information	1:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Maher was the son of Geo	orge Maher	
	Hurley Machine Company,	· ,
the first electric washing n	ne appliances and reportedly nachine	Photo 3 / Historic Photo
		•
		•
		•

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: August 21. 2012



General Information

Street Number: 909

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-317-005-0000

Construction Date/Other Year: 1931

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Stone quoin work at elevation

corners.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type:

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

with its massing and exterior organization. It retains a high level

of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Oriel

Window Storms: No

Significant Features: Oriel windows in south gable bay,

center entrance.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
This house is currently undergoing rehabilitation.	
	Photo 3 / Historic Photo
	Filoto 37 ristorio Filoto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 847

Former Street Number: 426

Street: Ashland Avenue

PIN Number(s): 15-01-323-001-0000

Construction Date/Other Year: 1925

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Brickwork at gable roof edges,

scroll work in window mullions

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: **Brick**

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations: Front entry door on north elevation

may have been replaced.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

house that expresses William Drummond's preference for simplified geometric building shapes and low roof lines. This

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Shed Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: No

Significant Features: Low roof lines, clipped dominant

gable of south elevation.



Research Information

Original Building Owner:	E. Norman Rauland	
Historic Name:	Norman Rauland House	The same of the sa
Current Name:		A WALL TO SE
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 846

Former Street Number: 419

Street: Ashland Avenue

PIN Number(s): 15-01-322-004-0000

Construction Date/Other Year: 1927

Architect: James Denson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Stucco

Original Wall Material 1: Stone

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Wood Shingle

Alterations:



Significant:

В

Yes

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of the more distinctive Tudor

Revival homes, and carriage house, ot be designed and constructed by the Buurma Brothers in River Forest. It also

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material:

Window Detail: Paired

Window Storms:

Significant Features:



Research Information

Original Building Owner: Frank Oechslin

Frank Oechslin House **Historic Name:**

Current Name:

Construction Cost:

Architect 1 Information: James F. Denson

Architect 2 Information:

Contractor Information: Buurma Brothers

Developer Information:

Research/Archival Information: Fields: A Guidebook to the River

Forest Architecture

Permit:

Subdivision:

Landscape/Streetscape: Train tracks encompassing front



Oechslin was the owner of a floral wholesale company



Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 831
Former Street Number: 410

Street: Ashland Avenue

PIN Number(s): 15-01-323-003-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival house

with its own unique massing and spatial arrangement. It retains a high level of integrity. Bluestone entrance path paving may indicate

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail: Oriel

Window Storms:

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check this house again	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 20, 2012



General Information

Street Number: 830

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-322-017-0000

Construction Date/Other Year: 1936

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

house especially in regards to its massing, spatial arrangement and use of stone. The house retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Oriel

Window Storms: No

Significant Features: Distinctive chimney on west

elevation; Stone entrance bay



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Building massing and design may indicate a Buurma-	
constructed house. Additional investigation is needed.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 815

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-323-005-0000

Construction Date/Other Year: 1928

Architect: Charles White

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Alternating facade stone, brick

pattern

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Building Form:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A highly distinctive French

> Normandy house designed by Charles White and retains a high

level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Lead Glazed

Hood Mold Window Detail:

Window Storms: No

Significant Features: Round tower at north elevation.

arched cornice level dormers, existing leaded glass casement

windows.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information: Charles White	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Additional research is needed to determine if this may	
have been a Buurma- constructed house.	
	Photo 3 / Historic Photo
·	Tido of historic risco
· · · · · · · · · · · · · · · · · · ·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Street Number: 814

Former Street Number:

Street: Ashland Avenue

PIN Number(s): 15-01-322-006-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Quoin work at corners, unusual for

Italian Renaissance house

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:


Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

Less Than 50 Years Old:

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings

Reason for Significance: A highly distinctive, large Italian

Renaissance house in River Forest designed and constructed by the Buurma Brothers. It also retains a

high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: Yes

Significant Features: Porte cochere on north eleveation



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information: Buurma Brothers	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 807

Former Street Number: 384

Street: Ashland Avenue

PIN Number(s): 15-01-323-006-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Keystone in hold molds, stone

window lintels.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Some windows may have been

replaced on south and east

elevations.



Significant:

Yes

National Register Criterion: B

С

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive and highly intact

Italian Renaissance house constructed by the Buurma

Brothers.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms:

Significant Features: Arched windows on first floor;

entrance surround, dormer facing

west elevation.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		-
		Photo 3 / Historic Photo
		-
		- -
		-
		- -
		-

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Street Number: 739

Former Street Number: 364

Street: Ashland Avenue

PIN Number(s): 15-12-105-005-0000

Construction Date/Other Year: 1904

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive

A distinctive early Foursquare in River Forest with unique Colonial Revival styled porch and ornamentation. The house also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Cornice line swag ornamentation

and Queen Anne porch.



Research Information

1.Cocaron information	
Original Building Owner:	the said of the sa
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 731 **Former Street Number:** 354

Street: Ashland Avenue

PIN Number(s): 15-12-105-007-0000

Construction Date/Other Year: 1938

Architect: R. Webster Tomlinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Brick

Original Wall Material 1: Stucco

Original Wall Material 2: Brick

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive but later example of a

two-story Craftsman house in River Forest. The house also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Boxed return ends and brackets at

roof line.



Research Information

Original Building Owner: R. Leland

Historic Name: R. Leland House

Current Name:

Construction Cost:

Architect 1 Information: R. Webster Tomlinson

Architect 2 Information:

Contractor Information: Guy and McClintock

Developer Information:

Research/Archival Information: River Forest National Register

Historic District Nomination

Permit:

Subdivision:

Landscape/Streetscape:

Notes			



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 629

Former Street Number: 316

Street: Ashland Avenue

PIN Number(s): 15-12-111-002-0000

Construction Date/Other Year: 1889

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Substantial rear addition.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Queen Anne

house with some Greek Revival detailing with a high level of

integrity.

Entrance

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Transom

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Porch:

Window Storms: Yes

Significant Features:



Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 562

Former Street Number: 285

Street: Ashland Avenue

PIN Number(s): 15-12-110-030-0000

Construction Date/Other Year: 1919

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 1/2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: С В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tallmadge and

Watson Prairie house design that retains a high level of integrity.

Roof Ornamentation:

Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features:



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	William Lally	
Historic Name:	William Lally House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Check for significance.		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 559

Former Street Number: 280

Street: Ashland Avenue

PIN Number(s): 15-12-111-011-0000

Construction Date/Other Year: 1901

Architect: Frank Lloyd Wright

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

В

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance:

Important and early Prairie house by Frank Lloyd Wright, based on a 1901 design in Ladies Home Journal. Board and batten siding is unusual and the gable roofs are

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms:

Significant Features:



Research Information		
Original Building Owner:	E. Arthur and Susan Davenport	
Historic Name:	Arthur Davenport House	
Current Name:		
Construction Cost:	\$3,544	
Architect 1 Information:	Frank Lloyd Wright	
Architect 2 Information:	Restored by Paul Harding; Harding Partners	
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Arthur Davenport was a par Pullman Company	ssenger agent for the	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 554
Former Street Number: 275

Street: Ashland Avenue

PIN Number(s): 15-12-110-032-0000

Construction Date/Other Year: 1911

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Foursquare

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Ornamentation:

Building Form:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



.....

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive front gabled

Foursquare with Craftsman/Arts and Crafts porch and stylistic elements. The home retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features: Craftsman/Arts and Crafts porch

with flower motifs



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 550 **Former Street Number:** 271

Street: Ashland Avenue

PIN Number(s): 15-12-110-033-0000

Construction Date/Other Year: 1913

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Current Wall Material 2:

Building Form: Foursquare

Number of Stories:

Current Wall Material 1: Wood clapboard

Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Foursquare with both

Colonial Revival and Queen Anne design elements. The house also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Full Front Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Free Classic porch, wide eaves at

roof line



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	THE HELL
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Former Street Number:

Street Number: 530

Street: Ashland Avenue

PIN Number(s): 15-12-110-038-0000

Construction Date/Other Year: 1916

Architect: Paul Strayer

Current Function/Category: Single Family Residential Building

253

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Ornamentation:

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Building Form: Bungalow

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Sun room dormer on north

elevation; other dormers on both north and south elevations are later



Significant: Yes

National Register Criterion: B

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Histor

Historically significant as home to Paul Strayer, well-known artist and

illustrator.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:		1 4 M	No.
Historic Name:	Paul Strayer House		
Current Name:		2000	
Construction Cost:			The state of
Architect 1 Information:		X X	
Architect 2 Information:	Paul Strayer		
Contractor Information:			The State of the S
Developer Information:		Photo 2	
Research/Archival Information:			
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
Strayer was an artist and ill magazines	ustrator for numerous		
		Photo 3 / Historic Photo	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2013



General Information

Street Number: 526

Former Street Number: 249

Street: Ashland Avenue

PIN Number(s): 15-12-110-039-0000

Construction Date/Other Year: 1906

Architect: Drummond and Guenzel

Current Function/Category: Single Family Residential Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Solar thermal panels installed on

roof, west elevation.



Significant: Yes

National Register Criterion: С

В

Contributing to a **National Register District:** Yes

Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Important design by William

> Drummond, one of the best nonresidential examples of the Prairie Style in River Forest; constructed for the the River Forest Women's

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Fixed

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner: River Forest Women's Club

Historic Name: River Forest Women's Club

Current Name: private residence

Construction Cost:

Architect 1 Information: William Drummond and Louis

Guenzel

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: Guidebook to the

Architecture of River Forest

Permit:

Subdivision:

Landscape/Streetscape:

Notes

converted to private residence in 2005	
-	



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 107

Former Street Number: 56

Street: Ashland Avenue

PIN Number(s): 15-12-317-024-0000

Construction Date/Other Year: 1922

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical portico

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of a large

bungalow in a Colonial Revival style; one of the grander

bungalows in south River Forest.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Entry, stuccoed eaves



Research Information

Original Building Owner:			
Historic Name:			
Current Name:			
Construction Cost:			
Architect 1 Information:			or Bull fill for
Architect 2 Information:			J.
Contractor Information:			
Developer Information:		Photo 2	
Research/Archival Information:			
Permit:	Yes		
Subdivision:			
Landscape/Streetscape:			
Notes			
		Photo 3 / Historic Photo	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: October 1, 2012



General Information

Street Number: 7800
Former Street Number: 288

Street: Augusta Street

PIN Number(s):

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Windows may have been replaced

on south and east elevations.



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A unique variation of the Colonial

Revival in River Forest with its refined ornamentation, tile roof and irregular front entry placement.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail: Ribbon

Window Storms: No

Significant Features: Tile roof and ribbon windows,

asymmetrical facade arrangement;

carriage house garage



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check for significance.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2012



General Information

Street Number: 7600

Former Street Number:

Street: Augusta Street

PIN Number(s): 15-01-311-012-0000, 15-01-311

-018-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Windows may have been replaced

on all elevations; new windows in

room above Porte cochere.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the more distinctive, grand

examples of the Italian

Renaissance style in River Forest.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch: Entrance

Dormers: Arched

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail: Hood Mold

Window Storms: Yes

Significant Features: Pedimented front entrance; porte

cochere on north elevation; blind arch windows on south elevation.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	Elle Services
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Re check this house.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 7400

Former Street Number:

Street: Augusta Street

PIN Number(s): 15-01-402-002-0000

Construction Date/Other Year: 1914

Architect: attributed to F.G. Walker

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation: Stone columns at entry

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Original Wall Material 2:

Storefront Material:

Wall Detailing/Ornamentation:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Attached to other buildings



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Educational importance in the

> community, it's the main historic building for the campus and best represents Concordia University's University's significance and

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features:



Research Information		
Original Building Owner:	Concordia University	
Historic Name:		
Current Name:	Addison Hall	
Construction Cost:		
Architect 1 Information:	attributed to F.G. Walker	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
	_	Filoto 37 Historic Filoto
-		

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 30, 2012



General Information

Street Number: 525

Former Street Number:

Street: Auvergne Place

PIN Number(s): 15-11-207-027-0000, 15-11-207

-031-0000

Construction Date/Other Year: 1951

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form:

Number of Stories: 2 1/2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Windows on west elevation may

have been replaced.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: An outstanding example of Mid-

Century Modern residential architecture in River Forest. The house also retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features: Front entrance door with zig-zag

glazing; alternating roof lines and

projections.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 515

Former Street Number:

Street: Auvergne Place

PIN Number(s): 15-11-207-043-0000

Construction Date/Other Year: 1894

Architect: Frank Lloyd Wright

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: Yes

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Sullivanesque tinted plaster

ornament surrounding entrance

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

В

Yes

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Frank Lloyd Wright's first important

independent commission and the progenitor of his later Prairie houses. it also retains a high level

of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Use of Roman brick and deep roof

eaves.



Research Information

Original Building Owner: William Herman Winslow

Historic Name: William Winslow House and

Stables

Current Name:

Construction Cost:

Architect 1 Information: Frank Lloyd Wright

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: Guidebook to the

Architecture of River Forest; River Forest Historic District National

Permit:

Subdivision:

Landscape/Streetscape:



Also part of IL Landmark Survey		
· · · · · · · · · · · · · · · · · · ·		



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 7525

Former Street Number:

Street: Berkshire Street

PIN Number(s): 15-01-216-001-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Structure

Historic Function: Structure

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Terra cotta window trim

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:


Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District:

Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent style example and rare

> use of terra cotta ornament in River Forest, civic use significant to community development.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Fixed

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail: Label Mold

Window Storms:

Significant Features:



Research Information		
Original Building Owner:		
Historic Name:	Pumping Station	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Site is used as a small park	(
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 23, 2012



General Information

Street Number: 500-510

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s):

Construction Date/Other Year: 1945

Architect: Carl Kastrup

Current Function/Category: Multi Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical stone entry surrounds,

brick quoins

Building Form: Courtyard Apartment

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Replacement windows compatible



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the Colonial

Revival style with Art Deco detailing, an early apartment development in River Forest and built during World War II; part of

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features: Art Deco styling to classical details



Research Information

Original Building Owner:	John Cummings Lindop
--------------------------	----------------------

Historic Name:

Current Name:

Construction Cost: \$150,000

Architect 1 Information: Carl Kastrup

Architect 2 Information:

Contractor Information: Harvey P. Mukelson

Developer Information:

Research/Archival Information:

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes

This apartment development was constructed for returning war veterans after a long zoning battle over the site. Lindop, the grandson of area developer E.A. Cummings, lost a battle to build a commercial building on the site.

Kastrup was	from Forest	Park.	
•			



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Street Number: 1515

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s): 15-01-205-051-0000

Construction Date/Other Year: 1955

Architect:

Current Function/Category: Multi Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: International Style

Building Form: Apartment Flat/Block

Number of Stories: 3

Current Wall Material 1: Stone

Current Wall Material 2: Concrete/Concrete Block

Original Wall Material 1:

Ornamentation:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material:

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the

International Style in an apartment block form; the International Style is not common in River Forest.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail: Paired

Window Storms:

Significant Features: Cantilevered balconies



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
once home to mobster Paul "The Waiter" Ricca	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 17, 2012



General Information

Street Number: 1407

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s): 15-01-211-082-1002

Construction Date/Other Year: 1961

Architect:

Current Function/Category: Multi Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: Shaped concrete block

Building Form: Apartment Flat/Block

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Concrete/Concrete Block

Original Wall Material 1: Brick

Original Wall Material 2: Concrete/Concrete Block

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Stylish Mid-Century Modern

building with excellent integrity and distinctive use of modern materials.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration:

Window Material: Wood

Window Detail: Ribbon

Window Storms:

Significant Features: Open trellis over entry



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	
	Photo 3 / Historic Photo
	Filolo 37 Historic Filolo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 17, 2012



General Information

Street Number: 944

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s): 15-01-411-009-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Arched openings, classical stone

porch, eaves brackets

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the Italian

Renaissance style with a distinct side porch detailed with terra cotta

columns.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Side porch with rope columns



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	医 原则 上部大学 (5)。
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 915

Former Street Number: 440

Street: Bonnie Brae Place

PIN Number(s): 15-01-412-007-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Arched windows with carved stone

panels, classical entry surround,

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Window replacements are

appropriate



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Grand example of the Italian

Renaissance style with high quality

design and detailing.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Label Mold

Window Storms: Yes

Significant Features: Carved stone



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 846

Former Street Number: 425

Street: Bonnie Brae Place

PIN Number(s): 15-01-417-011-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Arched windows with stone

surrounds, classical stone panels,

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Building Form:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Replacement windows are in

character



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of the grandest examples of

the Italian Renaissance style in this part of River Forest with excellent details and a historically-designed

landscaped yard.

Roof Ornamentation: Cornice

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail: Label Mold

Window Storms: Yes

Significant Features: Stone veranda, stone lions at

sidewalk, stone fountain in yard



Research Information

Original Building Owner:	
Historic Name:	No. of the second second
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 825
Former Street Number: 404

Street: Bonnie Brae Place

PIN Number(s): 15-01-418-005-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

2

Ornamentation:
Building Form:

Number of Stories:

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Tile

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A grand, distinctive example of the

Italian Renaissance style in River Forest with excellent design and

detailing.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Sidelights

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Awnings over veranda and each

window, corner towers



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 734

Former Street Number: 355

Street: Bonnie Brae Place

PIN Number(s): 15-12-204-019-0000

Construction Date/Other Year: 1919

Architect: John S. Van Bergen

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal banding, corner piers

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent Prairie style example by

John S. Van Bergen with a stucco exterior and an intact example of

his unique entry design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing: Sidelights

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features:



Research Information

Original Building Owner: Thomas E. Heald

Thomas Heald House **Historic Name:**

Current Name:

Construction Cost: \$7000

Architect 1 Information: John S. Van Bergen

Architect 2 Information:

Contractor Information: Guy & McClintock

Developer Information:

Research/Archival Information:

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes			



Dhata 2 / Historia Dhata		

Photo 3 / Historic Photo

Survey Information

Doug Gilbert, Douglas Gilbert Architect Preparer:

Survey Date: August 21, 2012



General Information

Street Number: 628

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s): 15-12-210-011-0000

Construction Date/Other Year: 1909, modifications 1915

Architect: William Purcell

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Fretwork ornament in porch gable,

beadboard trim, art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: **Brick**

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the best Prairie style

examples in River Forest, with art glass windows and fretwork and intact garage, all constructed with

excellent craftsmanship.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features:



Research Information

Original Building Owner: Charles A. Purcell

Historic Name: Charles Purcell House

Current Name:

Construction Cost: \$8000

Architect 1 Information: William Purcell

Architect 2 Information: George Elmslie added the fretwork

and windows in 1915

Contractor Information: Guy & McClintock

Developer Information:

Research/Archival Information: Guidebook to the Architecture of

River Forest

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes

Charles Purcell was the father of architect William
Purcell. The house was designed prior to the successful
partnership of Purcell and Elmslie, but later modified
with the designs of Elmslie. A 1989 rear addition is by
Henry Zimoch.



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Former Street Number:

Street Number: 604

Street: Bonnie Brae Place

PIN Number(s): 15-12-210-016-0000

Construction Date/Other Year: 1913

Architect:

Current Function/Category: Single Family Residential Building

287

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical porch, bay window,

corner pilasters

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Rear addition is visible but

compatible



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Distinctive example of the Colonial

Revival style with Classical porch, bay windows and corner pilasters.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Full Front Porch:

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Street Number: 601

Former Street Number:

Street: Bonnie Brae Place

PIN Number(s): 15-12-211-012-0000

Construction Date/Other Year: 1907

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Wood banding

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

В

Yes

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and unusual Craftsman

Deep Eaves

style example by Tallmadge and Watson with excellent integrity.

Foundation Material/Form:

Roof Ornamentation:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information		
Original Building Owner:	Elias V. Day	
Historic Name:	Elias Day House	
Current Name:		
Construction Cost:	\$6,300	
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
This house design was rep Tallmadge and Watson in 1 house. Day was a lecturer	919 as a Sears Catalog	
		Photo 3 / Historic Photo
	-	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 20, 2012



General Information

Street Number: 8001

Former Street Number:

Street: Central Street

PIN Number(s):

Construction Date/Other Year: 1915

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Concrete/Concrete Block

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the

Craftsman style applied to a train station; it retains a high level of integrity. The station was constructed by the Chicago and

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms:



Research Information		
Original Building Owner:	Chicago and Northwestern Railway	у
Historic Name:		
Current Name:	River Forest Metra Train Station	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		1,100 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		-
		Photo 3 / Historic Photo
		-
		_
		-
		_
		_

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 7980

Former Street Number:

Street: Chicago Avenue

PIN Number(s): 15-02-405-010-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Not as grand in size and massing

as other Italian Renaissance homes in River Forest, but it retains a high level of design detail

and integrity.

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Elaborate entrance surround, rave

brackets and side wing on east

elevation.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	
	Photo 3 / Historic Photo
	Prioto 37 Historic Prioto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 23, 2013



General Information

Street Number: 1511

Former Street Number:

Street: Clinton Place

PIN Number(s): 15-01-204-021-0000

Construction Date/Other Year: 1958

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Stone

Brick

Brick

Ornamentation:

Number of Stories:

Current Wall Material 1:

Current Wall Material 2:

Original Wall Material 2:

Building Form: Ranch

Original Wall Material 1: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of Ranch type

and style with distinctive roof line

and entry.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Height

Dormers:

Window Type: Fixed

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Dramatic roof overhang and entry Significant Features:

porch, picture window



Photo 2
Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 18, 2012



General Information

Street Number: 1402

Former Street Number:

Street: Clinton Place

PIN Number(s): 15-01-209-022-0000

Construction Date/Other Year: 1937

Architect: Jerome Cerny

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical entry surround, shutters

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Slate

Alterations:



Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent style example, one of the

Yes

grander examples of Colonial Revival from the late 1930s.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Side gable chimneys, side sun

room



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Jerome Cerny	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	per plaque on house	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 18, 2012



General Information

Street Number: 837

Former Street Number: 414

Street: Clinton Place

PIN Number(s): 15-01-417-003-0000

Construction Date/Other Year: 1922

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Stucco with wood trim, bracketed portico

Building Form:

Ornamentation:

Number of Stories: 1 1/2

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and rare example of the

English Craftsman style with some

Tudor character.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	F1000 2
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
	Tible 57 Historie Filoto
	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 14, 2012



General Information

Street Number: 810

Former Street Number:

Street: Clinton Place

PIN Number(s): 15-01-416-023-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Chicago Bungalow

Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Ornamentation:

Building Form:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and grand example of a

> Chicago Style bungalow with excellent materials and tile roof.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Full Front Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information: Bu	uurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		FIIOLO 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 14, 2012



General Information

Street Number: 806

Former Street Number: 383

Street: Clinton Place

PIN Number(s): 15-01-416-024-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Chicago Bungalow

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and grand example of a

Chicago Style bungalow with excellent materials and tile roof.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information: Buurma Brothers	
Developer Information:	Photos
Research/Archival Information:	Photo 2
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	_
-	_
	Photo 3 / Historic Photo
	
	
	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 14, 2012



General Information

Former Street Number:

Street Number: 731

Street: Clinton Place

PIN Number(s): 15-12-204-007-0000

Construction Date/Other Year: 1915

Architect:

Current Function/Category: Single Family Residential Building

352

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Porch windows replaced or in filled

- sensitively done



Photo 1

Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Prairie Style example

with distinctive art glass.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Full Front Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Art glass windows on front



Research Information		
Original Building Owner:	Mrs. B. Harrison	
Historic Name:		
Current Name:		
Construction Cost:	\$5,500	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Hanson Brothers	
Developer Information:		Photo 2
Research/Archival Information:		F1000 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		Those of this circle is the
-	<u> </u>	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 727

Former Street Number: 348

Street: Clinton Place

PIN Number(s): 15-12-204-008-0000

Construction Date/Other Year: 1912

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the best examples of a

Prairie style bungalow with unique

detailing of the gable.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Unique wall detailing in gables



Research Information				
Original Building Owner:	R.F. Nicholos			
Historic Name:				
Current Name:				
Construction Cost:	\$4,500			
Architect 1 Information:				
Architect 2 Information:				
Contractor Information:	E. Holmstrad			
Developer Information:		Photo 2		
Research/Archival Information:		FIIOLO 2		
Permit:	Yes			
Subdivision:				
Landscape/Streetscape:				
Notes				
		Photo 3 / Histo	orio Bhoto	
		Filoto 37 filoto	THE PHOLO	
-				

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 723

Former Street Number: 344

Street: Clinton Place

PIN Number(s): 15-12-204-009-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, brick nogging

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent Tudor style example with

Yes

wonderful and highly detailed

masonry work.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Bay window, stone detailing,

brickwork



Research Information		
Original Building Owner:	Seth Rhodes	
Historic Name:		
Current Name:		
Construction Cost:	\$6,500	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		F1101.0 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 719

Former Street Number: 340

Street: Clinton Place

PIN Number(s): 15-12-204-010-0000

Construction Date/Other Year: 1918

Architect: John S. Van Bergen

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: River Forest Significant Properties

List

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal banding, leaded glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch infilled



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent example of Van Bergen's

interpretation of the Prairie Style

with excellent integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Transom

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:	Seth Rhodes	
Historic Name:	Seth Rhodes House	
Current Name:		
Construction Cost:		
Architect 1 Information:	John S. Van Bergen	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		F11010 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 715
Former Street Number: 336

Street: Clinton Place

PIN Number(s): 15-12-204-011-0000

Construction Date/Other Year: 1913

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal banding, art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch infilled, A/C unit mounted to

side wall



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Exce

Excellent example of the Prairie

Style as designed by Harry

Robinson.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:	James H. Heald	
Historic Name:	James Heald House	
Current Name:		
Construction Cost:	\$6,000	
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:	J. Vaughan	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 710

Former Street Number:

Street: Clinton Place

PIN Number(s): 15-12-203-025-0000

Construction Date/Other Year: 1924

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical porch

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations:



Prioto 1

Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Property associated with Phillip

Butler White, important American

realist artist.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms:



Research Information		
Original Building Owner:		
Historic Name:	Phillip B. White House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		FIIII 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	from 1938-2001. White was He was the 1980 Centennial	
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 629

Former Street Number: 316

Street: Clinton Place

PIN Number(s): 15-12-210-002-0000

Construction Date/Other Year: 1913

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Banding

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Very good example of a simplified

Yes

Prairie Style house but with a very unique porch design, all with

excellent integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Rounded corner porch windows



Research Information

rescaren inioniatio	''	
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$3700	
Architect 1 Information:		Caralle Control
Architect 2 Information:		
Contractor Information:	Gus Peterson	
Developer Information:		Photo 2
Research/Archival Informati	on:	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		_
		Photo 3 / Historic Photo
		<u> </u>
		_
-		
		

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Street Number: 625

Former Street Number: 312

Street: Clinton Place

PIN Number(s): 15-12-210-003-0000

Construction Date/Other Year: 1919

Architect: John S. Van Bergen

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Banding

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Compatible replacement windows,

alterations to entry stoop



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Work of John S. Van Bergen

Roof Ornamentation:

Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$4500	
Architect 1 Information:	John S. Van Bergen	
Architect 2 Information:		
Contractor Information:	Henry Hogans	The second second
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Street Number: 609

Former Street Number: 292

Street: Clinton Place

PIN Number(s): 15-12-210-007-0000

Construction Date/Other Year: 1916

Architect: John S. Van Bergen

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Door replaced, windows replaced



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Work of John S. Van Bergen

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms:



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$4500	
Architect 1 Information:	John S. Van Bergen	
Architect 2 Information:		
Contractor Information:	Henry Hogans	
Developer Information:		Photo 2
Research/Archival Information:		FIIII 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
	_	
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012



General Information

Street Number: 7900

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1925-1927

Architect: Ralph Adams Cram

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Collegiate Gothic

Ornamentation: Building Form:

Number of Stories: 2 1/2

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Designed by Ralph Adams Cram of

the Cram and Ferguson architectural firm, Boston, Massachusetts. Cram was the leading practitioner of the

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Fixed

Window Configuration: Multi-Paned

Window Material: Lead Glazed

Window Detail: Hood Mold

Window Storms:

Significant Features: Cloisters



Research Information		
Original Building Owner:	Rosary College/Domincan University	
Historic Name:	Mazzuchelli Hall	
Current Name:	Mazzuchelli Hall	
Construction Cost:		
Architect 1 Information:	Ralph Adams Cram; Cram and Ferguson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	University Special Collections	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 5, 2012



General Information

Street Number: 7900

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1925

Architect: Ralph Adams Cram

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Collegiate Gothic

Ornamentation: Building Form:

Number of Stories: 4+

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations: Original have been replaced on all

elevations.



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Designed by Ralph Adams Cram of

the Cram and Ferguson architectural firm, Boston, Massachusetts. Cram was the leading practitioner of the

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Storms: No

Window Material:

Window Detail:

Significant Features: Gothic windows with tracery.

Aluminum

Paired



Research Information		
Original Building Owner:	Rosary College/Domincan University	
Historic Name:	Lewis Memorial Hall	
Current Name:	Lewis Hall	
Construction Cost:		
Architect 1 Information:	Ralph Adams Cram; Cram and Ferguson	Danasi T
Architect 2 Information:		Park to minute the second
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information	:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Collegiate Gothic		
		Photo 3 / Historic Photo
-		

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: August 5, 2012



General Information

Street Number: 7900

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1922

Architect: Ralph Adams Cram

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Collegiate Gothic

Ornamentation:

Building Form:

Number of Stories: 4+

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Designed by Ralph Adams Cram of

the Cram and Ferguson architectural firm, Boston, Massachusetts. Cram was the leading practitioner of the

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features:



Research Information			
Original Building Owner:	Rosary College/Domincan University		
Historic Name:	Mother Emily Power Memorial Hall		
Current Name:	Power Hall		
Construction Cost:			
Architect 1 Information:	Ralph Adams Cram		
Architect 2 Information:			
Contractor Information:			
Developer Information:			
Research/Archival Information:			
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
Collegiate Gothic			

Photo 2		

Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: August 5, 2012



General Information

Street Number: 7900

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Site

Historic Function: Site

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:
Building Form:

Number of Stories:

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type:
Roof Material:

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A landscaped designed grotto

dating from the College's early years. It appears to have high

integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features:



Original Building Owner: Rosary College/Domincan University Historic Name: Grotto Current Name: Grotto Construction Cost: Architect 1 Information: Eugene A. De St. Aubin and Bro, Inc., Landscape Architects. Architect 2 Information: Contractor Information: Developer Information: Photo 2 Research/Archival Information: Permit:	Research Information		
Current Name: Grotto Construction Cost: Architect 1 Information: Eugene A. De St. Aubin and Bro, Inc., Landscape Architects. Architect 2 Information: Contractor Information: Developer Information: Photo 2	Original Building Owner:	Rosary College/Domincan University	
Construction Cost: Architect 1 Information: Eugene A. De St. Aubin and Bro, Inc., Landscape Architects. Architect 2 Information: Contractor Information: Developer Information: Photo 2	Historic Name:	Grotto	
Architect 1 Information: Eugene A. De St. Aubin and Bro, Inc., Landscape Architects. Architect 2 Information: Contractor Information: Developer Information: Photo 2	Current Name:	Grotto	
Inc., Landscape Architects. Architect 2 Information: Contractor Information: Developer Information: Photo 2 Research/Archival Information:	Construction Cost:		
Contractor Information: Developer Information: Photo 2 Research/Archival Information:	Architect 1 Information:	Eugene A. De St. Aubin and Bro, Inc., Landscape Architects.	
Developer Information: Photo 2 Research/Archival Information:	Architect 2 Information:		
Photo 2 Research/Archival Information:	Contractor Information:		
	Developer Information:		Photo 2
Permit:	Research/Archival Information:		
Permit:			
	Permit:		
Subdivision:	Subdivision:		
Landscape/Streetscape:	Landscape/Streetscape:		
Notes	Notes		
Photo 3 / Historic Photo			Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 5, 2012



General Information

Street Number: 7574

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation: Gothic ornament at entries

Building Form:

Number of Stories: 3

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type:

Alterations:

Roof Material: Not visible/cannot be determined

Flat

Recent additions at side elevations do not impact overall integrity

Photo 1

Significant: Yes

National Register Criterion: A

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinct, refined Gothic Revival

building with significance to educational development in River

Forest.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features:



Research Information Original Building Owner: Trinity High School **Historic Name:**

Current Name: Trinity High School **Construction Cost: Architect 1 Information: Architect 2 Information: Contractor Information:**

Developer Information: Research/Archival Information:

Permit: Subdivision: Landscape/Streetscape:

Notes

Photo 2

Photo 3 / Historic Photo		

Photo 3 / Historic Photo

Survey Information

Doug Gilbert, Douglas Gilbert Architect Preparer:

Survey Date: July 23, 2012



General Information

Street Number: 7300

Former Street Number:

Street: Division Street

PIN Number(s): 15-01-218-005-0000, 15-01-402

-003-0000

Construction Date/Other Year: 1929

Architect: Tallmadge and Watson

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation: sculptures of saints, chevrons,

pointed arches

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Slate

Alterations: Large but sympathetic addition



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:
Potentially Contributing to a

National Register District: Y

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An unusual Art Deco stylized

example of Gothic Revival, dramatic bell tower, designed by Tallmadge and Watson. The building also retains a high level of

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material: Lead Glazed

Window Detail:

Window Storms:

Significant Features: Entry tower



Research Information

Origin	al Bui	lding	Owner:
--------	--------	-------	--------

Historic Name: Grace Lutheran Church

Current Name: Grace Lutheran Church

Construction Cost: \$180,000

Architect 1 Information: Tallmadge and Watson

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: Guidebook to the

Architecture of River Forest

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes

The church has a long association with Concordia
University. The interior woodwork is by Joseph
Moroder. Art glass is by C.J. Connick.
- · · ·



Photo 3 / Historic Photo

Survey Information

Doug Gilbert, Douglas Gilbert Architect Preparer:

Survey Date: July 30, 2012



General Information

Street Number: 7200

Former Street Number:

Street: Division Street

PIN Number(s):

Construction Date/Other Year: 1925

Architect: Wilfrid E. Anthony

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the Gothic

Revival Style, the Priory's educational use important in the development of this part of River

Forest.

Roof Ornamentation: Crenellated

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features: Roof tower



Research Information

Origin	al Build	ding Ov	vner:)omi	nican	Orc	lei
--------	----------	---------	-------	--	------	-------	-----	-----

Historic Name: Dominican House of Studies

Current Name: Dominican University Priory

Campilio

Construction Cost: \$900,000

Architect 1 Information: Wilfrid E. Anthony

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:



Subdivision:

Landscape/Streetscape:



priests. The school closed in 1970 but it is still used as
a retreat and education center for Dominican University.

Built as a training school for Dominican Order Catholic



Photo 2

Dhata 2 / Historia Dha	4 -		_

Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 20, 2012



General Information

Street Number: 631

Former Street Number: 310

Street: **Edgewood Place**

PIN Number(s): 15-11-208-002-0000

Construction Date/Other Year: 1905

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Building Form:

Number of Stories: 1 1/2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: This house exhibits a unique

amalgam of Prairie, Tudor and Craftsman design elements; it also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: This house exhibits both Prairie.

Craftsman and Tudor elements.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 603 **Former Street Number:** 294

Street: **Edgewood Place**

PIN Number(s): 15-11-208-006-0000

Construction Date/Other Year: 1908

Architect: Frank Lloyd Wright

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Building Form:

Number of Stories: 1 1/2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Metal

Alterations:



Significant:

Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance:

The most significant, highly stylistic Prairie house designed by Frank Lloyd Wright in River Forest. The house also retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Fixed

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Roman brick, long overhanging

eaves



Research Information

Original Building Owner: Isabel Roberts

Historic Name: Isabel Roberts House

Current Name:

Construction Cost:

Architect 1 Information: Frank Lloyd Wright

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: River Forest National Register

Nomination; Fields: A Guidebook to the Architecture of River Forest

Permit:

Subdivision:

Landscape/Streetscape: Jens Jensen, rear landscape



It was likely that Jens Jensen designed the rear
landscape. Jensen was good friends with Drummond.
living next door and knew many of Wright's colleagues -
probably including Roberts.
,



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 560

Former Street Number: 287

Street: **Edgewood Place**

PIN Number(s): 15-11-207-046-0000

Construction Date/Other Year: 1912

Architect: Drummond and Guenzel

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 1/2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: С

В

Contributing to a **National Register District:** Yes

Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive but more refined

Prairie house designed by William

Drummond.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features:



Research Information		
Original Building Owner:	Albert Muther	
Historic Name:	Albert Muther House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
has been infilled with a randesigned a grotto, not sure	lot on the south side but that ch. Jens Jensen reportedly if there is anything left due to n Wright Plus so the research	
should have more info.	T WINGHET TUS SO THE TESEATOR	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 559

Former Street Number: 288

Street: Edgewood Place

PIN Number(s): 15-11-208-007-0000

Construction Date/Other Year: 1910

Architect: Drummond and Guenzel

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: Yes

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Flat

Roof Material:

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An outstanding example of Prairie

style residential architecture designed and lived in but one of River Forest's most prominent

architects.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features:



Research Information		
Original Building Owner:	William Drummond	
Historic Name:	William Drummond House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register District Nomination; Guide to River Forest, Fields.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Also part of IL Landmark S	urvey	
		Photo 3 / Historic Photo
		Photo 37 historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 555

Former Street Number: 280

Street: **Edgewood Place**

PIN Number(s): 15-11-208-056-0000

Construction Date/Other Year: 1926

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: **Brick**

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Wood Shingle

Alterations:



Significant: Yes

National Register Criterion: С

В

Contributing to a **National Register District:** Yes Potentially Contributing to a

National Register District: Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival noted

> for its geometric front gable form and porch entrance; it also retains

a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Triangle main gable bay and porch

entrance.



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	Ben Badenough	
Historic Name:	Ben Badenough House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: Guidebook to the Architecture of River Forest.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Natao		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 543

Former Street Number: 270

Street: Edgewood Place

PIN Number(s): 15-11-208-054-0000

Construction Date/Other Year: 1899

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 2:

Original Wall Material 1:

Current Wall Material 1: Vinyl Siding

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Vinyl siding installed at some point.

3

Stone

Wood clapboard



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: House owned by George Thatcher,

a prominent attorney in River Forest during the late 1800s on the Village's first corporate attorney. George Thatcher was also the

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: 3 story tower on south east

elevation; free classic porch with columns; second story sleeping

balcony over porch



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	George Thatcher	
Historic Name:	George Thatcher House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register District Nomination	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Check materials		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 535

Former Street Number:

Street: **Edgewood Place**

PIN Number(s): 15-11-208-013-0000

Construction Date/Other Year: 1919

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival

designed by William Drummond; emphasizing a geometric front gable bay and round entrance tower. The house also retains a

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Clipped gable on main gable bay

and slate tower porch entry.



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	O.B. Higgins	
Historic Name:	O.B. Higgins Hiuse	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Guide to River Forest, Fields.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 530

Former Street Number:

Street: **Edgewood Place**

PIN Number(s): 15-11-207-009-0000

Construction Date/Other Year: 1895

Architect: Frank Lloyd Wright

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Wood Shingle

Alterations:



Significant: Yes

National Register Criterion: С

В Yes

Contributing to a

National Register District: Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of Frank Lloyd Wrights early

homes exhibiting stylistic elements that led to his later Prairie style; it also retains a high level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Massive chimney; high pitched

roof,; shingled roof.



Research Information		
Original Building Owner:	Chauncey Williams	
Historic Name:	Chauncey Williams House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Frank Lloyd Wright	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register Nomination; Guide to River Forest, Fields.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		Photo 3 / Historic Photo
		- -
		- -
		-
		- -

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 525

Former Street Number:

Street: Edgewood Place

PIN Number(s): 15-11-208-015-0000

Construction Date/Other Year: 1943

Architect: George Murison

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Art Deco/Moderne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of few outstanding Art

Moderne homes in River Forest, constructed in cut stone. It also retain a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner: Alfred E. Bishop **Historic Name:** Alfred E. Bishop House **Current Name: Construction Cost:** Architect 1 Information: George Murison **Architect 2 Information: Contractor Information: Developer Information:** Research/Archival Information: Fields: Guidebook to the Architecture of River Forest; Permit: Subdivision: Landscape/Streetscape: **Notes**



Photo 2

Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:



General Information

Street Number: 519
Former Street Number: 241

Street: Edgewood Place

PIN Number(s): 15-11-208-016-0000

Construction Date/Other Year: 1925

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Outstanding example of Tudor

Revival country house/cottage designed by Tallmadge and Watson; it also retains a high level

of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Pedimented

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features:



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	Edward Hack	
Historic Name:	Edward Hack House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register District Nomination.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 511 **Former Street Number:** 234

Street: **Edgewood Place**

PIN Number(s): 15-11-208-050-0000

Construction Date/Other Year: 1858

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form: L-Shaped Cottage/House

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Fascia and soffits have been

replaced; vinyl storm windows.



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Home of River Forest's first settler,

> David Cunningham; and one of the earliest homes in River Forest. It is also an excellent example of a more vernacular Italianate-styled

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Label Mold

Window Storms: Yes

Significant Features: Second story balcony; eave

brackets



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	David Cunningham	
Historic Name:	David Cunningham Thatcher House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register District Nomination; Field's: Guidebook to the Architecture of	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 1018

Former Street Number:

Street: Forest Aenue

PIN Number(s): 15-01-307-018-0000, 15-01-307

-019-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Wood Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Prairie house with a

Craftsman clipped gable. This house retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Replace picture.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 1512

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-01-102-032-0000, 15-01-102

-033-0000

Construction Date/Other Year: 1943

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Stucco

Original Wall Material 1: Stone

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive "French Country

House." designed by Jerome Cerny. The house retains a high

level of integrity.

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Central tower, gable dormers and

attached garage.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Jerome Cerney	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		11002
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 16, 2012



General Information

Street Number: 1430

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-01-102-106-0000

Construction Date/Other Year: 1931

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:

Building Form: Number of Stories:

Current Wall Material 1:

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Roof Type:

Roof Material:

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: This house is a distinctive version

of the French Eclectic in River

Forest

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
investigation needed if this individually meets NR criteria. An outstanding individual example of the	
French Eclectic in River Forest.	
	Photo 3 / Historic Photo

Survey Information

Preparer:

Survey Date:



General Information

Street Number: 1403

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-01-103-024-0000

Construction Date/Other Year: 1931

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

with massive chimney and rook line dormers. It also retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Gabled

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Oriel

Window Storms: No

Significant Features: Massive chimney with pots, roof

line dormers.



Photo 2
Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1044

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-01-307-012-0000

Construction Date/Other Year: 1929

Architect: Spencer S. Beman Jr.

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:

Building Form:

Current Wall Material 2:

Original Wall Material 2:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Original Wall Material 1: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Brick

Brick

Roof Material: Slate

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: An excellent example of the French

Eclectic/Normandy architectural style with high integrity. Architect is son of S.S. Bemen, famous for designing the Pullman Factory

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Dominant central tower entrance

bay



Research Information		
Original Building Owner:	Verna Ross Oradorff	
Historic Name:	Verna Ross Oradorff House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Spencer S. Beman	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		Prioto 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Significant house- needs to be surveyed.		
		Photo 3 / Historic Photo
-	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2013



General Information

Street Number: 1037
Former Street Number: 512

Street: Forest Avenue

PIN Number(s): 15-01-308-039-0000

Construction Date/Other Year: 1924

Architect: Edward Probst

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Windows in north bay may have

been replaced.



Significant:

Yes

National Register Criterion: C

В

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

Home of important architect Edward Probst, of Chicago-based Graham, Anderson, Probst and White; art glass done by Giannini & Hilgart, designer of many of Frank

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Label Mold

Window Storms:



Research Information		
Original Building Owner:	Edward Probst	
Historic Name:	Edward Probst House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Edward Probst	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Giannini & Hilgart (art glass)	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Probst was a partner in Gra White, the successor firm to Company, it was his own his		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2012



General Information

Street Number: 1031

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-01-308-004-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Original windows on west elevation

2

may have been replaced. This house may have had brackets



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A unique and only "Chalet" version

of the Craftsman style in River

Forest.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: No



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Swiss chalet style. Check style and permits.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 11, 2012



General Information

Street Number: 1010
Former Street Number: 487

Street: Forest Avenue

PIN Number(s): 15-01-307-020-0000

Construction Date/Other Year: 1915

Architect: Purcell and Elmslie

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: An excellent example of a Prairie-

styled house designed by the noted architecture firm of Purcell and Elmslie, noted. This house retains

a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features: Center gable dormer with wide

eave line.



Research Information		
Original Building Owner:	Henry Einfeldt	
Historic Name:	Henry Einfeldt House	
Current Name:		
Construction Cost:	\$5,000	
Architect 1 Information:	Purcell and Elmslie	
Architect 2 Information:		
Contractor Information:	Guy and McClintock	
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register Historic District nomination.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 947

Former Street Number: 474

Street: Forest Avenue

PIN Number(s): 15-01-314-001-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival with

twin high pitched gables on north elevation. The house retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Twin high pitched gables on north

elevation.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
remit.	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2012



General Information

Street Number: 815

Former Street Number: 394

Street: Forest Avenue

PIN Number(s): 15-01-320-009-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Building Form:

Ornamentation:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Brick

Original Wall Material 1: Stucco

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the more distinctive

Craftsman homes with Prairie stylistic influences. Although the garage has been remodeled, the house retains a high level of

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Significant Prairie influences.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check styles.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2022



General Information

Street Number: 559

Former Street Number: 282

Street: Forest Avenue

PIN Number(s): 15-12-108-013-0000

Construction Date/Other Year: 1916

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Windows may have been replaced

on west elevation except for shed

dormer.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Craftsman "saltbox, "

I-House home in River Forest with

good integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	I Blick Mary
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
remit.	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check significance rating.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 20, 2012



General Information

Street Number: 534

Former Street Number: 255

PIN Number(s): 15-12-107-043-0000

Construction Date/Other Year: 1886

Architect:

Street:

Current Function/Category: Single Family Residential

Ruildinaw

Forest Avenue

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few vernacular

Italianate residential homes in River Forest, later remodeled with a stucco cladding. The house also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	
	Photo 3 / Historic Photo
	Filolo 37 Historic Filolo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2012



General Information

Street Number: 520

Former Street Number: 243

Street: Forest Avenue

PIN Number(s): 15-12-107-048-0000

Construction Date/Other Year: 1879

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Good

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of few remaining Carpenter

Gothic styled houses in River Forest and retains its original window trim and hold molds.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	District O (III) design District
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2012



General Information

Street Number: 504

Former Street Number: 227

Street: Forest Avenue

PIN Number(s): 15-12-107-053-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Attached garage may have been

added at later date.



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive late Foursquare

example with Prairie stylistic elements with a later attached garage. This house also retains a

high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 10, 2012



General Information

Street Number: 303

Former Street Number:

Street: Forest Avenue

PIN Number(s): 15-12-302-013-0000

Construction Date/Other Year: 1911

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form: Bungalow

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Windows may have been replaced

on west elevation.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive local example of the

Chalet Craftsman bungalow style. This house also retains a high level

of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Arched

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features: Side entrance porch



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	ZZAZ
Construction Cost:	
Architect 1 Information:	303
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Power#s	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
	•
	•

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 15, 2012



General Information

Former Street Number:

Street Number: 230

Street: Forest Avenue

PIN Number(s): 15-12-307-009-0000

Construction Date/Other Year: 1887

Architect:

Current Function/Category: Single Family Residential Building

129

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Building Form: Gable Front Cottage/House

Number of Stories: 1 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1:

Ornamentation:

Original Wall Material 2:

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type:

Roof Material:

Alterations:



Significant: Yes

National Register Criterion: A

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: House was original home of the

First Presbyterian Church and the River Forest Women's Club. It also an outstanding example of Queen

Anne architecture.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Gable front with shingle patterns,

original windows.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 12, 2012



General Information

Street Number: 1516

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-104-016-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: River Forest Significant Properties

List

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: Yes

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:
Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A designated River Forest

Landmark and once home to the

Troost family.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information		
Original Building Owner:	Michael P. Troost	
Historic Name:	Michael Troost/William Steep House	
Current Name:		
Construction Cost:	\$16,000	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Michael Troost	
Developer Information:		Photo 2
Research/Archival Information:	RF Landmark Nomination	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		

Notes

Troost was of the Troost family known in the area for their stone monument firm. This house could be a Buurma constructed house - further research and investigation is warranted.

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 22, 2012



General Information

Street Number: 1445

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-108-001-0000

Construction Date/Other Year: 1942

Architect: Michael Troost

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Art Deco/Moderne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A unique version of Art Modern

residential architecture in River

Forest.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms:

Significant Features: Glass block window wall on

southeast elevation.



Research Information

Original Building Owner: Michael Troost

Historic Name: Michael Troost House

Current Name:

Construction Cost:

Architect 1 Information: Michael Troost

Architect 2 Information:

Contractor Information: Michael Troost

Developer Information:

Research/Archival Information: per landmark nomination for 1516

Franklin

Permit:

Subdivision:

Landscape/Streetscape:



Troost was a local builder and member of the family
regionally known for the Troost Monument Co.
•



Photo 2

Photo 3 / Historic Photo		

Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: July 18, 2012



General Information

Street Number: 1418

Former Street Number: 687

Street: Franklin Avenue

PIN Number(s): 15-01-107-038-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An excellent example of the Tudor

Revival in River Forest with high

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 22, 2012



General Information

Street Number: 1227

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-112-038-0000

Construction Date/Other Year: 1955

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:

Building Form:

Number of Stories: 1 1/2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Windows and doors have been

replaced on all elevations.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: **Excellent examples of Mid-Century**

Modern "Shed" residential design.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features: Projecting roof lines and stone

chimneys with alternating colors.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Shares same driveway as 1223 Franklin, possibly	
developed together.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1223

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-112-041-0000

Construction Date/Other Year: 1955

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: Building Form:

Number of Stories:

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Windows and doors have been

replaced on all elevations.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: **Excellent examples of Mid Century**

Modern "Shed" residential design.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features: Projecting roof lines and stone

chimney with alternating colors.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Shares same driveway as 1227 Franklin.	_
	_
	-
	Photo 3 / Historic Photo
	- -
	_
	_
	- -
	_

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1145

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-304-001-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Stucco

Original Wall Material 1: Stone

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

В

Yes

Contributing to a National Register District:

Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: This is a highly distinctive Tudor

Revival attributed to the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail: Ribbon

Window Storms: No

Significant Features: Rough course stone work as

exterior cladding



Research Information

rescaron information		
Original Building Owner:		
Historic Name:		5000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Attributable to Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone front entrance path	
Notes		
Research is further needed	to determine if this is an	
architect designed house.		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1138

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-303-013-0000

Construction Date/Other Year: 1941

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:

Building Form:

Current Wall Material 1:

Number of Stories: 2 ½

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Windows/ French doors may have

Brick

been removed on east elevation.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A Buurma Brothers constructed

house with a distinctive conical entrance bay roof. It is likely this may also be an architect designed

house.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features: Conical tower entrance bay and tile

roof.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture.	FIIIIO Z
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone pavers in entrance path	
Notes		
	ary to determine if this is an	
architect designed house.		
		Photo 3 / Historic Photo
-		
-	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1137

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-304-002-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation: Terra cotta scroll work in central

bay

Stone

Brick

Number of Stories: 2 ½

Current Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Current Wall Material 2:

Original Wall Material 1:

Building Form:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:
Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Spanish Revival

house constructed by the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Entranceway surround, overall

massing and proportion; front chimney, arcaded windows on east

elevation



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Notes		
		_
		_
		Photo 3 / Historic Photo
		_
		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Former Street Number:

Street Number: 1131

Street: Franklin Avenue

PIN Number(s): 15-01-304-003-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

rity

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant:

National Register Criterion: С

Yes

Contributing to a **National Register District:**

Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival home

constructed by the Buurma

Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information: Buurma Brothers	
Developer Information:	Photos
Research/Archival Information:	Photo 2
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	_
-	_
	Photo 3 / Historic Photo
	
	
	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1123

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-304-004-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant:

Yes

National Register Criterion: B

С

Contributing to a National Register District:

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

house constructed by the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Entrance

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Leaded windows, entrance porch

hood, stonework and front entrance

bay window.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information: Buurma Brothers	
Developer Information:	Photos
Research/Archival Information:	Photo 2
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	_
-	_
	Photo 3 / Historic Photo
	
	
	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1122

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-303-009-0000

Construction Date/Other Year: 1934

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival house

constructed by the Buurma

Brothers and retains a high level of integrity. House was once owned by Leonard Japp, founder of Jay's

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Front elevation massing, scolled

timbering.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Dhata 2
Research/Archival Information:		Photo 2
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone paving in front entrance	
Notes		
Further research is needed	to determine if house is	
architect designed.		
	_	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1112

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-303-010-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations: Some windows may have been

replaced on east and south

elevations.



Significant: Yes

National Register Criterion: С

Contributing to a **National Register District:**

Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive French Eclectic

house with its dominant entrance turret/tower, most likely constructed

by the Buurma Brothers.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Surrounds **Door Detailing:**

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: Entrance tower, chimney with

chimney pots



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Dhata 2
Research/Archival Information:		Photo 2
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone front entrance path	
Notes		
Further research is needed	to determine if house is	
architect designed.		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1046

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-309-007-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Current Wall Material 2:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Original Wall Material 1: Stone

Original Wall Material 2: Brick

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations: Some windows on east elevation

may have been replaced.bay

tower.

Brick



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

house constructed by the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features: East elevation chimney, overall

massing and stonework, entrance



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	Buurma Brothers
Developer Information:	
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1039

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-310-002-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Spanish Reviv



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Spansih Revival

house constructed by the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Elaborate Spanish Revival

entrance surround and dominant

west elevation chimney.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	11002
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Further research is needed architect designed.	to determine if house was	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1036

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-309-008-0000

Construction Date/Other Year: 1931

Architect: Arthur Maiwurm

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: **Exceptionally distinctive Tudor**

Revival design by Arthur Maiwurm and constructed by the Buurma Brothers. This house also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Gabled Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Overall building massing, stone

and brick work, chimneys with chimney pots, gabled dormers.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Arthur Maiwurm	
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone pavers in front entrance	
Notes		
		Photo 3 / Historic Photo
_	_	Filoto 37 Historic Frioto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 1029

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-310-003-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Brick

Original Wall Material 1: Stone

Original Wall Material 2: Brick

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Wood Shingle

Alterations: Storm windows are not original to

house.



Photo 1

Significant: Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: This is an exceptionally significant

Yes

French Eclectic house that is most likely an architect designed house constructed by the Buurma

Brothers.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Transom

Porch: Entrance

Dormers: Hipped

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Label Mold

Window Storms: Yes

Significant Features: Brick two story bay, chimney with

chimney pots.



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		The state of the s
Contractor Information:	Attributable to Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		Prioto 37 Historic Prioto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 927

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-316-011-0000

Construction Date/Other Year: 1932

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Stone

Original Wall Material 1: Stone

Original Wall Material 2: Brick

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: В С

Contributing to a **National Register District:** Yes Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

> constructed by the Buurma Brothers and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	11002
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	ue to fence, dense trees and	
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: December 17, 2012



General Information

Street Number: 915

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-316-012-0000

Construction Date/Other Year: 1930

Architect: Olsen and Urbain

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

В

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance: One of the most significant, large

scale Tudor Revival mansions in River Forest, designed by Olsen and Urbain and constructed by the Buurma Brothers. Later home of

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Window glazing on front gable and

Italian Renaissance-styled first

floor bays.



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	William Grunow	
Historic Name:	Grunow House	
Current Name:		
Construction Cost:	\$400,000	
Architect 1 Information:	Olsen and Urbain	
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		

Notes

Landscape/Streetscape:

Grunow was the manufacturer of Majestic Radios

Tony "the Big Tuna" Accardo lived in the house from 1953 a 1961, Accardo ran the Chicago Outfit mafia for many decades and had started by working for Al Capone

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 847

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-322-001-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

В

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance: One of the few distinctive Spanish

Revival/Eclectic homes in River Forest. This home was constructed by the Buurma

Brothers and retains a high level of

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:	Fence with stucco-faced niere/noete: and bluestone front	
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group



General Information

Street Number: 838
Former Street Number: 415

Street: Franklin Avenue

PIN Number(s): 15-01-321-015-0000

Construction Date/Other Year: 1927

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant:

В

Yes

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

designed by Tallmadge and Watson and constructed by the Buurma Brothers. This house retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Dominant north gable bay,

timbering, diamond pane casement

windows



Research Information

Original Building Owner: R.F. Locke

Historic Name: R.F. Locke House

Current Name:

Construction Cost:

Architect 1 Information: Tallmadge and Watson

Architect 2 Information:

Contractor Information: Buurma Brothers

Developer Information:

Research/Archival Information: Fields: A Guidebook to River

Forest Architecture



Notes			



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Former Street Number:

Street Number: 830

Street: Franklin Avenue

PIN Number(s): 15-01-321-009-0000

Construction Date/Other Year: 1928

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

407

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Brackets under roof line eaves,

arched windows in first floor

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Windows/ French doors on east

> elevation may have been replaced. Rear one- story addition may have



Significant: Yes

National Register Criterion: С В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings**

Reason for Significance:

Less Than 50 Years Old:

The only Italian Renaissance house designed by Tallmadge and Watson in River Forest. It also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Entrance porch and surrounds,

arched windows



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	W.J. Clarkson	
Historic Name:	W.j. Clarkson House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
	-	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Street Number: 822

Former Street Number: 397

Street: Franklin Avenue

PIN Number(s): 15-01-321-010-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Italian Renaissance

house with elaborate front entrance surround and campanile tower on south elevation. This house also retains a high level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Elaborate door surround.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Re check style.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 19, 2012



General Information

Street Number: 811

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-01-322-012-0000

Construction Date/Other Year: 1957

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Building Form: Ranch

Number of Stories: 1

Current Wall Material 1: Brick

Current Wall Material 2:

Ornamentation:

Original Wall Material 1: Brick

Original Wall Material 2:

Storefront Material:

Wall Detailing/Ornamentation:

Roof Type:

Roof Material: Not visible/cannot be determined

Flat

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the more exceptional Mid-

Century Modern homes in River Forest with a distinctive low-slung "shed roof" design. This house also retains a high level of intergity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms: No

Significant Features: Slanted shed roof design typical of

high Mid-Century Modernism



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Additional research is needed to determine design	
architect	
	Photo 3 / Historic Photo
	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 2012



General Information

Street Number: 751

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-12-104-030-0000

Construction Date/Other Year: 1909

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Prioto 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Prairie house

designed by Tallmadge and Watson and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner: John B. Piggott

Historic Name: John Piggott House

Current Name:

Construction Cost: \$7000

Architect 1 Information: Tallmadge and Watson

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: A Guidebook to River

Forest Architecture

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes			



Photo 2

DI 4 0/111 4 1 DI		

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Street Number: 742

Former Street Number: 365

Street: Franklin Avenue

PIN Number(s): 15-12-103-018-0000

Construction Date/Other Year: 1912

Architect: Robert C. Spencer, attributed

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

2 ½

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the more simplified but

distinctive Prairie home attributed to Robert Spencer in River Forest. This house retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

rescaren information		
Original Building Owner:	Clem De Graw	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Historic Name:	Clem De Graw House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Robert C. Spencer, attributed	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Street Number: 632

Former Street Number: 319

Street: Franklin Avenue

PIN Number(s): 15-12-109-023-0000

Construction Date/Other Year: 1889

Architect: W.J. Van Keuren

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:
Building Form:

Number of Stories: 3

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Deck addition on west elevation.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A classic, distinctive example of a

Queen Anne house in River Forest with characteristic Palladian window on north elevation. The house also retains a high level of

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Palladian

Window Storms:

Significant Features:



Research Information

Original Building Owner: Jacob Frank

Historic Name: Jacob Frank House

Current Name:

Construction Cost: \$7,000

Architect 1 Information: W.J. Van Keuren

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: A Guidebook to River

Forest Architecture

Permit:

Subdivision:

Landscape/Streetscape:

Notes			



Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: September 25, 201



General Information

Street Number: 612

Former Street Number: 299

Street: Franklin Avenue

PIN Number(s): 15-12-109-045-0000

Construction Date/Other Year: 1911

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive early Tudor

Revival in the form of a Queen Anne home. This house retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 601

Former Street Number: 284

Street: Franklin Avenue

PIN Number(s): 15-12-110-008-0000

Construction Date/Other Year: 1910

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Ornamentation:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A

A highly unique house that combines aspects of the Craftsman and Prairie styles. The large gabled dormers are also unique. This house retains a high level of

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Full Front

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Gabled dormers on three sides



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check for significance.	
·	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 27, 2012



General Information

Street Number: 600

Former Street Number: 283

Street: Franklin Avenue

PIN Number(s): 15-12-109-031-0000

Construction Date/Other Year: 1897

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Queen Anne with

> unique eyebrow dormer on south elevation. It retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Eyebrow window on east elevation

roof.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 559

Former Street Number: 280

Street: Franklin Avenue

PIN Number(s): 15-12-110-045-0000

Construction Date/Other Year: 1910

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One one of two masonry Queen

Anne homes in River Forest with a distinctive two story round nay tower. It also retains a high level of

integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Round tower on south elevetion.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
check for style and significance.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 558

Former Street Number: 279

Street: Franklin Avenue

PIN Number(s): 15-12-109-032-0000

Construction Date/Other Year: 1908

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Stucco

Current Wall Material 2: Vinyl Siding

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Originally a Queen Anne that was

later modified with Prairie porch and stucco wall covering.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive, late Queen Anne

> house reclad in stucco with unique polygonal tower and steeply pitched dormer. This house retains

a high level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Sidelights

Full Front Porch:

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Porte-cochere on north elevation



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Based on building massing and features, especially the polygonal second floor tower, the original wall cladding may have been shingles.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Street Number: 538

Former Street Number: 271

Street: Franklin Avenue

PIN Number(s): 15-12-109-036-0000

Construction Date/Other Year: 1908

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Foursquare with

Prairie stylistic influences, including porch, deep eave lines and dormer. This house also retains a high level

of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers: Arched

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Prairie styled dormer on east

elevation.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	Those 37 Historic Filodo
-	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Former Street Number:

Street Number: 535

Street: Franklin Avenue

PIN Number(s): 15-12-110-014-0000

Construction Date/Other Year: 1916

Architect:

Current Function/Category: Single Family Residential Building

258

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive side-gabled Prairie

house that retains a high level of

integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 534

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-12-109-037-0000

Construction Date/Other Year: 1909

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Foursquare with

Prairie stylistic influences on porch and gables. This house also retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Art Glass

Window Material:

Window Detail:

Window Storms:

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Former Street Number:

Street Number: 530

Street: Franklin Avenue

PIN Number(s): 15-12-109-038-0000, 15-12-109

267

-043-0000

Construction Date/Other Year: 1906

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Foursquare with

> significant Prairie stylistic elements. This house also retains a high level

of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Full Front Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: East elevation bay window; front

> Free Classic porch, which may have been open when first

constructed.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Street Number: 523

Former Street Number: 246

Street: Franklin Avenue

PIN Number(s): 15-12-110-017-0000

Construction Date/Other Year: 1910

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: This is a highly distinctive Prairie

> Foursquare with wood clad boarding and wide eaves.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Full Front Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Wide eaves, use of clad boarding

on elevations



Research Information		
Original Building Owner:	James Harper	
Historic Name:	James Harper House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register Historic District Nomination	11100 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 27, 2012



General Information

Street Number: 515

Former Street Number:

Street: Franklin Avenue

PIN Number(s): 15-12-110-019-0000

Construction Date/Other Year: 1920s

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the smaller churches in

River Forest designed in the Gothic Revival style but is distinctive in its own right. It retains a high level of

integrity.

Roof Ornamentation: Crenellated

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Metal

Window Detail: Clerestory

Window Storms: No

Significant Features: Dominant gable and stained glass

windows.



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:	Christ Episcopal Church.	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		1.002
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Check for significance.		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 147

Former Street Number: 94

Street: Franklin Avenue

PIN Number(s): 15-12-316-001-0000

Construction Date/Other Year: 1914

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Brackets, horizontal banding, art

gia

Building Form: Foursquare

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Distinctive Prairie style example in

Hipped

southern River Forest with excellent porch and dormer

detailing.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Full Front

• •

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Dormers:

Window Storms: Yes

Significant Features:



Research Information		
Original Building Owner:	Emma Herzog	
Historic Name:		
Current Name:		
Construction Cost:	\$4500	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Duff Houston	
Developer Information:		Photo 2
Research/Archival Information:		Photo 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
-		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: October 9, 2012



General Information

Street Number: 343

Former Street Number:

Street: Gale Avenue

PIN Number(s): 15-12-300-003-000

Construction Date/Other Year: 1922

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 1 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Windows have been replaced on

west and south elevations.



Prioto 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: The only residential building in

River Forest in a simplified, stoneconstructed Collegiate/Gothic

Revival.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: Porch as classical Revival

elements.



Research Information

Original Building Owner:	Thomas MacArthur			7
Historic Name:	Thomas MacArthur House			
Current Name:			里里	-
Construction Cost:			I THE	4
Architect 1 Information:				4
Architect 2 Information:			TERRO	
Contractor Information:	Thomas MacArthur		The state of the s	
Developer Information:		Photo 2		
Research/Archival Information:				
Permit:				
Subdivision:				
Landscape/Streetscape:				
Notes				
		Photo 3 / Historic Photo		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 214 **Former Street Number:** 111

Street: Gale Avenue

PIN Number(s): 15-11-402-016-0000

Construction Date/Other Year: 1902

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Current Wall Material 2:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: An outstanding example of

> Colonial/Dutch Colonial architecture; the two roofline towers are especially distinctive; overall integrity and condition is

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Partial

Window Type: Double-Hung

Window Material: Wood

Window Detail:

Window Configuration:

Dormers:

Window Storms: Yes

Significant Features: Towers on each end of second

Gabled

1 over 1

story roof line



Research Information

Original Building Owner:		
Historic Name:	H.E. Page House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 17, 2012



General Information

Street Number: 202

Former Street Number:

Street: Gale Avenue

PIN Number(s): 15-11-402-019-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco


Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Wood Shingle

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A Tudor Revival with geometric

ornament on south elevation gable that suggests a Prairie influence.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:		
Historic Name:	H.A. Ullrich House	
Current Name:		
Construction Cost:		
Architect 1 Information:		COOCC
Architect 2 Information:		
Contractor Information:		F-3.6.42.20
Developer Information:		Photo 2
Research/Archival Information	:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Need to take picture at late	er date.	
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 17, 2012



General Information

Street Number: 7900

Former Street Number:

Street: Greenfield Street

PIN Number(s): 15-01-101-023-0000

Construction Date/Other Year: 1952

Architect: Jerome Cerny

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Cornice line dormers, asymmetrical

form, shutter, first floor bay

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Wood Shingle

Alterations: Windows may have been replaced

- Unclear if stone was not originally

painted.



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: This is a distinctive version of the

French Eclectic/French Country House in River Forest designed by

Jerome Cerny.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: Other

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features: Cornice line arched dormers,

steeply pitched roof, two large

chimneys



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information: Jerome Cerny	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Assessors date may be inaccurate. This appears to be an earlier house. Research is needed to determine architect/contractor.	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 3, 2012



General Information

Street Number: 7849

Former Street Number:

Street: Greenfield Street

PIN Number(s): 15-01-110-003-0000

Construction Date/Other Year: 1940

Architect: Jerome Cerny

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An distinctive example of the

French Eclectic style in River Forest designed by Jerome Cerny.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Gabled

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms: Yes

Significant Features: Massive chimney, steep pitched

roofs.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
This house was difficult to survey give orientation and	
vegetation.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 18, 2012



General Information

Street Number: 1040

Former Street Number:

Street: Harlem Avenue

PIN Number(s): 15-01-406-010-0000

Construction Date/Other Year: 1949 - 53

Architect: Loebel, Schlossman & Bennett

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: carved stone relief on wall

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2: Brick

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Metal

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Distinctive style example with

excellent integrity, use of carved relief ornament is rare in River Forest and on Jewish Temples.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features:



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:	West Suburban Temple Har Zion	
Construction Cost:		
Architect 1 Information:	Loebel, Schlossman & Bennett	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Dhata 2
Research/Archival Information:		F1101.0 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
The sculpture on the facad		
reportedly the first modern	figurative temple sculpture.	
		Prioto 37 nistorie Proto
Architect 2 Information: Contractor Information: Developer Information: Research/Archival Information: Permit: Subdivision: Landscape/Streetscape: Notes The sculpture on the facad	Yes	Photo 2 Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 30, 2012



General Information

Street Number: 536

Former Street Number:

Street: Harlem Avenue

PIN Number(s):

Construction Date/Other Year: 1936

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a **National Register District:** Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent Tudor style in a larger

> institutional example, Forest Preserve Headquarters.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers: Gabled

Window Type: Fixed

Multi-Paned **Window Configuration:**

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features:



Research Information

Original Building Owner:		
Historic Name:		
Current Name:	Cook County Forest Preserve	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		•

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 20, 2012



General Information

Street Number: 7426

Former Street Number:

Street: lowa Street

PIN Number(s): 15-01-409-010-0000

Construction Date/Other Year: 1897

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Barge board, buttons, bay window

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Inappropriate rear deck



Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of Queen Anne

Yes

style, not commonly found in this part of River Forest, excellent detailing and use of materials.

Roof Ornamentation: Vergeboard

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Bay window



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 8, 2012



General Information

Street Number: 1427

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-207-007-0000

Construction Date/Other Year: 1932

Architect: Harold Zook

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2: Stucco

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Tile

Alterations: Some additions to rear are not

visible, replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Only documented house in River

Forest design by noted Hinsdale architect Harold Zook. It also an excellent example of Zook's work in

the Tudor Revival style.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms:

Significant Features: Incorporates spiderweb window

unique to Zook



Research Information		
Original Building Owner:	Walter Johnson	
Historic Name:	Walter Johnson House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Harold Zook	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
Harold Zook was a promine	ent architect from Hinsdale.	
He is best known for his Tu	idor Revival and Cotswold	
Cottage Style designs in th	e Unicago area.	
-		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 20, 2012



General Information

Street Number: 1302

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-212-024-0000

Construction Date/Other Year: 1936

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Art Deco/Moderne

Ornamentation: horizontal and vertical banding

Building Form:

Number of Stories: 2

Current Wall Material 1: Stone

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Sensitive side addition replaced an

earlier inappropriate addition



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Very distinct and rare example of

the Art Moderne style in River

Forest.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms:

Significant Features: Balcony



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 23, 2012



General Information

Street Number: 1046

Former Street Number: 521

Street: Jackson Avenue

PIN Number(s): 15-01-404-007-0000

Construction Date/Other Year: 1925

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Stone window surrounds, corner

tower

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Grand example of the Tudor

Revival style with large and highly

detailed entry turret.

Roof Ornamentation: Crenellated

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Entry tower with pointed arches

and crenellations



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 1025

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-405-005-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, stone detailing,

stone chimney with pots

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the Tudor

Revival style, unusual placement on site, dramatic form that is more picturesque than most houses in

River Forest

Roof Ornamentation: Crenellated

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail: Paired

Window Storms: No

Significant Features: Rambling form, entry turret



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 1, 2012



General Information

Street Number: 1020

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-404-010-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Arched and Palladian windows,

plain stone piers, dropped stone

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Tile

Alterations:



Photo

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Unusual blend of Renaissance and

Deco styles, the main form is Italian Renaissance style but many

of the details are Art Deco

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Palladian

Window Storms: Yes

Significant Features: Vertically fluted stone corners



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 918

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-407-016-0000

Construction Date/Other Year: 1928

Architect: James F. Denson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation: Rope columns, iron balconies,

arched openings

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Tile

Alterations: Large rear addition not visible



Photo

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Distinctive example of rare Spanish

Revival style with excellent integrity

and detailing.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail: Paired

Window Storms:

Significant Features: Small porch above entry



Research Information

Original Building Owner:

Historic Name:	Sawiak House	
Current Name:		
Construction Cost:	\$7000	
Architect 1 Information:	James F. Denson	

Philip and Olga Sawiak

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes			

j		

Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 800

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-01-413-014-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Inset stone, awning

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Distinctive example of the French

Towers/Turrets

Eclectic style with excellent integrity, distinctive turret and entry

and matching style for the garage.

Foundation Material/Form:

Roof Ornamentation:

Door Detailing:

Porch: Terrace

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail: Paired

Window Storms:

Significant Features: Turret, crenelated entry portico



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 745

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-12-201-003-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Classical entry, shutters, classical

dormers

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Tile

Alterations: Slightly visible modern rear

addition



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Distinctive, grand example of the

> Colonial Revival style with high quality materials and detailing.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Terrace

Gabled Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Dormers, stonework



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 707

Former Street Number: 330

Street: Jackson Avenue

PIN Number(s): 15-12-201-009-0000

Construction Date/Other Year: 1920

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Arched entry canopy, entry side

and fan lights, eyebrow order,

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Small rear addition



Photo 1

Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Unusual example of the Colonial

> Revival style with Prairie style influences in the horizontal brick

and entry canopy.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Arched Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: No

Significant Features: Horizontal banding of brick, open

eaves



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$13500	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Edwin H. Wood	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 607

Former Street Number: 296

Street: Jackson Avenue

PIN Number(s): 15-12-207-006-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Eaves corbels, stone urns,

balustrade

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: Open porch enclosed



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Italian Renaissance style

example with unusual corner setting and distinctive use of materials and detailing.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Terrace

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Palladian

Window Storms: Yes

Significant Features: Entry portico, porte cochere



Research Information

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 551

Former Street Number: 274

Street: Jackson Avenue

PIN Number(s): 15-12-213-002-0000

Construction Date/Other Year: 1922

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Arched entry, shutters, Palladian

window

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and well detailed

example of the Colonial Revival

style.

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 539

Former Street Number:

Street: Jackson Avenue

PIN Number(s): 15-12-213-004-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Wrought ironwork, half timbering,

brick nogging, window trim

Building Form: L-Shaped Cottage/House

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Side Gabled

Roof Material: Slate

Alterations: Large visible side enclosed porch



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Very grand, highly designed and

detailed example of the Tudor Revival style with excellent mix of

materials.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Gabled Dormers:

Window Type: Casement

Window Configuration: Diamond Pane

Window Material:

Window Detail: Hood Mold

Window Storms: Yes

Significant Features: Massive chimney, side garden

walls



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 1433

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-102-017-0000

Construction Date/Other Year: 1937

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Quoin work

Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive French Eclectic house

mostly likely developed by the Buurma Brothers and attributed to

Jerome Cerny.

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Arched

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Attributed to Jerome Cerny	
Architect 2 Information:		
Contractor Information:	Attributed to Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:	Front entrance path bluestone	
Notes		
This property may be designed research is needed to determine the control of the		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 3, 2012



General Information

Street Number: 1419

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-102-020-0000

Construction Date/Other Year: 1931

Architect: attributed to Harold Zook

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



FIIOLO

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: The house retains typical feature of

a Harold Zook designed house including its Art Deco entrance surround and spider web window on south elevation. It is a highly

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Spider web window over front

entrance on south elevation is a

distinguishing feature.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	ALT THE PARTY OF A SECOND
Architect 1 Information: attributed to Harold Zook	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit: Subdivision:	
Landscape/Streetscape:	
Notes	
Attributes typical to Harold Zook designed house, including the spider web window and the Art Deco entry detailing. This needs to be confirmed with further research.	
iesearon.	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 3, 2012



General Information

Street Number: 1408

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-101-020-0000

Construction Date/Other Year: 1939

Architect: Robert Seyfarth

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Wood Shingle

Alterations: Garage is new construction;

windows have been replaced.



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive example of a French

Eclectic country "barn houses.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features: Steeply pitched roof and second

floor recessed windows.



Research Information

Original Building Owner:		
Historic Name:	McGrath House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Robert Seyfarth	
Architect 2 Information:		
Contractor Information:		THE RESERVE AND ASSESSMENT OF THE PERSON NAMED IN COLUMN TWO PARTY.
Developer Information:		Photo 2
Research/Archival Information:	Robert Seyfarth website: http: //www.robertseyfartharchitect. com/index.html	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Cerney designed building. a barn form. Garage is rec replacements.c		
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 16, 2012



General Information

Street Number: 1111

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-301-010-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

mansion that may attributable to the Buurma Brothers given its overall massing and design. It retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Hipped

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Oriel

Window Storms:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Bluestone front pathway pavers may indicate this house	
could habe been constructed by the Buurma Brothers. This is a distinctive house that merits further research.	
This is a distillictive modes that ments faither research.	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 1103

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-301-012-0000

Construction Date/Other Year: 1926, expanded 1936

Architect: Meyer and Cook

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation: Stained glass trefoil windows,

cartouches, spiral, fluted columns;

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Stone

Original Wall Material 1: Stucco

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: 1950s addition to the east

elevation.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the few Spanish Revival

> homes in River Forest and the most distinguished in its architectural features, ornamentation and its use of

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing: Surrounds

Partial Porch:

Dormers:

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Hood Mold

Window Storms: No

Significant Features: Elaborate brackets, tile roof,

arched porch arcade.



Research Information

Original Building Owner:		
Historic Name:	Joseph J. Butler House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Meyer and Cook	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:	Garden wall and trellis	
Notes		
	of Streets and Sanitation. He	
built the house originally as greatly expanded in 1936 for		
	or a fair time residence.	Physical Cilindric Physics
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 1100

Former Street Number: 521

Street: Keystone Avenue

PIN Number(s): 15-01-300-021-0000

Construction Date/Other Year: 1924

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Gambrel roof.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations: Some windows may have been

replaced on second story.



Photo 1

Significant: Yes

National Register Criterion: A

Contributing to a

National Register District: Potentially Contributing to a National Register District: Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of two Sears Pre-Cut Colonial

Revival homes to be constructed in River Forest during the 1920s. This appears to be the "Martha Washington" model sold by Sears

Roof Ornamentation:

Foundation Material/Form: Brick

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture.	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 3, 2012



General Information

Street Number: 1047

Former Street Number: 522

Street: Keystone Avenue

PIN Number(s): 15-01-307-029-0000

Construction Date/Other Year: 1917

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 1 1/2

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the more distinctive Prairie

> homes constructed by the Vierow Brothers and retains a high level of

integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information		
Original Building Owner:	Robert Worthington	
Historic Name:	Robert Worthington House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Vierow Brothers	
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register Historic District Nomination	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
Check this house for significaddition.	cance. There may be an	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 915

Former Street Number: 444

Street: Keystone Avenue

PIN Number(s): 15-01-313-005-0000

Construction Date/Other Year: 1899

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Palladian gable

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: First floor west elevation windows

may have been changed.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An outstanding example of an early

Foursquare designed with Colonial Revival elements, including

Palladian gable and corner column pilasters. The home also retains a

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Full Front

Dormers: Pedimented

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Full width porch and Palladian front

dormer



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Garage is new construction.	
	Photo 3 / Historic Photo
	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 815

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-01-319-009-0000

Construction Date/Other Year: 1917

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Bungalow

Number of Stories: 1 1/2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Craftsman bungalow

with front dormer with art glass and flared eaves. This house retains a

high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stucco

Sidelights **Door Detailing:**

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Material: Wood

Window Configuration:

Window Detail: Ribbon

Window Storms: No

Significant Features: Centered roof dormer with art glass

Art Glass

windows; Craftsman/ Prairie

arched entry porch.



Original Building Owner: Baldwin and Elizabeth Kannenberg Historic Name: Baldwin Kannenberg House Current Name: Construction Cost: \$7,000 Architect 1 Information: Architect 2 Information: Contractor Information: Developer Information: Photo 2
Current Name: Construction Cost: \$7,000 Architect 1 Information: Architect 2 Information: Contractor Information: August Peterson Developer Information:
Construction Cost: \$7,000 Architect 1 Information: Architect 2 Information: Contractor Information: August Peterson Developer Information:
Architect 1 Information: Architect 2 Information: Contractor Information: August Peterson Developer Information:
Architect 2 Information: Contractor Information: August Peterson Developer Information:
Contractor Information: August Peterson Developer Information:
Developer Information:
Developer Information:
Research/Archival Information:
Permit:
Subdivision:
Landscape/Streetscape:
Notes
Photo 3 / Historic Photo
-

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 807

Former Street Number: 386

Street: Keystone Avenue

PIN Number(s): 15-01-319-011-0000

Construction Date/Other Year: 1914

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2: Stucco

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations: Original windows appear to have

been removed.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive Prairie styled house

that was altered with stone facing typical of the Mid-Century Modern

style.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Aluminum

Window Detail: Ribbon

Window Storms: No

Significant Features: Stone refacing on lower half

undertaken in the 1960s according

to property owner.



Research Information

Original Building Owner:		
Historic Name:	Frank D. Abbbot House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Spencer and Powers	
Architect 2 Information:		
Contractor Information:	Guy and McClintock	
Developer Information:		Photo 2
Research/Archival Information	n:	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
Re check this.		-
		-
		Photo 3 / Historic Photo
		Photo 37 Historic Photo
		-
		- -
		-
-		• •

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 4, 2012



General Information

Street Number: 737

Former Street Number: 360

Street: Keystone Avenue

PIN Number(s): 15-12-101-004-0000

Construction Date/Other Year: 1927

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the more distinctive

Tallmadge and Watson homes in River Forest with engaged piers on west elevation and cross-gabled roof form. It also retains a high

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: No



Research Information		
Original Building Owner:	Paul Oliver	
Historic Name:	Paul Oliver House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Could not view garage from sidewalk.		
		Photo 3 / Historic Photo
-		
-	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 727

Former Street Number: 352

Street: Keystone Avenue

PIN Number(s): 15-12-101-005-0000

Construction Date/Other Year: 1907

Architect: Spencer and Powers

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material:

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the more significant Tudor

homes designed by Spencer and Powers but has many Prairie stylistic elements. It retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Casement

Window Configuration: Art Glass

Window Material:

Window Detail:

Window Storms: No



Research Information		
Original Building Owner:	C.S. Pellet	
Historic Name:	Pellet House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Spencer and Powers	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		Prioto 2
Permit:		
Subdivision:		
Landscape/Streetscape:	Marshall Johnson-designed	
Notes		
Marshall Johnson, son-in-lathe original landscape.	aw to Jens Jensen, designed	
		Photo 3 / Historic Photo
		Filoto 37 ristolic Filoto
	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 720

Former Street Number: 341

Street: Keystone Avenue

PIN Number(s): 15-12-100-006-0000

Construction Date/Other Year: 1916

Architect: H.G. Fiddelke

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Wood Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few Fiddelke homes in

River Forest. This house is a large side gabled house designed in the Prairie style and retains a high

level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers: Gabled

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:



Research Information

Original Building Owner:	John J. Arnold zhouse	
Historic Name:	John J. Arnold House	
Current Name:		
Construction Cost:		
Architect 1 Information:	H.G. Fiddelke	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Check style on this house.		
		Photo 3 / Historic Photo
		Filoto 37 Historic Filoto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 706

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-12-100-012-0000

Construction Date/Other Year: 1894

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Tudor elements in timbering and

porch columns.

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Stone

Original Wall Material 1: Stucco

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Queen Anne

Foursquare with Craftsman detailing. This house also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	-
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Unclear if this has been recently remodeled. Evidence of timbering in west gable.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 633

Former Street Number: 322

Street: Keystone Avenue

PIN Number(s): 15-12-107-001-0000

Construction Date/Other Year: 1920

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: English Arts and Crafts features.

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Storefront Material:

Wall Detailing/Ornamentation:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly unique and distinctive

example of an English Arts and Crafts house in River Forest. The house also retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: No



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
_unuscape/encetosape.	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 620

Former Street Number: 297

Street: Keystone Avenue

PIN Number(s): 15-12-106-003-0000

Construction Date/Other Year: 1914

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Has Prairie influences including

stucco walls and casement

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A unique, distinctive Italian

Renaissance house with Prairie style detailing in wall cladding and

window arrangement.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms:

Significant Features: Italian Renaissance form; shed

dormer.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
An usual building form for a Prairie house in River	
Forest house- it has an Italian Renaissance form with	
Prairie detailing.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 619

Former Street Number: 310

Street: Keystone Avenue

PIN Number(s): 15-12-107-006-0000

Construction Date/Other Year: 1926

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

B Yes

Contributing to a

National Register District:
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Or

One of William Drummond's most distinctive design in the Tudor Revival. It also retains a high level

of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration:

Window Material:

Window Detail:

Window Storms: No



Research Information

Original Building Owner:	Edward Scott	
Historic Name:	Edward Scott House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Informatio	n:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 615

Former Street Number: 302

Street: Keystone Avenue

PIN Number(s): 15-12-107-007-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive large scale Tudor

Revival house that retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
	·
9	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Former Street Number:

Street Number: 612

Street: Keystone Avenue

PIN Number(s): 15-12-106-004-0000

Construction Date/Other Year: 1916

Architect:

Current Function/Category: Single Family Residential Building

293

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material:

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive late Queen Anne

house designed in the Prairie style. It retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 611

Former Street Number: 296

Street: Keystone Avenue

PIN Number(s): 15-12-107-008-0000

Construction Date/Other Year: 1879

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: The Charles A Wilmeroth House, a

distinct and one of the few Italianate homes in River Forest. This house retains a high level of

integrity.

Entrance

Roof Ornamentation:

Porch:

Foundation Material/Form: Brick

Door Detailing: Transom

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms:



Research Information		
Original Building Owner:		
Historic Name:	Charles A Wilmeroth House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Check this again for rear ac	ddition.	_
		_
		Photo 3 / Historic Photo
-		_
		- -
		_
		-
		- -

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 606 Former Street Number: 287

Street: Keystone Avenue

PIN Number(s): 15-11-209-009-0000, 15-12-106

-005-0000

Construction Date/Other Year: 1906

Architect: E.E Roberts

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Brick

Original Wall Material 1: Stucco

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival house

design by Prairie School architect E.E. Roberts. This house also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material:

Window Detail: Ribbon

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:	C.C Collins House	
Current Name:		
Construction Cost:		
Architect 1 Information:	E.E. Roberts	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		- -
		Photo 3 / Historic Photo
		_ _
		- -
		_
		- -

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 605

Former Street Number: 292

Street: Keystone Avenue

PIN Number(s): 15-12-107-009-0000

Construction Date/Other Year: 1906

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:


Storefront Material:

Roof Type: Hipped

Roof Material:

Alterations: Windows may have been replaced.

on west elevation.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A unique Queen Anne home with

an a distinctive Italianate central tower. This house also retains a

good level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Full Front

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check this one again.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 601
Former Street Number: 280

Street: Keystone Avenue

PIN Number(s): 15-12-107-010-0000

Construction Date/Other Year: 1904

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive early Tudor Revival

home with some Prairie stylistic elements and a modified Queen

Anne form.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Partial

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: No



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
<u> </u>	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 562

Former Street Number: 285-89

Street: Keystone Avenue

PIN Number(s): 15-11-209-011-0000, 15-12-106

-006-0000

Construction Date/Other Year: 1909 with additions in 1917 and

1026

Architect: Frank Lloyd Wright

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Addition constructed on west

elevation in 1981



Significant: Yes

National Register Criterion: C

В

Contributing to a
National Register District: Yes
Potentially Contributing to a
National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive high style Prairie

home designed by Frank Lloyd Wright in River Forest, and later remodeled by William Drummond. This house retains a high level of

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms: No



Research Information

Original Building Owner: J. Kibbons

Historic Name: J. Kibbons Ingalls House

Current Name:

Construction Cost:

Architect 1 Information: Frank Lloyd Wright

Architect 2 Information: William Drummond

Contractor Information:

Developer Information:

Research/Archival Information: Fields: A Guidebook to River

Forest Architecture

Permit:

Subdivision:

Landscape/Streetscape:

Notes	



Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 558

Former Street Number: 281

PIN Number(s): 15-11-209-013-0000, 15-12-106

-007-0000, 15-12-106-016-0000

Keystone Avenue

Construction Date/Other Year: 1868

Architect:

Street:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form: T-Shaped Cottage/House

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few Gothic/Carpenter

Revival homes in River Forest and retains a high level of integrity.

Roof Ornamentation: Vergeboard

Foundation Material/Form: Brick

Door Detailing: Transom

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes



Research Information

Original Building Owner:	Solomon Thatcher	
Historic Name:	Solomon Thatcher House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 547

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-12-107-014-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Wood Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few Tudor Revival

homes located along keystone Avenue and retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 530

Former Street Number:

Street: Keystone Avenue

PIN Number(s): 15-12-106-024-0000

Construction Date/Other Year: 1910

Architect: Spencer and Powers

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive, important design by

> Robert Spencer - a refined example of the Prairie Style in River Forest with intact art glass windows. This house also retains

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms: No



Research Information		
Original Building Owner:	John W. Broughton	
Historic Name:	John W. Broughton House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Robert Spencer	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	F110.02
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	nt of the River Forest State	
Bank		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Former Street Number:

Street Number: 518

Street: Keystone Avenue

PIN Number(s): 15-12-106-019-0000, 15-12-106

245

-020-0000

Construction Date/Other Year: 1883 (1921)

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Second Empire

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: **Brick**

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Mansard

Roof Material: Asphalt Shingle

Alterations: Some elements, including its

original tower/cupola were removed during an earlier



Significant: Yes

National Register Criterion: С В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: This house is associated with

Thatcher family, a prominent early family in River Forest; it is also a grand, rare example of the Second

Empire style

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Full Front

Dormers: Arched

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Label Mold

Window Storms: Yes



Research Information		
Original Building Owner:	Solomon and Clara Thatcher	
Historic Name:	Solomon Thatcher Jr. House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		F1000 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Thatcher was a founder of	River Forest and helped	
found the Methodist Church	1	
Rear additions added in 19	20s in a Spanish Revival	Diet O (Water Diet
style by then owner J.C. Hi	ggins	Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 14, 2012



General Information

Street Number: 517

Former Street Number: 240

Street: Keystone Avenue

PIN Number(s): 15-12-107-020-0000

Construction Date/Other Year: 1916

Architect: Drummond and Guenzel

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 1/2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance:

A highly distinctive house designed by William Drummond, utilizing a Foursquare form and a side gabled roof shape. This house also retains a high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Diamond shaped windows in side

gables.



Research Information		
Original Building Owner:	John A. Klasert	
Historic Name:	John A. Klasert House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Drummond and Guenzel	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	11362
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	_	
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 344

Former Street Number: 187

PIN Number(s): 15-12-300-015-0000, 15-12-300

-016-0000

Keystone Avenue

Construction Date/Other Year: 1883

Architect:

Street:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Mansard

Roof Material: Asphalt Shingle

Alterations: Swimming pool in rear house in

Italianate styled barn.



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: An outstanding example of

Italianate "villa" architecture with high integrity. Constructed by one of River Forest's most prominent early citizens. This house retains a

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Partial

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Hood Mold

Window Storms: No

Significant Features: Central bay belvedere tower,

window hoods, porch.



Research Information

Original Building Owner:	William F. Blocki	
Historic Name:	William F. Blocki House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		The last of the last
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
construction date per owne the house	r's research and materials in	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 309 **Former Street Number:** 145

Street: Keystone Avenue

PIN Number(s): 15-12-300-024-0000

Construction Date/Other Year: circa 1881

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: Yes

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: An outstanding example of Queen

Anne residential architecture with

Stick style elements.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Extensive bandboard trim

suggestive of the Stick Style; spindled porches; carriage house.



Research Information

Original Building Owner:	William Hatch House	
Historic Name:	William Hatch House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Hatch House National Register Nomination.	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		_
-		-
		Photo 3 / Historic Photo
		- -
		-
		- -
		- -
		-

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 236

Former Street Number:

Street: Keystone Avenue

PIN Number(s):

Construction Date/Other Year: 1890s

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: dentil work underneath 2nd story

eave line and third story dormer

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: some windows may have been

replaced on east elevation



Yes

Significant:

National Register Criterion: B

Contributing to a

National Register District:
Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: House associated with prominent

Yes

musician and composer Charles Gabriel. The house was also designed in a highly distinctive Queen Anne form and

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing:

Porch: Wrap-Around

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Art Glass

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: the tower on the south east

elevation; the hipped roof dormer; wrap-around porch with columns



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check for significance.	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 230

Former Street Number: 127

Street: Keystone Avenue

PIN Number(s): 15-12-306-010-0000

Construction Date/Other Year: 1904

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A late Queen Anne cottage with

some Italianate and Greek Revival stylistic elements. It also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Undergoing rehabilitation at time of survey.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: Waller Gates

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1901

Architect:

Current Function/Category: Structure

Historic Function: Structure

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style:

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 2:

Current Wall Material 1:

Original Wall Material 1: Stone

Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type:
Roof Material:

Alterations:



Significant: Yes

National Register Criterion: B

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

Gates designed by Frank Lloyd Wright for the Waller estate.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 7977-7985

Former Street Number:

Street: Lake Street

PIN Number(s): 15-11-212-001-0000

Construction Date/Other Year: 1889

Architect:

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Two-Part Commercial

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Some storefronts have been

slightly altered.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: The oldest, extant commercial

building in River Forest. It also embodies a distinct Queen Anne

commercial style.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:

Significant Features: Conical tower over main storefront

entrance.



Research Information

Original Building Owner:	
Historic Name:	THE SHARE SHARE
Current Name:	
Construction Cost:	100 TO THE RESERVE T
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 3, 2012



General Information

Street Number: 7753-7771

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1912

Architect: William Drummond

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Ornamentation:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Building Form: Two-Part Commercial

Number of Stories:

Current Wall Material 1: Brick

Current Wall Material 2: Concrete/Concrete Block

Original Wall Material 1: Brick

Original Wall Material 2: Concrete/Concrete Block

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Some windows on upper floors

have been replaced.



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Perhaps the most important historic

commercial building in River Forest, designed in the Prairie style

by William Drummond.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Transom

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner:			*	
Historic Name:	River Forest Bank Biilding.			2
Current Name:			THE RES	IN
Construction Cost:		INC.	111 18 3	FEE
Architect 1 Information:				
Architect 2 Information:				
Contractor Information:				-
Developer Information:		Photo 2		
Research/Archival Information	on:			
Permit:				
Subdivision:				
Landscape/Streetscape:				
Notes				
		_		
		_		
		Photo 3 / Histo	ric Photo	
		_		
		_		
		<u> </u>		
		_		
		_		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 25, 2012



General Information

Street Number: 7623-7629

Former Street Number: 219

Street: Lake Street

PIN Number(s): 15-12-117-001-0000

Construction Date/Other Year: 1916, alterations 1927

Architect: Henry H. Mahler, 1916; William

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Teera cotta ornamentation and

carved panels

Building Form: Two-Part Commercial

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material: Aluminum Framing/Knee Walls

Roof Type:

Roof Material: Tile

Alterations:



Significant:

Yes

National Register Criterion: С

В

Contributing to a

National Register District: Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of the most distinctive

commercial buildings in River Forest with ornate terra cotta ornamentation, designed by two well-known River Forest architects.

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Arched Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features:



Research Information		
Original Building Owner:	Otto Luhman	- 38
Historic Name:		
Current Name:		
Construction Cost:	\$10000	
Architect 1 Information:	Henry H. Mahler	
Architect 2 Information:	William Drummond	CAD II I
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Economist, Vol 55, March 4, 1916	
Permit:	No	
Subdivision:		
Landscape/Streetscape:		
Notes		

Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: October 5, 2012



General Information

Street Number: 7970

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1912

Architect: William Drummond

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material:

Alterations:



Photo 1

Significant: Yes

В

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance:

A unique Gothic Revival church designed by William Drummond with Prairie elements that include its overall horizontal form, stained glass and shed dormers. It also

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers: Shed

Window Type: Fixed

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Label Mold

Window Storms: Yes

Significant Features: Prairie style shed dormers; stained

glass



Research Information

Original Building Owner: River Forest Methodist Church

River Forest Methodist Church **Historic Name:**

Current Name: River Forest Methodist Church

Construction Cost:

Architect 1 Information: William Drummond

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information: Fields: A Guidebook to the

Architecture of River Forest

Permit:

Subdivision:

Landscape/Streetscape:

Notes			



Photo 3 / Historic Photo

Survey Information

Nick Kalogeresis, The Lakota Group Preparer:

Survey Date: September 13, 2012



General Information

Street Number: 7776

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1859

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Landmarks Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Building displays a unique

combination of the Italianate and Greek Revival styles; it is the only institutional building in River Forest designed with Greek Revival

Roof Ornamentation: Cupolas

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Transom

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail: Hood Mold

Window Storms:

Significant Features: Reconstructed cupola on south

elevation. Greek Revival triangular

pediment on top gable end.



Research Information

Original Building Owner:		
Historic Name:	Harlem School	
Current Name:	District 90 Administration Building	The state of the s
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Cupola was reconstructed in		
as administrative offices.		
		Photo 3 / Historic Photo
Developer Information: Research/Archival Information: Permit: Subdivision: Landscape/Streetscape: Notes Cupola was reconstructed in Dornbusch remodeled the information:	Architecture of River Forest	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 15, 2012



General Information

Street Number: 7727

Former Street Number:

Street: Lake Street

PIN Number(s): 15-12-116-002-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation:

Building Form: One-Part Commercial

Number of Stories: 1 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Storefront Material:

Wall Detailing/Ornamentation:

Roof Type: Flat

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: The second River Forest Bank

Buildings designed in the Beaux Arts/Classical revival style - the only commercial building designed as such in River Forest. It also

Roof Ornamentation: Cornice

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features:



Research Information

Original Building Owner:		
Historic Name:	River Forest State Bank	
Current Name:	MB Financial	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 17, 2012



General Information

Street Number: 7600

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1936

Architect: McCarty and Smith

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: Α

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of the largest religious

buildings constructed in River Forest, in a high Gothic Revival style with a high level of integrity. St. Luke's also represents one of

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Fixed

Window Configuration: Art Glass

Window Material:

Window Detail:

Window Storms: Yes

Significant Features:



Research information		
Original Building Owner:	St. Luke's Parish Church	
Historic Name:	St. Luke's Parish Church	
Current Name:	St. Luke's Parish Church	
Construction Cost:	\$285,000	
Architect 1 Information:	McCarty and Smith	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Chicago Tribune, Jan. 10, 1937 article	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
. 10.00		

Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 7600

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1955

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: A

Contributing to a

National Register District:

Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A richly designed Gothic Revival

school that compliments the architecture of St. Luke Parish Church. The construction of the School represents the Parish's

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Aluminum

Window Detail:

Window Storms: Yes

Significant Features:



Research Information

Original Building Owner: St. Luke's Parish Church School. St. Luke's Parish Church School. **Historic Name: Current Name:** St. Luke's Parish Church School. **Construction Cost: Architect 1 Information: Architect 2 Information: Contractor Information: Developer Information:** Photo 2 Research/Archival Information: Permit: Subdivision: Landscape/Streetscape: **Notes** Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 7600

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1939

Architect: McCarty and Smith

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: A

Contributing to a

National Register District:
Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Designed by the same architects

as the Parish Church, this building exhibits a high level of design and integrity of the Gothic Revival style.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



Research Information		
Original Building Owner:	St. Luke's Parish Rectory	
Historic Name:	St. Luke's Parish Rectory	
Current Name:	St. Luke's Parish Rectory	
Construction Cost:		
Architect 1 Information:	McCarty and Smith	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Chicago Tribune, Jan. 10, 1937 article; Parish website	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		_ _
		Photo 3 / Historic Photo
		_ _
-		_
		_ _

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number:

Former Street Number:

Street: Lake Street

PIN Number(s):

Construction Date/Other Year: 1924

Architect: White & Weber

Current Function/Category: Structure

Historic Function: Structure

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

Ornamentation: Pilasters

Building Form:

Number of Stories: 1

Current Wall Material 1: Stone

Original Wall Material 1: Stone

Original Wall Material 2: Concrete/Concrete Block

Wall Detailing/Ornamentation:

Current Wall Material 2:

Storefront Material:

Roof Type:
Roof Material:

Alterations: Alterations to the rear of the

Memorial

Concrete/Concrete Block



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent Neo-Classical style

example, rare public structure example in River Forest, public park association and used as a gathering place for the Village.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features: Inscriptions



Research Information		
Original Building Owner:	Cook County Forest Preserve	
Historic Name:	Edmund Cummings Memorial	
Current Name:	Cummings Bandshell	
Construction Cost:	\$25,000	
Architect 1 Information:	White & Weber	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		Prioto 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Cummings Park		
		Photo 3 / Historic Photo
		Tiolo 37 material riole

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 20, 2012



General Information

Street Number: 729-735

Former Street Number:

Street: Lathrop Avenue

PIN Number(s):

Construction Date/Other Year: 1929, addition 1989

Architect: William Drummond

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Landmarks Survey

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Stonework, art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Slate

Alterations: Massive rear addition, visible from

sides and rear but main wing still

intact



Significant:

National Register Criterion: С

В

Contributing to a **National Register District:** Yes Potentially Contributing to a

National Register District: Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent Tudor Revival example in

Yes

River Forest, importance as the public library, designed by William

Drummond.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features: Window bays, chimney with

chimney pots



Research Information

rescuren information	
Original Building Owner:	
Historic Name:	River Forest Public Library
Current Name:	River Forest Public Library
Construction Cost:	\$60,000
Architect 1 Information:	William Drummond
Architect 2 Information:	Carow & Associates (addition)
Contractor Information:	
Developer Information:	
Research/Archival Information:	
Permit:	Yes
Subdivision:	
Landscape/Streetscape:	
Notes	

Photo 2		

l		
l		
l		

Photo 3 / Historic Photo

Survey Information

Doug Gilbert, Douglas Gilbert Architect Preparer:

Survey Date: September 19, 2012



General Information

Street Number: 1308

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-01-113-031-0000

Construction Date/Other Year: 1952

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: East elevation bay window may

have been replaced.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Historically important as the home

of James Dewar, the inventor of

the Twinkie.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 24, 2012



General Information

Street Number: 1301

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-01-212-026-0000

Construction Date/Other Year: 1960

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: International Style

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of the

International Style using varied materials and a distinct design for the windows, unusual style for a single family house in River Forest.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Sliding

Window Configuration:

Window Material: Aluminum

Window Detail: Ribbon

Window Storms: No

Significant Features: Vertical bands of stone, spandrels

of different colored brick



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 23, 2012



General Information

Street Number: 914

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-01-317-011-0000

Construction Date/Other Year: 1926

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Stone quoin work at main bay

corners; stone surrounds around

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive Italian

Renaissance house constructed by the Buurma Brothers and retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Pedimented

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes

Significant Features: Arched window hoods in main bay

with shields and leafwork; round arched pedimented main entrance.



Research Information			
Original Building Owner:			
Historic Name:			
Current Name:			
Construction Cost:			
Architect 1 Information:			
Architect 2 Information:			
Contractor Information:	Buurma Brothers		
Developer Information:		Photo 2	
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	1,1002	
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
		Photo 3 / Historic Photo	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 907

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-01-407-008-0000

Construction Date/Other Year: 1927

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, entry turret

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent and grand example of

Tudor Revival style with entry turret and attached garage in matching

style and detailing

Roof Ornamentation: Crenellated

Foundation Material/Form:

Door Detailing:

Porch: Terrace

Dormers: Gabled

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Crenelated entry, prominent

chimney with inset stone



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 839

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-01-413-016-0000

Construction Date/Other Year: 1931

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Stone window surrounds, awnings,

classical entry portico

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Vinyl siding on dormer



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and grand example of the

Italian Renaissance style with awnings and balustrades.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Terrace

Dormers: Arched

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Storms: Yes

Window Detail:

Significant Features: Porte cochere, entry portico

Paired



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	
	Photo 3 / Historic Photo
	Prioto 37 Historic Prioto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 6, 2012



General Information

Street Number: 812

Former Street Number: 391

Street: Lathrop Avenue

PIN Number(s): 15-01-323-011-0000

Construction Date/Other Year: 1930

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

2 ½

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Home of Paul "The Waiter" Ricca,

once considered the leader of the Chicago mafia during the 1930s, 40s and 50s. The house retains a high level of integrity and may have

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Terrace

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms:

Significant Features: Deep eaves; blind arch Pallidian

window in east elevation bay;

awning terrace



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 21, 2012



General Information

Street Number: 706

Former Street Number: 333

Street: Lathrop Avenue

PIN Number(s): 15-12-105-028-0000

Construction Date/Other Year: 1890

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Shingle

Ornamentation:

Building Form:

Number of Stories: 3

Current Wall Material 1: Wood Shingles

Current Wall Material 2: Brick

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

Rare example of a Shingle Style house in River Forest, it's polygonal second story window bays and hipped dormers are quite

distinctive.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Palladian

Window Storms: Yes

Significant Features: Dormers, gothic windows in second

story central bay, porch



Research Information

Original Building Owner:	John F. Barrett	
Historic Name:	John F. Barrett House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Barrett was a founding father founder of St. Luke Church	er of River Forest and a h, he was a financial trader	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 8, 2012



General Information

Street Number: 615

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-12-206-001-0000

Construction Date/Other Year: 1906, moved to site in 1920

Architect: Frank Lloyd Wright

Current Function/Category: Commercial Building

Historic Function: Commercial Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Good

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal board and battens

Building Form:

Number of Stories: 1

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Additions, some alterations on all

elevations



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance: Excellent, non-residential, Prairie

style example, designed by a team of Wright, White and Watson, association as a tennis club.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Louver

Window Configuration: 1 over 1

Window Material:

Window Detail: Clerestory

Window Storms:

Significant Features: Horizontal board and batten



Research Information

Original Building Owner:

Historic Name: River Forest Tennis Club

Current Name:

Construction Cost:

Architect 1 Information: Frank Lloyd Wright

Architect 2 Information: Charles White, Jr., Vernon Watson

Contractor Information:

Developer Information:

Research/Archival Information: Guidebook to the Architecture of

River Forest

Permit:

Subdivision:

Landscape/Streetscape:

Notes

The clubhouse was originally built near Quick and Harlem but was moved in 1920. Wright was the lead architect of the trio that worked on the original design. but much of his direct work has been lost in the move and later alterations. Watson did much of the design work during the move. Wright designed the RFTC logo still found on the chimney.





Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 530

Former Street Number: 251

Street: Lathrop Avenue

PIN Number(s): 15-12-111-038-0000

Construction Date/Other Year: 1899

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material: Asphalt Shingle

Alterations: Windows have been replaced on

east elevation; original porch

columns replaced.



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

An early Dutch Colonial in River Forest that has Queen Anne stylistic elements. This house retains a good level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: No

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Check significance status.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: October 5, 2012



General Information

Street Number: 515

Former Street Number:

Street: Lathrop Avenue

PIN Number(s): 15-12-111-044-0000, 15-12-212

-010-0000

Construction Date/Other Year: 1924

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation:

Building Form: Bungalow

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations: Porch infilled, replacement

windows



......

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District:

Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Small but excellent and rare

Spanish Revival style example that includes a multi-level terrace, matching garage and garden wall connecting the house and garage.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Terrace

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features: Multi-level terrace, awning, garden

wall



Photo 2
Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 20, 2012



General Information

Street Number: 7620

Former Street Number:

Street: Madison Street

PIN Number(s): 15-12-322-031-0000, 15-12-322

-032-0000, 15-12-322-033-0000, 15-12-322-034-0000, 15-12-322

Construction Date/Other Year: 1960

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: Stone screen, art glass

Building Form: Two-Part Commercial

Number of Stories: 1 1/2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Flat

Roof Material: Not visible/cannot be determined

Alterations: Replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** No

Noteworthy Buildings

Less Than 50 Years Old: Yes

Reason for Significance: **Excellent Mid-Century Modern**

style example with stone screen and extensive art glass, all with

excellent integrity.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: Stone entry with art glass



Research Information

Research information		
Original Building Owner:	Lutheran Child Welfare Association	LUTHERAN
Historic Name:		LUTHERAN CHILD & FAMILY SERVICES
Current Name:	Lutheran Child & Family Services	
Construction Cost:		3.6
Architect 1 Information:		
Architect 2 Information:	Additions by August J. Engler	
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information	:	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 24, 2012



General Information

Street Number: 1310

Former Street Number:

Street: Monroe Avenue

PIN Number(s): 15-01-213-021-0000

Construction Date/Other Year: 1935

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Art Deco/Moderne

Ornamentation: Distinct fluted entry tower

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Mansard

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Unusual example of Art Deco style

rarely seen in River Forest, and has a very distinct entry design.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features: Entry tower with vertical fluting and

chevron window



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 23, 2012



General Information

Street Number: 747

Former Street Number: 368

Street: Monroe Avenue

PIN Number(s): 15-12-202-003-0000

Construction Date/Other Year: 1918

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Eaves brackets

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2: Brick

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent example of a California

version of a Craftsman bungalow,

very rare in River Forest.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing:

Porch: Partial

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Porch, dormer



Research Information		
Original Building Owner:	Otto Kretzer	
Historic Name:	Otto Kretzer House	
Current Name:		
Construction Cost:	\$3000	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Otto Kretzer	
Developer Information:		Photo 2
Research/Archival Information:		F1002
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
Rare California style bunga	low in River Forest.	
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Former Street Number:

Street Number: 743

Street: Monroe Avenue

PIN Number(s): 15-12-202-004-0000

Construction Date/Other Year: 1916

Architect:

Current Function/Category: Single Family Residential Building

364

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Eaves brackets, half timbering

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2: Brick

Original Wall Material 1: Wood Shingles

Original Wall Material 2: **Brick**

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent and highly detailed

Craftsman bungalow with excellent

integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Full Front Porch:

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Porch and dormer



Research Information

Research information		
Original Building Owner:	Walter and Elizabeth Van Guilder	
Historic Name:	Walter Van Guilder House	
Current Name:		
Construction Cost:	\$3,000	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		•
		Photo 3 / Historic Photo
		•

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 633

Former Street Number:

Street: Monroe Avenue

PIN Number(s): 15-12-208-001-0000

Construction Date/Other Year: 1894

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Fish scale shingles, ornamental

trim, bay window

Building Form: Gable Front Cottage/House

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Portico columns changed, some

changes to rear porches



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Queen Anne style

> example for this part of River Forest with excellent integrity,

highly detailed.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features:



Research Information Original Building Owner:

Historic Name:

Current Name:

Construction Cost:

Architect 1 Information:

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit:

Subdivision:

Landscape/Streetscape:






Photo 2

Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 13, 2012



General Information

Street Number: 534

Former Street Number:

Street: Monroe Avenue

PIN Number(s): 15-12-213-015-0000

Construction Date/Other Year: 1928

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, stone details,

arched entry

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations: Rear addition



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Grand example of the Tudor

Revival style, highly detailed and designed. It also retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Terrace

Dormers: Gabled

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features:



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
<u> </u>	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 13, 2012



General Information

Street Number: 751

Former Street Number:

Street: Monroe Aveue

PIN Number(s): 15-12-202-002-0000

Construction Date/Other Year: 1918

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Eaves brackets, rubble stone

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Wood Shingles

Current Wall Material 2: Stone

Original Wall Material 1: Wood Shingles

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Stick Work

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Appropriate replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Distinctive and rare Craftsman

style bungalow known as an "Airplane" bungalow, with quality materials and detailing. It retains a

high level of integrity.

Roof Ornamentation: Trusses

Foundation Material/Form: Stone

Door Detailing:

Porch: Wrap-Around

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Vinyl

Window Detail:

Window Storms: Yes

Significant Features: Porch, framing, stonework



Research Information

rescaren imormatio	1.	
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$4,000	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Otto Kretzer	
Developer Information:		Photo 2
Research/Archival Information	on:	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		-
		Photo 3 / Historic Photo
		- -
		-
	_	. -
		<u>.</u>
		-

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 7565

Former Street Number:

Street: North Avenue

PIN Number(s):

Construction Date/Other Year: 1955

Architect: Frank J. Ellert

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:
Building Form:

Number of Stories:

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of a late Gothic

Revival church building in River Forest with excellent integrity and quality of the art glass windows.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:

Significant Features: Rose window on north elevation



Research Information		
Original Building Owner:	St. Vincent Ferrer Church Parish	
Historic Name:	St. Vincent Ferrer Church	
Current Name:	St. Vincent Ferrer Church	
Construction Cost:	\$500,000	
Architect 1 Information:	Frank J. Ellert	
Architect 2 Information:	Barry & Kay	
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 20, 2012



General Information

Street Number: 7200-14

Former Street Number:

Street: Oak Avenue

PIN Number(s): 15-12-205-024-1001

Construction Date/Other Year: 1939-44

Architect: Holsman & Holsman

Current Function/Category: Multi Family Residential Building

Historic Function: Multi Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: International Style

Ornamentation: Decorative metal panel at entries,

curved metal canopies, brick

Building Form: Courtyard Apartment

Number of Stories: 4+

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type:

Roof Material: Not visible/cannot be determined

Alterations: Replacement windows, some changes to brick, replacement

doors

Flat



Significant: Yes

National Register Criterion: Α

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Unusual and early apartment

complex for River Forest,

developed during World War II for critical housing, courtyard setting is very distinctive in River Forest.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail:

Window Storms:

Significant Features:



Research Information

Original Building Owner: River Forest Land Association

Historic Name: River Forest Garden Apartments

Current Name:

Construction Cost: \$475,000

Architect 1 Information: Holsman & Holsman

Architect 2 Information:

Contractor Information:

Developer Information:

Research/Archival Information:

Permit: Yes

Subdivision:

Landscape/Streetscape:

Notes

Eight buildings in complex, oriented inward with meandering walkway; despite alterations the complex is highly unusual for River Forest.



Photo 2

Photo	3	/ F	list	oric	Pho	oto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 8011
Former Street Number: 389

Street: Oak Avenue

PIN Number(s): 15-11-208-001-0000

Construction Date/Other Year: 1899

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Wood clapboard

Original Wall Material 1: Stucco

Original Wall Material 2: Wood clapboard

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive two-story Craftsman

house with Prairie-style elements. This house retains a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Brackets under roof eave line, use

of different materials between

floors.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: December 12, 2012



General Information

Street Number: 7560

Former Street Number:

Street: Oak Avenue

PIN Number(s):

Construction Date/Other Year: 1924, additions 1927, 1952, 1972

Architect: Perkins, Fellow & Hamilton

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Stonework

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations: Replacement windows, several

side and rear additions



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Association as a public school

important to the education of children in River Forest. An excellent example of a Gothic Revival public school building in

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Transom

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms:

Significant Features: Gothic entry arches



Research Information

Original Building Owner:		
Historic Name:	River Forest Junior High School	
Current Name:	Roosevelt Middle School	
Construction Cost:		THE THE HE
Architect 1 Information:	Perkins, Fellow & Hamilton	
Architect 2 Information: Perkins & Will		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Additions do not detract fro	m overall character	
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 7314

Former Street Number:

Street: Oak Avenue

PIN Number(s): 15-12-204-013-0000

Construction Date/Other Year: 1913

Architect: Harry H. Mahler

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal banding, art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent example of a grand

> Prairie Style House by someone not in Wright's inner circle, this was reportedly Mahler's only Prairie

style house.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features:



Research Information		
Original Building Owner:	F.H. and Daphne Bell	
Historic Name:	F.A. Bell House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Mahler	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to the Architecture of River Forest; River Forest National Register Historic	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Mahler reportedly worked for Holabird and Roche and lived in Oak Park and later on Thatcher Avenue in River Forest. The house was commissioned by Oak Parker George Edwards for his daughter and son-in-law.		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 5, 2012



General Information

Street Number: 1338

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-103-050-0000

Construction Date/Other Year: 1926

Architect: Purcell and Elmslie

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

В

Contributing to a National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of three Purcell and Elmslie

homes in River Forest - a distinctive side gabled Tudor Revival home with a horizontal emphasis. This homes also retains

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Two story bay on south elevation;

art glass treatments.



Research Information

Original Building Owner:	Charles Purcell	
Historic Name:	Charles Purcell House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Purcell and Elmslie	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
This house went through a	interior renovation in 2012.	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July 19, 2012



General Information

Street Number: 1129

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-303-003-0000

Construction Date/Other Year: 1939

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive, well-designed Tudor

> Revival styled house with a high degree of architectural integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Dominant front gable on east

elevation.



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Lanuscape/Streetscape.	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: Augustb15, 2012



General Information

Street Number: 1125

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-303-004-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Tile

Alterations: First floor east elevation arched

windows may have been replaced.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the few distinctive Spanish

Revival homes in River Forest with

a high level of integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Not visible/cannot be determined

Surrounds **Door Detailing:**

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms:

Significant Features:



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	Walter and Emma Leininger	
Historic Name:	Walter Leininger House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	Leininger Construction Co.	
and Commonwealth Constr	ruction, both paving firms.	
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 2012



General Information

Street Number: 1114

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-302-019-0000

Construction Date/Other Year: 1920

Architect: Tallmadge and Watson, attributed.

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: New storm windows may have

been installed.



Significant: Yes

В

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:
Reason for Significance:

A distinctive Prairie house designed by Tallmadge and Watson and retain a high level of

integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	Joseph S. Guy	
Historic Name:	Joseph S. Guy House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson, attributed	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2012



General Information

Street Number: 1108

Former Street Number: 529b

Street: Park Avenue

PIN Number(s): 15-01-302-020-0000

Construction Date/Other Year: 1920

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Bungalow

Number of Stories: 2 1/2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: **Brick**

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Some windows on east elevation;

second story dormer may have been replaced; a rear addition may



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Although this building does not

retain the highest level of integrity, it is a distinctive example of the Prairie style in a bungalow form designed by Tallmadge and

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Gabled

Window Type: Casement

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms: No



Research Information		
Original Building Owner:	G.A. Hills	
Historic Name:	G.A. Hills House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Tallmadge and Watson	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to the Architecture of River Forest	
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo
	_	Prioto 37 Historic Prioto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2012



General Information

Street Number: 1105

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-303-005-0000

Construction Date/Other Year: 1933

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

A distinctive Tudor Revival house

with unique massing

arrangements. This house was constructed by the Buurma Brothers and retains a high level of

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Oriel

Window Storms: No

Significant Features: Dominant front entrance gable,

distinctive timbering and oriel window on second story. Its overall massing is quite unique.



Research Information

Original Building Owner:		7 12	
Historic Name:			
Current Name:		AND AND	
Construction Cost:			
Architect 1 Information:			ir i bha
Architect 2 Information:			The same of the same of
Contractor Information:	Buurma Brothers		
Developer Information:		Photo 2	
Research/Archival Informatio	n:		
Permit:			
Subdivision:			
Landscape/Streetscape:	Front entrance path bluestone navers		
Notes			
		Photo 3 / Historic Photo	
		•	
		•	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 2022



General Information

Street Number: 1102

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-302-021-0000

Construction Date/Other Year: 1924

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: River Forest Significant Properties

List

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Building Form:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



.

Significant: Yes

National Register Criterion: C

В

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A highly distinctive house - one half

designed with Tudor Revival detailing, the other in Italian Renaissance. It also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features: This house displays a unique

Tudor/Italian Renaissance eclecticism. blind arch windows on the south elevation; Gothic arch

quorman, rinjurie quimer



Research Information

Original Building Owner:	Charles William Kallel		
Historic Name:	Charles William Kallel House		
Current Name:			
Construction Cost:			
Architect 1 Information:			
Architect 2 Information:		A siste	SINGADA BASE
Contractor Information:			
Developer Information:		Photo 2	4 60 60
Research/Archival Information:	River Forest National Register Historic District Nomination		
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
		_	
		_	
		Photo 3 / Historic Photo	
		<u> </u>	
		<u> </u>	
		<u> </u>	
		_	
		<u> </u>	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2012



General Information

Street Number: 1045

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-309-001-0000

Construction Date/Other Year: 1929

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Spanish Revival

Ornamentation:

Building Form:

Current Wall Material 1:

Number of Stories: 2 ½

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations: Windows have been replaced on

all elevations.

Brick



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive example of the

Spanish Revival in River Forest and retains a significant level of

integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Fixed

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail:

Window Storms: No

Significant Features: Roof tower



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	Carlotte Carlotte
Construction Cost:	944
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 21012



General Information

Street Number: 1044

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-308-045-0000

Construction Date/Other Year: 1918

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: West and west elevations may

have been altered at some point, slightly changing the facades'



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive French country house

constructed by the Buurma

Brothers; it also retains a high level

of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No



Research Information

Original Building Owner:			
Historic Name:			
Current Name:			4
Construction Cost:			
Architect 1 Information:		TO ALL THE STATE OF THE STATE O	TIME TO BE
Architect 2 Information:			
Contractor Information:	Buurma Brorhers		
Developer Information:		Photo 2	
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture		
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
Check this one for significa	nce.	_	
		_	
		Photo 3 / Historic Photo	
		<u>—</u> —	
		_	
		_	
		-	
		<u> </u>	
		<u></u>	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2013



General Information

Street Number: 1035

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-309-002-0000

Construction Date/Other Year: 1943

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Photo 1

Significant: Yes

National Register Criterion: B C

Contributing to a

National Register District: Yes
Potentially Contributing to a

National Register District: Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive late, high0style

Colonial Revival house, once associated with Paul Harvey, the well-known radio broadcaster.

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Pedimented

Porch: Terrace

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Gable pediment over front entrance

bay



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
·	
	Photo 3 / Historic Photo
	Prioto 37 Historic Prioto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 2012



General Information

Street Number: 1027

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-309-003-0000

Construction Date/Other Year: 1935

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A highly distinctive Tudor Revival

with a geometric dominant front gable and well maintained round windows. This house also retains

a high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Surrounds

Porch: Entrance

Dormers: Shed

Window Type: Fixed

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Oriel

Window Storms: No

Significant Features: Dominant front gable



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 15, 2012



General Information

Street Number: 1023

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-01-309-004-0000

Construction Date/Other Year: 1934

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: Brick

Original Wall Material 2: Stone

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Cross gabled

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: С

Contributing to a

National Register District: Potentially Contributing to a

National Register District:

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: A distinctive Tudor Revival house

constructed by the Buurma Brothers and retains a high level of detailing. The house's overall massing, design, and detailing is

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material:

Window Detail: Ribbon

Window Storms: No

Significant Features: Wood storm door



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Buurma Brothers	
Developer Information:		Photo 2
Research/Archival Information:	Historic context work and Fields: A Guidebook to the Architecture of River Forest.	
Permit:		
Subdivision:		
Landscape/Streetscape:	Bluestone paving in entrance path.	
Notes		
Garage could not be viewe	d from the sidewalk.	
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 25, 2012



General Information

Street Number: 946

Former Street Number: 473

Street: Park Avenue

15-01-314-023-0000 PIN Number(s):

Construction Date/Other Year: 1907

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Foursquare

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Some windows on north elevation

have been replaced.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinguished example of

Foursquare Queen Anne home in River Forest with high integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Full Front Porch:

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 14, 2012



General Information

Street Number: 926

Former Street Number: 453

Street: Park Avenue

PIN Number(s): 15-01-314-029-0000

Construction Date/Other Year: 1905

Architect: Robert Spencer

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant:

В

Yes

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Robert Spencer's, one of the more

significant architects in Oak Park-River Forest, designed this distinctive Prairie style house in 1905. This house retains a high

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material:

Window Detail: Ribbon

Window Storms: No



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	Robert C. Spencer	
Historic Name:	Robert Spencer House	
Current Name:		
Construction Cost:		
Architect 1 Information:	Robert C. Spencer	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Fields: A Guidebook to River Forest Architecture	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 24, 2012



General Information

Street Number: 743

Former Street Number: 366

Street: Park Avenue

PIN Number(s): 15-12-103-004-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A dis

A distinctive Prairie house that must be attributable to one of the Prairie School architects practicing in River Forest. This house has a distinctive design and has a high

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms:



Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 20, 2012



General Information

Street Number: 601

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-12-109-010-0000

Construction Date/Other Year: 1921

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Front porch may have been

replaced or altered



Significant: Yes

National Register Criterion: C

В

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Tallmadge and

Watson designed Prairie house with pointed arched windows and

open styled porch more

characteristic of the Prairie style.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch: Full Front

Dormers: Hipped

Window Type: Casement

Window Configuration: Diamond Pane

Window Material: Wood

Window Detail: Paired

Window Storms:

Significant Features: Hipped roof line dormers, second

floor pointed windows

characteristic of the Prairie style.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information: Tallmadge and Watson	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Further investigation is needed to determine if the front	
porch piers have been reconstructed or replaced.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 20, 2012



General Information

Street Number: 563

Former Street Number: 282

Street: Park Avenue

PIN Number(s): 15-12-109-011-0000

Construction Date/Other Year: 1901

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A unique Queen Anne Foursquare

that has an early Craftsman styled dormer. This house also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Surrounds

Porch: Full Front

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Recheck significance rating	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 20, 2012



General Information

Street Number: 221

Former Street Number:

Street: Park Avenue

PIN Number(s): 15-12-308-008-0000

Construction Date/Other Year: 1914

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Eaves brackets, jigsaw balustrade,

stone piers Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Building Form:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Dormer windows replaced



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent Craftsman style example

in southern River Forest and with stone piers and crafted elements.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing:

Porch: Full Front

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail: Paired

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$3000	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	E.E. Nowak	
Developer Information:		Photo 2
Research/Archival Information:		FIIOLO 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
_		Filoto 37 Historic Filoto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: October 2, 2012



General Information

Street Number: 217 **Former Street Number:** 116

Street: Park Avenue

PIN Number(s): 15-12-308-009-0000

Construction Date/Other Year: 1913

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, stone detailing

Building Form:

Number of Stories: 1 1/2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Roof was likely wood shingles, rear

addition has minimal visual impact



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:**

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Very unusual example of a

"storybook" cottage with curved roof eaves, decorative stone and

quaint detailing.

Roof Ornamentation:

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Sidelights

Porch: Terrace

Gabled Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Roofing wraps the eaves



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:	\$1500	
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	A.J. Stahmer	
Developer Information:		
Research/Archival Information:		Photo 2
Permit:	Yes	
Subdivision:		
Landscape/Streetscape:		
N. 4		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: October 2, 2012



General Information

Street Number: 7511-7551

Former Street Number:

Street: Quick Avenue

PIN Number(s):

Construction Date/Other Year: 1925

Architect: Holmes and Flinn

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation: Eaves corbels, stone finials,

pointed arches

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: An excellent Gothic Revival church

> style example constructed in brick. The building also retains excellent

integrity.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Concrete/Concrete Block

Door Detailing: Surrounds

Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material:

Window Detail:

Window Storms:

Significant Features: Bell tower



Research Information

Original Building Owner:		
Historic Name:		
Current Name:	First Presbyterian Church	
Construction Cost:	\$250,000	ALL WAR
Architect 1 Information:	Holmes and Flinn	
Architect 2 Information:		
Contractor Information:	Guy and McClintock	
Developer Information:		Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Morris Holmes and Raymo	nd Flinn were Chicago heir partnership with architect	
Normand Patton from 1912		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 19, 2012



General Information

Street Number: 7234

Former Street Number: 38

Street: Quick Avenue

PIN Number(s): 15-12-211-013-0000

Construction Date/Other Year: 1912

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal board and battens

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant:

В

Yes

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent example of Prairie Style

with distinctive horizontal board and batten siding mixed with

stucco.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Full Front

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Paired

Window Storms: No



Research Information		
Original Building Owner:	Charles Barr	
Historic Name:	Charles Barr House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	A STATE OF THE STA
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Guidebook to the Architecture of River Forest	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Charles Barr was a librarian and one of the founders of	n with the John Crerar Library the River Forest Library.	
		Photo 3 / Historic Photo

Survey Information

Doug Gilbert, Douglas Gilbert Architect Preparer:

Survey Date: August 17, 2012



General Information

Street Number: 7218
Former Street Number: 28

Street: Quick Avenue

PIN Number(s): 15-12-211-016-0000

Construction Date/Other Year: 1907

Architect: Tallmadge and Watson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Horizontal bands

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent Prairie style design by

Tallmadge and Watson, horizontal board and batten siding is

excellent.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Porch



Research Information Original Building Owner: Lewis H. Lozier Lozier House **Historic Name: Current Name: Construction Cost: Architect 1 Information:** Tallmadge and Watson **Architect 2 Information: Contractor Information: Developer Information:** Research/Archival Information: Guidebook to the Architecture of River Forest Permit: Subdivision: Landscape/Streetscape: **Notes** Lozier was a commercial artist and charter member of the RF Tennis Club. John Noerdinger lived in the house after Lozier and was a muralist. Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 7214

Former Street Number:

Street: Quick Avenue

PIN Number(s): 15-12-211-017-0000

Construction Date/Other Year: 1905, alterations 1911

Architect: Charles White

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Prairie style example by

Charles White with some design work by Wright, published as an example of modern architecture.

Roof Ornamentation:

Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: No



Research Information Original Building Owner: Walter Gerts Walter Gerts House **Historic Name: Current Name: Construction Cost: Architect 1 Information:** Charles E. White Frank Lloyd Wright **Architect 2 Information: Contractor Information: Developer Information:** Research/Archival Information: Permit: Subdivision: Landscape/Streetscape: **Notes** House was published by Herman Von Holst in "Modern American Homes" in 1928. After a fire in 1911, Wright was hired to undertake some interior changes. Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 17, 2012



General Information

Street Number: 1409

Former Street Number:

Street: Thatcher Avenue

PIN Number(s): 15-01-101-031-0000

Construction Date/Other Year: 1952

Architect: Keck and Keck

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation:
Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Flat

Not visible/cannot be determined

Alterations:

Roof Material:

Roof Type:

Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: This house was difficult to evaluate

due to heavy vegetation and screening by trees; this house need to be documented when leaves are off trees; Keck and Keck

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Metal

Window Detail:

Window Storms: No

Significant Features: Balcony over garage



Research Information		
Original Building Owner:	Russell Stamm	
Historic Name:	Russell Stamm House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information	:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	ements of the International	
Style.		
	1 Keck and Keck designed	Photo 3 / Historic Photo
	ting building. Reference: A	Filoto 37 ristoric Filoto
	cture of River Forest, Fields,	
<u>1990.</u>		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: July16, 2012



Street:

River Forest Village Wide Architectural and Historical Survey

General Information

Street Number: 835

Former Street Number: 416

PIN Number(s): 15-02-405-003-0000

Construction Date/Other Year: 1924

Architect: Schmidt, Garden and Martin

Current Function/Category: Single Family Residential Building

Thatcher Avenue

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Cornice line dentils, keystone

window arches

Building Form:

Number of Stories: 3

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant: Yes

National Register Criterion: C

В

Contributing to a
National Register District: Yes

Potentially Contributing to a National Register District:
Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance: A highly distinctive, grand example

of the Colonial Revival style in River Forest, designed by one of the prominent Chicago architecture firms during the first quarter of the

Roof Ornamentation: Cornice

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch: Entrance

Dormers: Pedimented

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Round front entrance portico;

pedimented gables.



Research Information

Original Building Owner:

0	
Historic Name:	Dr. Charles Davison House
Current Name:	
Construction Cost:	


Dr. Charles Davison

Schmidt, Garden and Martin

Architect 2 Information:

Architect 1 Information:

Contractor Information: Developer Information:



Notes			



Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 3, 2012



General Information

Street Number: 819

Former Street Number:

Street: Thatcher Avenue

PIN Number(s): 15-02-405-008-0000; 15-02-405

-007-0000; 15-02-405-006-0000

Construction Date/Other Year: 1918

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:
Building Form:

Number of Stories: 3

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: This house and attached coach

house is one of the largest estates in River Forest, constructed for prominent businessman W.S. Gerts. This house exhibits an

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Entrance

Dormers: Shed

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Shed dormers on second and third

stories; facade stone work; arched porch front entrance; windowed

pergola.



Research Information

Original Building Owner:		
Historic Name:	Marygate; W.S. Gerts House	ATT ATTACK TO
Current Name:		一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	HAARGIS Ref: 159421; National Register District Nomination	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
W.C. Gerts later commission construct a house in Whitele	oned Frank Lloyd Wright to nall, Michigan.	
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: August 3, 2012



General Information

Street Number: 738

Former Street Number:

Street: Thatcher Avenue

PIN Number(s):

Construction Date/Other Year: 1874

Architect:

Current Function/Category: Institutional Building

Historic Function: Institutional Building

Listing in Existing Survey: Illinois Historic Structures Survey

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form:

Number of Stories: 2 1/2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Addition added to west elevation.



Significant: Yes

National Register Criterion: С

В

Contributing to a **National Register District:** Yes

Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the two of the grand

> Italianate "villas" built in River Forest associated with its original owner, Abraham Hoffman, one of River Forest's most prominent early

Roof Ornamentation: Towers/Turrets

Foundation Material/Form:

Door Detailing: Transom

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Hood Mold

Window Storms: No

Significant Features: Central bay tower



Research Information		
Original Building Owner:	Abraham Hoffman	
Historic Name:	Abraham Hoffman House	
Current Name:	Trailside Museum	
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:	Antoine Bedard	
Developer Information:		Photo 2
Research/Archival Information:		
.		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Former Street Number:

Street Number: 633

Street: Thatcher Avenue

PIN Number(s): 15-11-209-001-0000

Construction Date/Other Year: 1894

Architect:

Current Function/Category: Single Family Residential Building

320

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Building Form: Foursquare

Number of Stories: 2 ½

Current Wall Material 1: Vinyl Siding

Current Wall Material 2:

Ornamentation:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: This may have been a Queen Anne

house originally and later remodeled with Prairie elements



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: An late Queen Anne Foursquare

> with distinctive angled windows on the second floor. It also retains a

high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Re check style.	
	District O (Ullistrate District
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 630

Former Street Number: 321

Street: Thatcher Avenue

PIN Number(s): 15-11-208-019-0000

Construction Date/Other Year: 1919

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italian Renaissance

Ornamentation: Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stone

Original Wall Material 1: **Brick**

Original Wall Material 2: Stone

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A early distinctive Italian

Renaissance home with Prairie stylistic elements. It also retains a

high level of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Sidelights

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Prairie styled dormer and deep

eaves give suggestions of the

Prairie style.



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
<u> </u>	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: Septembet 13, 2012



General Information

Street Number: 623

Former Street Number: 310

Street: Thatcher Avenue

PIN Number(s): 15-11-209-004-0000

Construction Date/Other Year: 1868

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation: Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

2 ½

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation: Stick Work

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance:

An early Queen Anne in River Forest that has retained a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Stone

Door Detailing: Sidelights

Full Front Porch:

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No



Photo 2
Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 615

Former Street Number: 304

Street: Thatcher Avenue

PIN Number(s): 15-11-209-005-0000

Construction Date/Other Year: 1870

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Gothic Revival

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Addition to rear south elevation.



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of

One of few remaining Carpenter Gothic homes in River Forest and retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Transom

Porch: Wrap-Around

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 12, 2012



General Information

Street Number: 606

Former Street Number: 285

Street: Thatcher Avenue

PIN Number(s): 15-11-208-049-0000

Construction Date/Other Year: 1920

Architect: Charles White

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2: Brick

Original Wall Material 1: Stucco

Original Wall Material 2: Brick

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Gambrel

Roof Material:

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Craftsman home

designed by Charles White and also retains a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers: Arched

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: No

Significant Features: Exposé rafters in east wing

extension.

Deep Eaves



Research Information Original Building Owner: O. Dolling House **Historic Name: Current Name: Construction Cost:** Architect 1 Information: Charles White **Architect 2 Information: Contractor Information: Developer Information:** Photo 2 Research/Archival Information: Permit: Subdivision: Landscape/Streetscape: **Notes** Check style. Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Former Street Number:

Street Number: 554

Street: Thatcher Avenue

PIN Number(s): 15-11-208-044-0000, 15-11-208

277

-046-0000

Construction Date/Other Year: 1911

Architect: William Drummond

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Carriage House

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:
Building Form:

Number of Stories: 3

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A rare Queen Anne home in River

Forest designed by William Drummond. It retains a high level

of integrity.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Prairie styled porch and deep

eaves.



Research Information		
Original Building Owner:		
Historic Name:	T.B. Klock House	
Current Name:		
Construction Cost:		
Architect 1 Information:	William Drummond	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Steiner Index	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 553 **Former Street Number:** 272

Street: Thatcher Avenue

15-11-209-026-0000, 15-11-209 PIN Number(s):

-027-0000

Construction Date/Other Year: 1883 (altered 1920s)

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Classical Revival/Beaux Arts

2 ½

Ornamentation:

Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2:

Original Wall Material 1: Wood clapboard

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Wood Shingle

Alterations: Earlier Queen Anne remodeled in

the Classical Revival style.



Significant: Yes

National Register Criterion: С

В

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Association with David A. Thatcher,

> part of the founding River Forest Thatcher family. Excellent and rare residential example of the Neo Classical style with its dramatic

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Transom

Full Front Porch:

Dormers: Hipped

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material:

Window Detail:

Window Storms: Yes

Significant Features: Doric columned porch



Research Information			
Original Building Owner:	David A. Thatcher		
Historic Name:	David A. Thatcher House		
Current Name:			
Construction Cost:			
Architect 1 Information:			
Architect 2 Information:			
Contractor Information:			
Developer Information:		Photo 2	
Research/Archival Information:	Fields: A Guide to River Forest Architecture		
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
Check materials.			
	son of River Forest founder		
	s a paving contractor. The	Photo 3 / Historic Photo	
house was originally Queen Anne Style but second			
	Pled the exterior in the 1920s		
with a Neo-Classical style. with the Elgin Watch Comp			
with the Light Water Comp	SALLY.		

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 542

Former Street Number:

Street: Thatcher Avenue

PIN Number(s): 15-11-208-033-0000

Construction Date/Other Year: 1897

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Italianate

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Second floor east elevation

windows were replaced. Stucco may have been added at a later



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few, distinctive

Italianate homes in River Forest that has retained a high level of

integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing: Transom

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Hood Mold

Window Storms: Yes



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
·	

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Former Street Number:

Street Number: 539

Street: Thatcher Avenue

PIN Number(s): 15-11-209-015-0000

Construction Date/Other Year: 1905

Architect: E.E. Roberts

Current Function/Category: Single Family Residential Building

264

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Windows on west elevation may

have been replaced



Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: A distinctive Prairie house design

Yes

by E.E. Roberts and retains a good

level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type: Casement

Window Configuration:

Window Material: Aluminum

Window Detail:

Window Storms:



Research Information		
Original Building Owner:	Robert Walbank	
Historic Name:	Robert Walbank House	
Current Name:		
Construction Cost:		
Architect 1 Information:	E. E. Roberts	
Architect 2 Information:		
Contractor Information:	Vierow Brothers	
Developer Information:		Photo 2
Research/Archival Information:	River Forest National Register Historic District Nomination	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		• •
		· ·

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Former Street Number:

Street Number: 535

Street: Thatcher Avenue

PIN Number(s):

Construction Date/Other Year: 1889

Architect:

Current Function/Category: Single Family Residential Building

260

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Building Form:

Ornamentation:

Number of Stories: 2 ½

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Wood Shingles

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Wood Shingles

Wall Detailing/Ornamentation: Shingles/Shingle Pattern

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Third story gable window may

have Ben replaced.



.

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: First home of Robert Walbank, an

early prominent citizen of River Forest; house is an excellent example of the Queen Anne style.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Transom

Porch: Wrap-Around

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information		
Original Building Owner:	Robert Walbank	
Historic Name:	Robert Walbank House	
Current Name:		
Construction Cost:		
Architect 1 Information:		
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Forest Leaves, July 2, 1980	
Dameit		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
_	_	
		Photo 3 / Historic Photo
_		Filoto 37 Historic Filoto

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 13, 2012



General Information

Street Number: 500

Former Street Number:

Street: Thatcher Avenue

PIN Number(s): 15-11-208-040-0000, 15-11-209

-023-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation:
Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:




Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: This house is a distinctive two-story

Craftsman home that retains a high

level of integrity.

Roof Ornamentation:

Foundation Material/Form: Not visible/cannot be determined

Door Detailing:

Porch:

Dormers: Hipped

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms:



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	SET UNION SET OF SET OF SET
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Vegetation and fencing makes it difficult to document portions of the house visible from the street	
	Photo 3 / Historic Photo

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 15, 2012



General Information

Street Number: 147

Former Street Number:

Street: Thatcher Avenue

PIN Number(s): 15-11-403-001-0000

Construction Date/Other Year: 1893

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Queen Anne

Ornamentation:

Building Form:

Number of Stories: 2 ½

Current Wall Material 1: Stone

Current Wall Material 2:

Original Wall Material 1: Stone

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Asphalt Shingle

Alterations: Porch dating from the 1920s has

been removed.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: A distinctive example of one of only

a handful of masonry Queen Anne

homes in River Forest.

Roof Ornamentation: Towers/Turrets

Foundation Material/Form: Stone

Door Detailing: Transom

Porch: Terrace

Dormers: Gabled

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail:

Window Storms: Yes

Significant Features: Romanesque styled windows.



Research Information

Original Building Owner:			×
Historic Name:	Cora Cummings House		M. A.
Current Name:			1
Construction Cost:			
Architect 1 Information:			4
Architect 2 Information:			1000
Contractor Information:		and transfer the state of the	1
Developer Information:		Photo 2	
Research/Archival Information	1:		
Permit:			
Subdivision:			
Landscape/Streetscape:			
Notes			
		Photo 3 / Historic Photo	
-			

Survey Information

Preparer: Nick Kalogeresis, The Lakota Group

Survey Date: September 17, 2012



Alterations:

River Forest Village Wide Architectural and Historical Survey

General Information			
Street Number:			
Former Street Number:			
Street:	Washington Street - Park Avenue		
PIN Number(s):			
Construction Date/Other Year:	1917		
Architect:	Jens Jensen		
Current Function/Category:	Site		
Historic Function:	Site	Photo 1	
Listing in Existing Survey:		Significant:	Yes
Evaluation		National Register Criterion	
Condition:	Excellent	Contributing to a	. (
Integrity:	Excellent	National Register District:	
Secondary Structure:		Potentially Contributing to National Register District:	a Yes
Secondary Structure Condition:		Noteworthy Buildings Less Than 50 Years Old:	
Secondary Structure Integrity:		Reason for Significance:	A small park designed by Jens
Landmark/National Register:	No	-	Jensen and with very good integrity.
-			3 7
Architectural Description			
Architectural Classification/Style):	Roof Ornamentation:	
Ornamentation:		Foundation Material/Form:	
Building Form:		Door Detailing:	
Number of Stories:		Porch:	
Current Wall Material 1:		Dormers:	
Current Wall Material 2:		Window Type:	
Original Wall Material 1:		Window Configuration:	
Original Wall Material 2:		Window Material:	
Wall Detailing/Ornamentation:		Window Detail:	
Storefront Material:		Window Storms:	
Roof Type:		Significant Features:	Open meadow with trees and some
Roof Material:			small plantings

Some plantings and trees have died or been removed



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:	River Forest Park District	
Historic Name:	Washington Triangle Park	
Current Name:	Washington Triangle Park	
Construction Cost:		
Architect 1 Information:	Jens Jensen	
Architect 2 Information:		
Contractor Information:		
Developer Information:		Photo 2
Research/Archival Information:	Research by Carol Yetken	
Permit:		
Subdivision:		
Landscape/Streetscape:	Trees and plantings	
Notes		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: October 5, 2012



General Information

Street Number: 1506

Former Street Number:

Street: William Street

PIN Number(s): 15-01-202-023-0000

Construction Date/Other Year: 1955

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Attached Garage

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register:

Architectural Descriptions

Architectural Classification/Style: Mid-Century Modern

Ornamentation: Decorative clapboards in gables

Building Form: Ranch

Number of Stories:

Current Wall Material 1: Stone

Current Wall Material 2: Brick

Original Wall Material 1: Stone

Original Wall Material 2: Brick

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent example of a modern

Ranch with distinct roof lines and

entry.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Full Height

Dormers:

Window Type: Louver

Window Configuration:

Window Material: Metal

Window Detail:

Window Storms:

Significant Features: Entry porch, garage door



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
<u> </u>	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: July 20, 2012



General Information

Street Number: 904

Former Street Number:

Street: William Street

PIN Number(s): 15-01-409-024-0000

Construction Date/Other Year: 1922

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Good

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Colonial Revival

Ornamentation: Shutters, portico, Palladian blind

arches, brick quoins

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: **Brick**

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Potentially Contributing to a **National Register District:** Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and grand example of

Colonial Revival style with side wings and highly detailed.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Terrace

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Palladian

Window Storms:

Significant Features: Brick veranda, enclosed sun

porches



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 8, 2012



General Information

Street Number: 827

Former Street Number:

Street: William Street

PIN Number(s): 15-01-416-005-0000

Construction Date/Other Year: 1936

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure:

Secondary Structure Condition:

Secondary Structure Integrity:

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: French Eclectic

Ornamentation: Art Deco vertical tone detailing

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Slate

Alterations:



Significant:

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a

National Register District: Yes

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: Excellent and rare blend of French

Yes

Eclectic and Art Deco styles, a French form with distinctive Deco

details.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing: Surrounds

Porch: Terrace

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features: Stepped stone window surround,

metal railings



Research Information	
Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Assessor listed this as built in 1915, this is not correct.	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 8, 2012



General Information

Street Number: 755
Former Street Number: 376

Street: William Street

PIN Number(s): 15-12-203-001-0000

Construction Date/Other Year: 1917

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: River Forest Significant Properties

List

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		Prioto 37 historic Prioto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 754

Former Street Number:

Street: William Street

PIN Number(s): 15-12-202-014-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Compatible but visible rear addition



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Sidelights **Door Detailing:**

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Listed in IL survey and has	a significant addition.	
	-	
		Dhate 2 (Wistoria Dhate
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Former Street Number:

Street Number: 751

Street: William Street

PIN Number(s): 15-12-203-002-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

372

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Side Gabled

Roof Material: Asphalt Shingle

Alterations: Replacement windows, porch infill



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Paired

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 750

Former Street Number:

Street: William Street

PIN Number(s): 15-12-202-015-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:


Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Door replaced, replacement

windows, stoop altered



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Horizontal board and batten siding



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		Prioto 37 historic Prioto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 747

Former Street Number: 368

Street: William Street

PIN Number(s): 15-12-203-003-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Porch infill or replacement windows



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Part of

Part of the Hogan development and a Robinson Prairie Style

design.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 746

Former Street Number: 367

Street: William Street

PIN Number(s): 15-12-202-016-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Good

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch infilled, entry porch altered,

entry altered



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

Part of Hogan development and a Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stucco

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		F1000 2
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Listed in IL survey but has	been altered over the years.	
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Former Street Number:

Street Number: 743

Street: William Street

PIN Number(s): 15-12-203-004-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

364

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Visible rear deck, porch infill or

replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Full Front Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



Street:

River Forest Village Wide Architectural and Historical Survey

General Information

Street Number: 742

Former Street Number: 363

PIN Number(s): 15-12-202-017-0000

Construction Date/Other Year: 1915

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

William Street

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Prairie style design by

> Robinson for Hogan & Sons with rare combo of wood board and batten and stucco and few

alterations.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Paired

Window Storms: Yes

Significant Features: Horizontal board and batten siding,

built in planter



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 739

Former Street Number: 360

Street: William Street

PIN Number(s): 15-12-203-005-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Rear addition, replacement

windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 738

Former Street Number:

Street: William Street

PIN Number(s): 15-12-202-018-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Excellent Prairie style example of

Robinson's design for Hogan & Sons with unusual combo of brick and stucco and few alterations.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 735

Former Street Number: 356

Street: William Street

PIN Number(s): 15-12-203-006-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Large visible rear addition,

replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Partial Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Paired

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 734 **Former Street Number:** 353

Street: William Street

PIN Number(s): 15-12-202-019-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch screened in, front stair

altered



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson designed group of Prairie

style houses.

Roof Ornamentation:

Foundation Material/Form: Stucco

Door Detailing: Sidelights

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
Listed in IL survey but alter	ations detract from its overall	
integrity.		
		Photo 3 / Historic Photo
-		

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 12, 2012



General Information

Street Number: 731

Former Street Number: 352

Street: William Street

PIN Number(s): 15-12-203-007-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Poor

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Building Form:

Number of Stories:

Current Wall Material 1: Wood Shingles

Current Wall Material 2:

Original Wall Material 1:

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Major alterations and additions to

front and rear, new siding.



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: No Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch:

Dormers:

Window Type:

Window Configuration:

Window Material:

Window Detail:

Window Storms:



Research Information

Original Building Owner:		- A
Historic Name:		
Current Name:		
Construction Cost:		11
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information	:	
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		-
		-
		Photo 3 / Historic Photo
		-
		-
		- -
		-
		-
		-

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: September 6, 2012



General Information

Street Number: 730

Former Street Number: 351

Street: William Street

PIN Number(s): 15-12-202-020-0000

Construction Date/Other Year: 1915

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Front door and transoms replaced



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: One of the better Prairie style

designs by Robinson for Hogan and Sons with art glass and nicely

restored.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	_	
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 727

Former Street Number: 348

Street: William Street

PIN Number(s): 15-12-203-008-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form: Foursquare

Number of Stories:

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch replacement windows or

infill, large rear addition



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Full Front Porch:

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information

River Forest Village Wide Architectural and Historical Survey

Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 726

Former Street Number:

Street: William Street

PIN Number(s): 15-12-202-021-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Porch infilled, front door replaced,

might be rear addition not visible



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance:

Excellent example of Robinson's Prairie style designs for Hogan and Sons and one with art glass and

few changes.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stucco

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	_	
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 723

Former Street Number: 344

Street: William Street

PIN Number(s): 15-12-203-009-0000

Construction Date/Other Year: 1919

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Replacement porch windows or



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

and a Robinson Prairie Style

design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Son	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



PIN Number(s):

River Forest Village Wide Architectural and Historical Survey

General Information

Street Number: 722

Former Street Number: 343

Street: William Street

Construction Date/Other Year: 1917

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

15-12-202-022-0000

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories:

Current Wall Material 1: Wood clapboard

Current Wall Material 2: Stucco

Original Wall Material 1: Wood clapboard

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Porch windows might be infill



Photo 1

Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Outstanding example of Robinson's

Prairie style designs for Hogan and Sons, excellent use of wood board and batten and stucco siding.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing: Sidelights

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Paired

Window Storms: No

Significant Features: Horizontal board and batten siding,

built in planter



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 719
Former Street Number: 340

Street: William Street

PIN Number(s): 15-12-203-010-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing:

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
	_	
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 718
Former Street Number: 339

Street: William Street

PIN Number(s): 15-12-202-023-0000

Construction Date/Other Year: 1915

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: One front window filled in



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the few brick and stucco

combination of exteriors on Robinson's designs for Hogan and

Sons.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: Leaded Glass

Window Material: Wood

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
		Prioto 37 historic Prioto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 715
Former Street Number: 336

Street: William Street

PIN Number(s): 15-12-203-011-0000

Construction Date/Other Year: 1919

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Good

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Replacement windows



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes

Potentially Contributing to a

National Register District:

Noteworthy Buildings

Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 714

Former Street Number:

Street: William Street

PIN Number(s): 15-12-202-024-0000

Construction Date/Other Year: 1917

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation: Art glass

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Replacement porch windows or

infill



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: One of the better and more intact

examples of Robinson's designs for

Hogan and Sons.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: Art Glass

Window Material: Wood

Window Detail: Paired

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 711
Former Street Number: 332

Street: William Street

PIN Number(s): 15-12-203-012-0000

Construction Date/Other Year: 1917

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Good

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:
Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations:



Yes

Significant:

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Part of Hogan development and a

Robinson Prairie Style design.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Paired

Window Storms: Yes



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



Street:

River Forest Village Wide Architectural and Historical Survey

General Information

Street Number: 710

Former Street Number: 331

PIN Number(s): 15-12-202-025-0000

Construction Date/Other Year: 1914

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

William Street

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Bandboards

Storefront Material:

Roof Type: Cross gabled

Roof Material: Asphalt Shingle

Alterations: Visible but compatible side

addition, replacement windows



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Part of the Hogan development

> and collection of Robinson designed Prairie style houses.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Brick

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Aluminum

Window Detail: Ribbon

Window Storms: No



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
-		
		Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 707

Former Street Number: 324

Street: William Street

PIN Number(s): 15-12-203-013-0000

Construction Date/Other Year: 1916

Architect: Harry Robinson

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Good

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Prairie

Ornamentation:

Building Form:

Number of Stories: 2

Current Wall Material 1: Brick

Current Wall Material 2:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Hipped

Roof Material: Asphalt Shingle

Alterations: Replacement windows



Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: The only al

The only all brick Prairie style house designed by Harry Robinson

for Hogan & Sons.

Roof Ornamentation: Deep Eaves

Foundation Material/Form:

Door Detailing:

Porch: Partial

Dormers:

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Vinyl

Window Detail: Ribbon

Window Storms: No

Significant Features: Arched entry



Research Information		
Original Building Owner:		
Historic Name:		
Current Name:		
Construction Cost:		
Architect 1 Information:	Harry Robinson	
Architect 2 Information:		
Contractor Information:		
Developer Information:	Henry Hogans and Sons	Photo 2
Research/Archival Information:		
Permit:		
Subdivision:		
Landscape/Streetscape:		
Notes		
		Photo 3 / Historic Photo
	_	

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 632 **Former Street Number:** 315

Street: William Street

PIN Number(s): 15-12-208-010-0000

Construction Date/Other Year: 1918

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey: Illinois Historic Structures Surveys

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Poor

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: eaves brackets, half timbering, art

Building Form:

Number of Stories: 2

Current Wall Material 1: Stucco

Current Wall Material 2:

Original Wall Material 1: Stucco

Original Wall Material 2:

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Front Gabled

Roof Material: Asphalt Shingle

Alterations: Replacement windows, compatible

rear addition



Significant: Yes

National Register Criterion:

Contributing to a

National Register District: Yes Potentially Contributing to a **National Register District: Noteworthy Buildings** Less Than 50 Years Old:

Reason for Significance: Very grand, highly detailed

Gabled

Craftsman style house with fantastically detailed porch.

Roof Ornamentation: Deep Eaves

Foundation Material/Form: Stone

Door Detailing: Sidelights

Porch: Full Front

Dormers:

Window Type: Double-Hung

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: No

Significant Features: Unique porch detailing



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 617

Former Street Number: 300

Street: William Street

PIN Number(s): 15-12-209-005-0000

Construction Date/Other Year: 1923

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Craftsman

Ornamentation: Eaves brackets, some banding,

bow window Bungalow

Brick

Number of Stories: 1 ½

Current Wall Material 1:

Current Wall Material 2:

Building Form:

Original Wall Material 1: Brick

Original Wall Material 2:

Wall Detailing/Ornamentation:

Storefront Material:

Roof Type: Cross gabled

Roof Material: Tile

Alterations:



Photo 1

Significant: Yes

National Register Criterion: C

Contributing to a

National Register District: Yes
Potentially Contributing to a
National Register District:
Noteworthy Buildings
Less Than 50 Years Old:

Reason for Significance: Excellent and highly detailed

Craftsman bungalow with excellent

integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers:

Window Type: Double-Hung

Window Configuration: Multi-Paned

Window Material: Wood

Window Detail:

Window Storms: Yes



Research Information

Original Building Owner:	
Historic Name:	AT
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
Notes	
	Photo 3 / Historic Photo
	Filoto 37 Historic Filoto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect



General Information

Street Number: 523

Former Street Number:

Street: William Street

PIN Number(s): 15-12-217-001-0000

Construction Date/Other Year: 1924

Architect:

Current Function/Category: Single Family Residential Building

Historic Function: Single Family Residential Building

Listing in Existing Survey:

Evaluation

Condition: Excellent

Integrity: Excellent

Secondary Structure: Garage

Secondary Structure Condition: Excellent

Secondary Structure Integrity: Excellent

Landmark/National Register: No

Architectural Descriptions

Architectural Classification/Style: Tudor Revival

Ornamentation: Half timbering, shutters

Building Form: Bungalow

Number of Stories: 1 ½

Current Wall Material 1: Brick

Current Wall Material 2: Stucco

Original Wall Material 1: Brick

Original Wall Material 2: Stucco

Wall Detailing/Ornamentation: Timbering

Storefront Material:

Roof Type: Hipped with Cross Gable

Roof Material: Tile

Alterations:



Significant:

Yes

National Register Criterion: C

Contributing to a

National Register District:

Potentially Contributing to a
National Register District: Ye

Noteworthy Buildings Less Than 50 Years Old:

Reason for Significance: One of the grand bungalows in

River Forest and designed in a rare Tudor Revival style. It also retains

a high level of integrity.

Roof Ornamentation:

Foundation Material/Form:

Door Detailing:

Porch: Entrance

Dormers: Shed

Window Type: Casement

Window Configuration: 1 over 1

Window Material: Wood

Window Detail: Ribbon

Window Storms: Yes

Significant Features: Ivy covered, yard has a pond



Research Information

Original Building Owner:	
Historic Name:	
Current Name:	
Construction Cost:	
Architect 1 Information:	
Architect 2 Information:	
Contractor Information:	
Developer Information:	Photo 2
Research/Archival Information:	
Permit:	
Subdivision:	
Landscape/Streetscape:	
Notes	
	Photo 3 / Historic Photo
	Prioto 3 / Historic Prioto

Survey Information

Preparer: Doug Gilbert, Douglas Gilbert Architect

Survey Date: August 21, 2012